


TRIANNUAL

AIRDROP REVIEW AND

MALFUNCTION/SAFETY ANALYSIS



PREPARED BY
THE US ARMY QUARTERMASTER SCHOOL
FORT LEE, VIRGINIA 23801-1502

AIRBORNE CREED

I am an Airborne trooper! A paratrooper!

I jump by parachute from any plane in flight. I volunteered to do it, knowing well the hazards of my choice.

I serve in a mighty Airborne Force—famed for deeds in war—renowned for readiness in peace. It is my pledge to uphold its honor and prestige in all I am—in all I do.

I am an elite trooper—a sky trooper—a shock trooper a spearhead trooper. I blaze the way to far-flung goals behind, before, above the foe's front line.

I know that I may have to fight without support for days on end. Therefore, I keep mind and body always fit to do my part in any airborne task. I am self-reliant and unafraid. I shoot true, and march fast and far. I fight hard and excel in every art and artifice of war.

I never fail a fellow trooper. I cherish as a sacred trust the lives of men with whom I serve. Leaders have my fullest loyalty, and those I lead never find me lacking.

I have pride in the Airborne! I never let it down!

In peace, I do not shirk the dullest duty nor protest the toughest training. My weapons and equipment are always combat ready. I am neat of dress—military in courtesy—proper in conduct and behavior.

In battle, I fear no foe's ability, nor underestimate his prowess, power and guile. I fight him with all my might and skill—ever alert to evade capture or escape a trap. I never surrender, though I be the last.

My goal in peace or war is to succeed in any mission of the day—or die, if needs be, in the try.

I belong to a proud and glorious team—the Airborne, the Army, my Country. I am its chosen pride to fight where others may not go—to serve them well until the final victory.

I am a trooper of the sky! I am my Nation's best! In peace and war I never fail. Anywhere, anytime, in anything— I am AIRBORNE!

IN THIS ISSUE

VOLUME II - 2001

Preface	ii
Reports and Analyses	iii
Personnel Malfunction Reports and Analyses	1
Cargo Malfunction Reports and Analyses	71
Aircraft Malfunction Reports and Analyses	129
Summary of Supply and Equipment Drops	166
Summary of Personnel Parachute Jumps	166
Summary of Personnel Parachute Malfunctions	167
Injuries Occurring on Parachute Operations as Reported on	
DA Form 285	167
Aircraft Malfunctions	168

TAR&M/SA VOL II

PREFACE

The Airdrop Review and Malfunction/Safety Analysis is published by the US Army Quartermaster School in hopes that by "passing the word" the malfunction rate within the Armed Forces may be minimized. The review and analysis in this issue covers the period 1 May 2001 - 31 August 2001.

POC AND MAILING ADDRESS

The POC for Airdrop Malfunction Reports, Monthly Airdrop Summary Reports, and any other information concerning the Airdrop Review and Malfunction/Safety Analysis is Mr. Roger Hale. All correspondence for the above reports and analysis should be addressed to:

AERIAL DELIVERY AND FIELD SERVICES DEPARTMENT ATTN MR ROGER HALE USA QUARTERMASTER CENTER AND SCHOOL 1010 SHOP ROAD FORT LEE VA 23801-1502

REPORTS AND ANALYSES

The Malfunction/Safety Review Board met at Fort Lee, Virginia on 24 - 25 October 2001. A breakdown of the areas in which malfunctions occurred from 1 May through 31 August 2001 follows:

10
18
34

All DD Forms 1748-2 (Airdrop Malfunction Report (Personnel-Cargo)) are reviewed, and any identifying information is removed. Block 24 is annotated to include both Army and Air Force references if only one is given. No grammatical editing is done to the reports.

T	R	R	M	/S A	V	\mathbf{OI}	II
	1 I 7	. A.W.		/ \ 7 /-	. v	. , .	

PERSONNEL MALFUNCTION REPORTS AND ANALYSES

									_			
I. 1. UNIT BEING AIRLIFTED			2. DEPARTU	RE AH	REIF	GENERAL	3 /	DATE	Δ	TYPE ACFT	-	S. ACFT SER NO.
1. ONLI BEING AIRLIFTED			2. DEPARTO	RE AII	RFIE	to	 					S. ACFT SER NO.
6. OPERATION/EXERCISE			<u> </u>			. DZ AND LOCATION	<u> </u>		<u> </u>	C-17	ND TIME	
. J. EINTHOM/EACHOISE					ľ	. DE AND EUCATION						
9. ACFT ALTITUDE (Feet)	10.	ACFT SPI	EED (Knots)	1	11. D	Z ELEVATION (Feet)		12. SURFACE WINI	DS (I	Knots)	13. VISIBI	.ITY (Feet/Miles)
800		1.	30			387		6 Kn	ots	S	4	Miles
II.						PERSONNE						
14. NAME (Last, First, MI), (GRADE,	SSAN, &	UNIT	19	5. E	QUIPMENT WORN BY J	JMPE	R		16. JUMPER	's Positio	N IN ACFT
						CE, Kevlar, F 11950 Wpn C					Left 3	2
17. TYPE PARACHUTE (Specify)	18.				TYPE MALFUN					•	19. NO. JUMPS	
ISDECIIVI		SEMI-I	NVERSION '			INVERSION	Ι	CIGARETTE ROLL		OTHER (SPECIFY)]
T-10C		PILOT	CHUTE			BLOWN SECTION		BROKEN SUSPEN- SION LINE		Brok Statio	en c Line	15
20. TYPE OF RESERVE	21.		FUNCTION-			22. RESULTING INJUR	Y			Juin	- 1110	1.0
	ED PROPERLY (# "No" explain in											
MIRPS	1	item 31	YES	NO				Neck a	nА	Rack		
MIIII		<u></u>	TES	NO				TYCCK al	ııu	Dack		
32. CAUSE OF MA Broken static l		CTION	N/FAILURI	E (If	f m	ore space is nee	ded,	, continue on	rev	verse.)		
									_			
			CO	NT	Γ ΙΓ	NUED ON N	EΧ	T PAGE				

WHAT WAS THE MALFUNCTION?

Broken static line.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Poor exit.
- Improper body position.
 Failure to control static line in aircraft.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING

- Jumpmaster check door.
 Proper exit.

<u> </u>				GENERAL					
I. UNIT BEING AIRLIFTED		2. DEPARTUI	RE AIR	RFIELD	3. DATE	4. 1	YPE ACFT C-13	1	ACFT SER NO.
5. OPERATION/EXERCISE				7. DZ AND LOCATION			8. DATE	AND TIME	
9. ACFT ALTITUDE (Feet)	10. /	ACFT SPEED (Knots)	11	1. DZ ELEVATION (Feet)	12. SURFACE W	NDS (K	nots)	13. VISIBIL	ITY (FeetiMiles)
2,999 Feet AGI	_ 1	25 Knots		15 Feet MSL	6 K	nots	S	Unli	mited
11.				PERSONNEL					
14. NAME (Last, First, MI), G	RADE,	SSAN, & UNIT	15	. EQUIPMENT WORN BY JUI	MPER	1	6. JUMPE	R'S POSITIO	IN ACFT
				None				3	
17. TYPE PARACHUTE (Specify)	18.			TYPE MALFUNCT	ION				19. NO. JUMP!
13200		SEMI-INVERSION		INVERSION	CIGARETTE ROLL		OTHER	(SPECIFY)]
MT-1X		PILOT CHUTE		BLOWN SECTION	BROKEN SUSPEN SION LINE	ļ .	Bas	g Lock	50 SL 310 FF
20. TYPE OF RESERVE		RESERVE FUNCTION	لببا	22. RESULTING INJURY	<u> </u>			,	01011
		ED PROPERLY (If "No" explain in item 31)							
MT-1S		X YES	NO	None					
								, ,	
				E/ DAMAGE INCURRI					
executed at 3,5 experienced ba suspension line cessful. At app Reserve canop approximately	00 for glood	eet AGL in stack malfunctionsts, jumper's mately 2,100 ly deployed a meters souther	abl on v att fee it ap east	ond jump of the e body position. which spun hard empt to reach an et AGL, jumper opproximately 1,8 of DZ without f	Upon contacountercloc d pull down executed pr 800 feet AG urther incide	ninen kwis n on oper L an ent/i	opense. Duboth reutavid jum	iing, jung te to sev risers w way pro aper lan	nper verity of as unsuc- cedures.
During inspectivere missing. T gether. The remevidence of a lo	on of he u ainir ckec	f main canopy nstowed susp ng stows were I stow, line ov	sys ens inta	stem on DZ, it was ion line and pilot act and in the pro- or damage were s and usually the re	s noted the f parachute b per size and een after a te	irst 4 ridle conf echn	suspe were igurat ical ri	wrappe ion. No gger's i	od to- other nspec-

WHAT WAS THE MALFUNCTION?

Bag lock.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Poor packing procedures.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

- Better attention to detail when packing.
 Ensure correct stow length.

I. 1. UNIT BEING AIRLIFTED			2. DEPARTU	RE AH	REI	GENERAL	13	DATE	ΙΔ.	TYPE ACFT		5. ACFT SER NO.			
1. ONLI BEING AIRLIFTED			2. DEPARTO	NE AII	RFII		 	DATE	1	C-130		S. ACPT SER NO.			
6. OPERATION/EXERCISE				-	Т	7. DZ AND LOCATION	<u> </u>		+	8. DATE A	ND TIME				
					ı										
9. ACFT ALTITUDE (Feet)	10.	ACFT SPE	ED (Knots)	1	1. (DZ ELEVATION (Feet)		12. SURFACE WIN	DS (K	(nots)	13. VISIBI	LITY (FeetiMiles)			
2,500 feet AGL		130	Knots	۱		490 Feet		3 K	no	ots 30 Miles					
II.	-					PERSONNEI	-								
14. NAME (Last, First, MI), GR	ADE,	SSAN, &	UNIT	19	5. E	QUIPMENT WORN BY JU)MP	ER	1	16. JUMPER	R'S POSITIO	N IN ACFT			
				ı					١						
						None				5	Left S	<u>ide</u>			
17. TYPE PARACHUTE (Specify)	18.			·	_	TYPE MALFUNC	TIO	N				19. NO. JUMPS			
		SEMI-I	NVERSION '	ļ	Ļ	INVERSION	4	CIGARETTE ROLL		·	SPECIFY)	4			
DD 200		PILOT	CHUTE		l	BLOWN SECTION	ı	BROKEN SUSPEN-			Broken				
PD 300				<u> </u>	Ц			SION LINE		Contr	ol Line	1100			
20. TYPE OF RESERVE	21.	ED PROI	FUNCTION- PERLY (If plain in			22. RESULTING INJURY	•								
		item 31)													
Raven IV-M		X	YES	NO		Nor	ne								
					_										
32. CAUSE OF MALI Jumper failed to p Parachute Systen ered that the left of not recovered. Bot the Javelin-8 harr ment at the last w dent, it might hav tion to the riggers	oroj n) v cont oth ness eigl	ction perly : which trol lin control s and of h in w	/FAILURE inspect to he pack ne had be ol lines he containe vas 278 pouted to t	he ded. rok nad r sy	U ter si yst nd	ntrol lines on the pon inspection off directly along of excessive mis 254 pour ls. Although wanage to the co	he n o ve nd: eig	ICRAPS (In f the recover we the finger wear. The T s. The weight was not to rol line. Pro	nstreder tra Fech ht o the o	ructor (l main ap loop nnical (of the ju only fa inspec	canopy Left to Standa Imper- ctor in ction ar	y, I discov- oggle was rd Order fo with equip- this inci- nd notifica-			
					_										
			CO	NT	ΓIJ	NUED ON NI	EΧ	T PAGE							

WHAT WAS THE MALFUNCTION?

Broken control line.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- Worn equipment.
 Excess weight.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Better inspections.

				_							
					GENERAL						
1. UNIT BEING AIRLIFTED		2. DEPAR	URE A	AIRF	IELD	3.	DATE		YPE ACFT	l i	S. ACFT SER NO.
								•	Casa 2	12	
6. OPERATION/EXERCISE					7. DZ AND LOCATION				8. DATE A	ND TIME	
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEED (Knots)		11.	DZ ELEVATION (Feet)		12. SURFACE WINE	DS (K	nots)	13. VISIBI	.ITY (Feet/Miles)
12,500 Feet AGL		130Knots			490 Feet		0 Knot	S		30	Miles
II.					PERSONNE	L					
14. NAME (Last, First, MI), GR	ADE,	SSAN, & UNIT		15.	EQUIPMENT WORN BY J	UMI	PER	1	6. JUMPER	's Positio	N IN ACFT
								ı	21	nd Jun	nper
					MC-4 Main n	οι	inted AR2		15	st Pass	
17. TYPE PARACHUTE	18.				TYPE MALFUN	CTIC	N .				19. NO. JUMPS
(Specify)		SEMI-INVERSION		Ι	INVERSION	brack	CIGARETTE ROLL		OTHER (SPECIFY)	
		PILOT CHUTE	Т	Т	BLOWN SECTION	П	BROKEN SUSPEN-				7
MC-4			1	1		-	SION LINE		l		2
20. TYPE OF RESERVE	21.	RESERVE FUNCTION			22. RESULTING INJUR	Υ					
		ED PROPERLY (If "No" explain in									
MC-4		item 31)	7 N	^			N	Vor	ne		
		TES		Ü	<u> </u>	-	1	101	-		
ment, no damage 32. CAUSE OF MAI Jumper inexperie	.FUI	NCTION/FAILU			•				,		
								-			
		C	ON'	TI	NUED ON N	ΕX	KT PAGE				

WHAT WAS THE MALFUNCTION?

INCIDENT - Main cutaway.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Inexperienced jumper.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Better training.

I. 1. UNIT BEING AIRLIFTED		1.	2. DEPARTU	DE AIR	GENERAL	13	DATE	A TV	PE ACFT	T.	S. ACFT SER NO.
I. ONH BEING AIKLIFTED		[z. DEPAKIŲ	NE AIN	riclu	1"	VAIE	4. i Y			ACT SEK NU.
6. OPERATION/EXERCISE					7. DZ AND LOCATION			Īρ	C-13		
o. or enormonial periods					DE AND LOCKTION	-		"	. DATE MA		
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEE	D (Knots)	111	. DZ ELEVATION (Feet)		12. SURFACE WIND	S (Kno	ots)	13. VISIBIL	ITY (Feet/Miles)
12,500 Feet AGL	l .	130 K			490 Feet		5 Kn	-	,) Miles
12,300 1 CCt / GL		130 K	11013		PERSONN	EL	JIXII	Ots			VIIICS
14. NAME (Last, First, MI), GR	ADE,	SSAN, & U	NIT	15	. EQUIPMENT WORN B		PER	16.	. JUMPER':	S POSITIO	N IN ACFT
,, ,				1					1	st Pas	a
				1	MC-4 Parac Rucksack	iiuic	s System,			si Fas th Jun	
17. TYPE PARACHUTE	18.				TYPE MALFL	NCTIO	N .	-		V G11	19. NO. JUMPS
(Specify)	<u> </u>	SEMI-IN	VERSION'		INVERSION	П	CIGARETTE ROLL		OTHER (S	PECIFY)	1
		PILOT C	HUTE	П	BLOWN SECTION	П	BROKEN SUSPEN-				1
MC-4]		X	SION LINE				7
20. TYPE OF RESERVE	21.	RESERVE F			22. RESULTING INJ	JRY					-
		*No" expl			1						
MC-4		item 31)	ES 🗍	NO			None				
	_	(42) 1	·	NO							
jumper landed sa of the parachute s finger-trapped loc 32. CAUSE OF MALE The cause of the placed into the filoop so that the r thong.	ystop. FUN mai	em, the	FAILURE on was	efic E (If due	more space is not to improper porrectly. The	eedec	nat the left co	rever	rse.) togglete the	was b	g was -trapped
			CO	NT	INUED ON I	NEX	KT PAGE				

WHAT WAS THE MALFUNCTION?

Broken control line.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Poor rigger checks.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

- Better training.
 More checks.

					<u> </u>							
l				GENE	RAL							
1. UNIT BEING AIRLIFTED		2. DEPARTU	RE All	RFIELD		3.	DATE	4. T	YPE ACFT		5. ACFT SER NO.	
						L		_	C-130			
6. OPERATION/EXERCISE				7. DZ AND LOC	ATION			T	8. DATE A	ND TIME		
							,					
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEED (Knots)	1	1. DZ ELEVATION			12. SURFACE WIND		nots)		ATY (Feet/Miles)	
800 Feet		130	L_	360 Fe			5 Kno	ts		10-	15 Miles	
ll. 14. NAME (Last, First, MI), G	DADE	CCAN G HANT	14	EQUIPMENT WO	ONNEL		CD	٦,	C 11184050	'S POSITIO	AL IN A CET	
14. NAME (Last, FIFSt, MIJ, G	KADE,	33AN, & UNII		S. EQUIPMENT WC	, 10 mm	, IVI P	EN	ľ	6. JUMPEK	3 2031110	N IN ACT	
			1	· M19	50 A	id	Raσ			1/31	rd	
17. TYPE PARACHUTE	M1950, Aid Bag 1/3rd Type Malfunction 19. No. Jum											
(Specify)		SEMI-INVERSION	Т	INVERSION	Т	Т	CIGARETTE ROLL		OTHER (SPECIFY)	7	
		PILOT CHUTE	1	BLOWN SECTIO	N N	†	BROKEN SUSPEN-		Slow		1	
T-10C	'		ı				SION LINE		Oper		10	
20. TYPE OF RESERVE	21.	RESERVE FUNCTION		22. RESULTIN	G INJUR	′						
		ED PROPERLY (If "No" explain in										
MIRPS		item 31)	l no				None					
Will'd 5	<u> </u>	TE3	NO	<u> </u>			INOIIC					
the shop. There v parachutes. Thre 32. CAUSE OF MALI Statements from eagle) causing hir of the main parachutes came to the ground the ground the shop of the sho	e to FUNC the m to	four twists reaction/FAILURE malfunction less spin, twistinge. After the res	(If NC)	more space is O indicate to the risers are parachute	nain s s need he jui nd sus	ed,	continue on reper had a badension lines r	eve l ex	rse.) it over	the tai	er landed. Il (spread capabilities	
		CO	NT	'INUED O	N NI	ΞX	KT PAGE					

WHAT WAS THE MALFUNCTION?

INCIDENT - Excessive twists.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Bad body position; spread eagle.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Better pre-jump training.

												·	
Ι.					GENERAL								
1. UNIT BEING AIRLIFTED		2. [DEPARTU	RE AIR	FIELD	3.	. DA	ATE .	4. TYP	PE ACFT	5	. ACFT SER NO.	
					_					C-13			
6. OPERATION/EXERCISE					7. DZ AND LOCATIO	1			8.	DATE A	ND TIME		
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEED (Knots)	11	. DZ ELEVATION (Feet)		1.	2. SURFACE WINDS	(Kno	ts)	13. VISIBIL	TY (Feet/Miles)	
12,500 Feet AGL		125 Kı	ots		15 Feet M	SL		4-6 Kno	ots		Unl	imited	
II.					PERSON			····					
14. NAME (Last, First, MI), GR	ADE,	SSAN, & UNI	Γ	15	EQUIPMENT WORN B	/ JUM	PER		16	JUMPER	's Positioi	I IN ACFT	
				F	Rear mounted	ruck	KS2	ack with					
spider harness, exposed weapon 4													
17. TYPE PARACHUTE 18. TYPE MALFUNCTION 19. NO. JUMPS (Specify)													
(Specify)		SEMI-INVE	RSION '		INVERSION	П	CI	GARETTE ROLL	Ţ	OTHER (S	SPECIFY)	1	
		PILOT CHU	TE		BLOWN SECTION	П	В	ROKEN SUSPEN-	Р	Pilot P	arachut	14 SL	
MT-1X				1		П	SI	ON LINE		Hesita		29 FF	
20. TYPE OF RESERVE	21.	RESERVE FUN			22. RESULTING INJ	URY							
		*No" explair											
MT 1C		item 31)							T				
MT-1S		X YES	لِــا	NO	1			Γ	Von	<u>e</u>			
							_						
parachute hesitat looking over his cutaway procedu jumper landed ap 32. CAUSE OF MALI Due to the loss of However increas this malfunction.	rigi ires pro FUN	ht shoul s. Reserve continues continues continues main ca	der. Ave can ly 300	At apnopy) me	pproximately y fully deploy eters southwe more space is no	2,4 ved a st of	00 at f E d, c	ofeet AGL, approxima DZ without continue on r	jun tely furt ever	nper of 2,00 ther in ese.)	execut 00 feet nciden	ed proper AGL and t/injury.	
			CO	NT	INUED ON 1	NEX	ΥT	T PAGE					

WHAT WAS THE MALFUNCTION?

Pilot parachute hesitation.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- Pilot parachute old.
 Jumper not stable.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

- Change out pilot parachute.
 Reinforce emergency procedures.

				GENERAL									
. UNIT BEING AIRLIFTED		2. DEPARTUI	RE AIF	RFIELD	3.	DATE 4		C-130					
. OPERATION/EXERCISE				7. DZ AND LOCATION	<u> </u>			AND TIME					
). ACFT ALTITUDE (Feet)	10.	ACFT SPEED (Knots)	1	1. DZ ELEVATION (Feet)		12. SURFACE WINDS	(Knots)	13. VISIBIL	TY (FeetiMiles)				
2,999 Feet AGL		130 Knots		Sea Level		6 Knots	070	Partl	y Cloudy				
l.			1	PERSONNEI									
14. NAME (<i>Last, First, MI),</i> Gl	ADE,	SSAN, & UNIT		EQUIPMENT WORN BY IN BDUs, Boots, Glov Goggles, Lrg Alice	es ru	s, Gentex w/ acksack w/		r's position					
17. TYPE PARACHUTE	18.		1.9	special tactics lower		-	13	t juiiipe	19. NO. JUMP				
(Specify)		SEMI-INVERSION		INVERSION	I	CIGARETTE ROLL	OTHER	(SPECIFY)					
MC-4		PILOT CHUTE		BLOWN SECTION	I	BROKEN SUSPEN- SION LINE	Hun	gslider	UNK				
20. TYPE OF RESERVE	21.	RESERVE FUNCTION- ED PROPERLY (#	ــــــا	22. RESULTING INJUR	,			<u> </u>	OTAL				
		"No" explain in item 31)											
MC-4		X yes	NO			None							
					_								
31. DESCRIPTION OF					_	- 40							
damage and wa lines were twist loop, was found	I was for ed,	as conducted und to be serv the slider was the left rear sli	to brice up	poth main and reable. On inspect by the slider stogrommet. This feer placement o	se io ps	erve canopies. n of the main of , the left contro the probable ca	Reserve anopy of line, ause of	, the sus at the at the mal	pension tachment function.				
locking stows,	SM loo	pushed slider	gro	mmets down be lider grommet. R	tv	veen the folds.	This m	nay have	caused				

WHAT WAS THE MALFUNCTION?

Hung slider.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- Packing issue.
 Improper sequence.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

- Refresher training.
 Aggressive rigger checks.

l.				GENERAL					
1. UNIT BEING AIRLIFTED		2. DEPARTUR	RE All	RFIELD	3.	DATE 4	. TYPE ACF C-1		. ACFT SER NO.
6. OPERATION/EXERCISE				7. DZ AND LOCATION	<u> </u>			AND TIME	
			_			•	<u> </u>	-	
9. ACFT ALTITUDE (Feet) 12,999 Feet AGI	1	ACFT SPEED (Knots) 130 Knots	1	1. DZ ELEVATION (Feet) 39 MSL		12. SURFACE WINDS 6 Knots	(Knots)		ity (FeetiMiles) illy Cloudy
II.	<u> </u>	130 Kilots		PERSONNE		O IXIIOtS		1 artic	illy Cloudy
14. NAME (Last, First, MI), GI	RADE,	SSAN, & UNIT	11	5. EQUIPMENT WORN BY J	JMP	ER	16. JUMPE	R'S POSITION	I IN ACFT
				BDUs, Boots, Glo Goggles, Lrg Alice		•			
				special tactics low			1st.	Jumper	of 11
17. TYPE PARACHUTE (Specify)	18.			TYPE MALFUN		0,			19. NO. JUMPS
(SDECITO)		SEMI-INVERSION		INVERSION	$oldsymbol{\perp}$	CIGARETTE ROLL	OTHER	(SPECIFY)]
		PILOT CHUTE		BLOWN SECTION	ı	BROKEN SUSPEN-			į
MC-4	Ш		<u> </u>		┙	SION LINE	Hor	seshoe	900+
20. TYPE OF RESERVE		RESERVE FUNCTION ED PROPERLY (If		22. RESULTING INJUR	Y				
		"No" explain in item 31)		i					
MC-4		X YES	NO			None			
and serviceable	M tur the place	urned to his siden landed on the hanging from CTION/FAILURI was conducted to cause of this	de a he m ti E (I	and performed on PI. The main can he left leg and ru	uta nop ck edec	away procedu by was still in sack. d, continue on reve. Both were wn. There are	res. A gethe D-lesses everse.) found itoo ma	good responding with	erve was two
		CO	NT	'INUED ON N	ΕX	KT PAGE			

WHAT WAS THE MALFUNCTION?

Horseshoe malfunction.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Unstable body position.

$\underline{\textbf{WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?}}$

Reinforce body stablization.

					GENERAL						
. UNIT BEING AIRLIFTED		Ī	2. DEPARTU	JRE AI	 	3	DATE	4	TYPE ACFT		5. ACFT SER NO.
									C-13	0	
OPERATION/EXERCISE					7. DZ AND LOCATIO	1				AND TIME	
ACFT ALTITUDE (Feet)	10.	ACFT SPE	ED (Knots)	1	1. DZ ELEVATION (Feet)		12. SURFACE	NINDS .	Knots)	13. VISIB	LITY (FeetiMiles)
800 Feet		138 K	Cnots	$oldsymbol{\perp}$	335 Feet		3-4	Knc	ts	Ur	limited
					PERSON	IEL					
4. NAME (Last, First, MI), (GRADE,	SSAN, & L	JNIT	11	5. EQUIPMENT WORN B	/ JUM	PER		16. JUMPE	R'S POSITIO	ON IN ACFT
				1		١K			,	INIIZ	
3. TVOS DA OA CHUTS	Tan					-			į	JNK	Les ves unes
7. TYPE PARACHUTE (Specify)	18.			·	TYPE MALF	NCH			T		19. NO. JUMP
	-	PILOT (IVERSION '	╫	INVERSION BLOWN SECTION	Н	BROKEN SUSP		OTHER	(SPECIFY)	-
UNK	1	PILOT	LHUIE		BLOWN SECTION		SION LINE	EN-	١,	UNK	UNK
20. TYPE OF RESERVE	21.		FUNCTION-		22. RESULTING INJ	URY				U1 VIX	UINIX
		ED PROPI			1						
UNK		item 31)		1			ī	JNK			
OTVIX		<u>' </u>	/ES	NO) 1 1 1 1	-		
32. CAUSE OF MAI Reserve accided Malfunction NO	ntly o	deploy	ed insi	de a	ircraft. Parach	ute	and reserv	e we	ere take	en by th	ne
							_	_			

WHAT WAS THE MALFUNCTION?

INCIDENT - Reserve deployment in aircraft. Jumper extracted.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- Jumpmaster procedure.
 Door check procedure.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Ensure proper procedures are followed (FM 57-220/FM 3-20.220)

TAR&M/SA VOL II

		-									
1.					GENERAL					*** * * * * * * * * * * * * * * * * * *	
1. UNIT BEING AIRLIFTED			2. DEPARTUI	RE AIR	FIELD	3. (DATE	4.	type acft UNK		5. ACFT SER NO.
6. OPERATION/EXERCISE					7. DZ AND LOCATION				8. DATE A	ND TIME	
9. ACFT ALTITUDE (Feet)	10.		ED (Knots)	11	. DZ ELEVATION (Feet)		12. SURFACE WIN			13. VISIBI	LITY (Feet/Miles)
UNK II.		J	JNK		UNK PERSONNEI		UN	١K			UNK
it. 14. NAME <i>(Last, First, Ml),</i> Gl	RADE,	SSAN, &	UNIT	15.	EQUIPMENT WORN BY JU		ER	1	16. JUMPER	r's Positio	ON IN ACFT
					·	IN:	K		U	INK	
17. TYPE PARACHUTE (Specify)	18.				TYPE MALFUNC	TIOI	N				19. NO. JUMPS
ISDECTIVE		SEMI-I	NVERSION '		INVERSION	\downarrow	CIGARETTE ROLL		OTHER (SPECIFY)	
UNK		PILOT	CHUTE		BLOWN SECTION		BROKEN SUSPEN- SION LINE				UNK
20. TYPE OF RESERVE	21.	ED PROF			22. RESULTING INJURY	,					
UNK		item 31)	YES	NO			UNK				
32. CAUSE OF MALI	FUN	CTION	/FAILURE	(If 1	nore space is need	ed,	continue on	rev	erse.)		
			CO	NT.	INUED ON NI	EΧ	T PAGE				

WHAT WAS THE MALFUNCTION?

INCIDENT - Premature activation of reserve in aircraft before jump doors were opened.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Failure to protect ripcord grip.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Avoid excessive movement in aircraft (need more information - incomplete report).

TAR&M/SA VOL II

l.					GENERAL					***	
1. UNIT BEING AIRLIFTED			2. DEPART	URE AIF	RFIELD	3.	DATE	4. T	YPE ACFT		5. ACFT SER NO.
			1.						C-17	ı	•
6. OPERATION/EXERCISE		·			7. DZ AND LOCATIO	1			8. DATE A	ND TIME	
9. ACFT ALTITUDE (Feet)	10.	ACFT SPI	EED (Knots)	1	1. DZ ELEVATION (Feet)		12. SURFACE WIN	DS (K	nots)	13. VISIBI	LITY (Feet/Miles)
800	ı	Uì	NK		UNK		0 Knot	S		U	NK
II.					PERSON	EL					
14. NAME (Last, First, MI), G	RADE,	SSAN, &	UNIT	15	. EQUIPMENT WORN B	JUMF	PER	1	6. JUMPER	's Positio	N IN ACFT
				ł	Weapon/Ru	cksa	ack	- 1		Left	Door
17. TYPE PARACHUTE	18.				TYPE MALF	NCTIO	N			•	19. NO. JUMPS
(Specify)		SEMI-	INVERSION '	7	INVERSION	П	CIGARETTE ROLL		OTHER (SPECIFY)	7
		PILOT	CHUTE		BLOWN SECTION	П	BROKEN SUSPEN-		Mid-A		7
T-10C		1		1 1		Н	SION LINE			Air glemen	t UNK
20. TYPE OF RESERVE	21.		E FUNCTION-		22. RESULTING INJ	JRY			Diltall	CICILICI	L II
			PERLY (# kplain in								
MDDC	:	item 31	· _	٦ .			C				
MIRPS			YES	NO			Sore w	vrist			
32. CAUSE OF MA Failure to yield descent.										during	g total
								_			

WHAT WAS THE MALFUNCTION?

INCIDENT - Mid-air entanglement.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Air control.
- 2. Attention to detail.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

- Follow proper procedures (57-220).
 Keep a sharp look out during descent.

.					GENER	AL					
. UNIT BEING AIRLIFTED			2. DEPARTU	RE All	 		3. DATE	T	4. TYPE ACFI		5. ACFT SER NO.
									C-17		
. OPERATION/EXERCISE					7. DZ AND LOCA	ION	•		8. DATE	AND TIME	
. ACFT ALTITUDE (Feet)	10.	ACFT SPEE	D (Knots)	1	1. DZ ELEVATION (F	et)	12. SURF	ACE WINDS	(Knots)	13. VISIB	ILITY (Feet/Miles)
9,500		14			419			3			Unlimited
),500 I.		17	<u> </u>		PERSO	NNEL		<u> </u>		<u> </u>	Omminica
4. NAME (Last, First, MI), C	RADE,	SSAN, & L	JNIT	19	5. EQUIPMENT WOR	N BY JUN	APER		16. JUMPE	R'S POSITI	ON IN ACFT
					Wear	on/A	dice Pa	ck .		Ramp	_
7. TYPE PARACHUTE (Specify)	18.				TYPE MA	LFUNCT	ON				19. NO. JUMP
	-	 	IVERSION	 	INVERSION		CIGARET		OTHER	(SPECIFY)	4
MC-4		PILOT	CHUTE		BLOWN SECTION		BROKEN SION LIN				150+
0. TYPE OF RESERVE	21.		UNCTION		22. RESULTING	NJURY	4				
	1	"No" exp item 31)									
MC-4	1		res	NO.			None	3			
	_					7	1,011	-			
32. CAUSE OF MAI INCIDENT - P enough to clear time and landed	ilot j the	parach pilot p	ute was	s ca te o	ught in vacu ff his back. S	um. S SM in	SM did	not cle	ar over s		
								_	,		
				NT							

WHAT WAS THE MALFUNCTION?

Pilot parachute hesitation.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Not clearing over shoulder.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Follow emergency procedures.

. UNIT BEING AIRLIFTED					GENERAL						
		2. DEPA	RTURE	E AIRFI	 	3.	DATE	4.	TYPE ACFT		5. ACFT SER NO.
									C-1	7	
. OPERATION/EXERCISE					7. DZ AND LOCATION				8. DATE	AND TIME	
ACFT ALTITUDE (Feet)	110	ACFT SPEED (Knot	c)	111	DZ ELEVATION (Feet)		12. SURFACE W	INDS ((nots)	13 VISIR	LITY (Feet/Miles)
	"	140	,,	'''	419		3	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Kilots)	1	nlimited
17,900	.J	140		1	PERSONNI	:1	1 3			U.	IIIIIIIIeu
4. NAME (Last, First, MI), GI	RADE,	SSAN, & UNIT		15. (QUIPMENT WORN BY		PER	1	16. JUMPE	R'S POSITIO	IN IN ACFT
				,	Weapon, Alice	e Pa	ack. Oxvge	n		Ramp	
7. TYPE PARACHUTE	18.			1	TYPE MALFUI	_				. · · · · · · ·	19. NO. JUMP
(Specify)		SEMI-INVERSIO	١,		INVERSION		CIGARETTE ROL	L	OTHER	(SPECIFY)	
MC-4		PILOT CHUTE			BLOWN SECTION		BROKEN SUSPE	N-			45
0. TYPE OF RESERVE	21.	RESERVE FUNCTIO	N-		22. RESULTING INJU	RY					
		ED PROPERLY (If "No" explain in item 31)									
UNK		YES	\neg	NO		Di	slocated le	ft kn	ee		
	<u> </u>		=			=1			-		
32. CAUSE OF MAL	FUN	CTION/FAILU	RE ((If m	nore space is nee	edec	l, continue o	n rev	verse.)		
Incident - Jumpe entangled with h prescribed. Rese	is le	eft foot. Ma	in p	arac	chute complet						
								_			
							_				

WHAT WAS THE MALFUNCTION?

INCIDENT - Left leg in suspension lines of main parachute (MC-4).

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Jumper was not stable.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Follow military free-fall procedures as outlined in FM 31-19.

l.				GENERAL					
1. UNIT BEING AIRLIFTED		2. DEPARTUR	RE All	RFIELD	3.	DATE	4. TYPE ACF	1	. ACFT SER NO.
6. OPERATION/EXERCISE				7. DZ AND LOCATION			UNK	AND TIME	
B. OFERATION/EXERCISE				7. DZ AND LOCATION	•		B. DATE	AND TIME	
9. ACFT ALTITUDE (Feet)	110	ACFT SPEED (Knots)	Ιı	1. DZ ELEVATION (Feet)		12. SURFACE WINDS	(Knots)	13 VISIRII	ITY (FeetiMiles)
14,500 AGL	"	130 Knots	ľ	796 MSL					r/unlimited
14,300AGL	ــــــــــــــــــــــــــــــــــــــ	130 Kilots		PERSONN	FI	0 - :	2	Clea	r/uriiiriiitea
14. NAME (Last, First, MI), G	RADE.	SSAN, & UNIT	119	5. EQUIPMENT WORN BY		PER	16. JUMPE	R'S POSITIO	N IN ACFT
,	·		1						
			1	02 Mask, to front mount				1	
17. TYPE PARACHUTE	18.			TYPE MALFL			<u> </u>	•	19. NO. JUMPS
(Specify)	一	SEMI-INVERSION '		INVERSION	П	CIGARETTE ROLL	OTHER	(SPECIFY)	1
	Г	PILOT CHUTE		BLOWN SECTION	П	BROKEN SUSPEN-			FF55/
MC-4	ı				Ш	SION LINE			SL87
20. TYPE OF RESERVE	21.	RESERVE FUNCTION		22. RESULTING INJU	JRY				2207
	ļ	ED PROPERLY (If "No" explain in							
MC-4	ĺ	item 31)	NO			None			
WIC-4	<u> </u>	YES	NU			1 (0110			<u> </u>
				7_					
32. CAUSE OF MA The MFF jumpr rigging procedur onto the aircraft feet) at 6,000 feed due to the oxyge aircraft, he was a parachute, howe jumper stated th securely to his pa checks prior to e check his equipr door on exit and on with the rest of	nas res a ancet ar n m able ever at he arac exiti	ter conducted at the same time I secure them is ask he was we to pay special he was not able cinched down that equipment the aircraft t. As the jumper abled for appropri	JM ne. for for att att le t vn v nt a cer le	IPI on the grouder that then allowed take off. The judgment of the end of the	nd a ed the ump of most wood in the contract of the contract o	and inspected the jumpers to be armed his inute warning and the recoment secured ment on his leading part of that he was the diving position of the regaining armed to be a secured to the the was the the was the the was the the the was the the was the the the was the	rucksacarry the AOD (I g. The juced light to the inft side a re his rull that he oo rush in, he hing stabili	cks for ceir rucks FF2 set sumper seghting ir right sid as closely cksack receive ed to protect a portion	sacks for 2,500 tated that nside the e of his y. The was held d two pin operly on of the ntinued
		CO	NT	INUED ON I	NEX	KT PAGE			

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

pulled his main ripcord grip and stated that his opening shock was a little harder than usual. The jumper said he felt his left QRL was pulled away from his front mounted rucksack at the end of the opening shock. This was actually the reserve ripcord grip. It is my belief that the jumper's reserve ripcord pins were not fully extracted from the newly fabricated reserve closing loop assembly until the jumper had a full main canopy above his head and had transitioned from downward to forward movement. At this time the jumper would have stopped his freefall and transitioned into his post opening canopy control procedures. When the weight of the rucksack was transferred downward, it allowed the rucksack to pull the remaining portion of the pins from the newly fabricated reserve closing loop assembly, and allowed his reserve pilot parachute to launch in a horizontal manner behind him, instead of a vertical manner above him. The 1 inch needle fold of the reserve bridle line, which is inserted into the elastic locking loop, was not pulled free from the elastic locking loop, therefore the reserve canopy remained inside of the deployment bag, failing to function properly. The needle fold of the bridle line inserted into the elastic locking loop was measured at 7/8th of an inch long. It is probable that the reserve pilot parachute did not pull the needle fold from the elastic locking loop due to its trajectory angle of approximately 90 degrees from the needle folds downward inserted portion inside of the locking loop. The reduced airspeed from terminal velocity to forward flight may have also contributed to the needle fold being intact. The reserve deployment bag had stretched the elastic locking loop, and put further pressure on the bridle line needle fold keeping it locked in position.

ANALYSIS: 15

WHAT WAS THE MALFUNCTION?

INCIDENT - Improper rigging procedures USASOC Reg 350-2.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Failure to attach equipment to proper D-ring.
- 2. Failure to receive second JM check.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Follow USASOC 350-2.

I. UNIT BEING AIRLIFTED		2. DEPART	URE AIF	GENERAL	3.4	DATE	4. TV	PE ACFT	T.	S. ACFT SER NO.
J BEING PHIER IED		1	- m. mil		ַר"			C-130	- 1	
6. OPERATION/EXERCISE		. J	-	7. DZ AND LOCATION	<u>. </u>			O-13U		
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEED (Knots)	1	1. DZ ELEVATION (Feet)		12. SURFACE WIND	S (Kno	ots)	13. VISIBIL	ITY (Feet/Miles)
1250		130		247 Feet		8 - 10 K	not	s	U	nlimited
II.				PERSONNE	L	······································				
14. NAME (Last, First, MI), G	RADE,	SSAN, & UNIT	15	. EQUIPMENT WORN BY J	UMPI	ER	16.	JUMPER'	S POSITIO	N IN ACFT
				Ruck, M-2	49v	w/case,			_	
	7			helmet, LB	E, I	BDU		2nd	Pass	8th
17. TYPE PARACHUTE (Specify)	18.		-	TYPE MALFUN	CTIOI	N				19. NO. JUMPS
	<u> </u>	SEMI-INVERSION	4	INVERSION	4	CIGARETTE ROLL		OTHER (S	PECIFY)	4
MC 1 10		PILOT CHUTE		BLOWN SECTION	ı	BROKEN SUSPEN-	Broken			
MC-1-1C	 	<u> </u>	لــــــــــــــــــــــــــــــــــــــ	L,		SION LINE		Static	Line	13
20. TYPE OF RESERVE	21.	RESERVE FUNCTION ED PROPERLY (#		22. RESULTING INJUR	Y					
		"No" explain in item 31)								
MIRPS		YES _	NO			Bac	ck aı	nd Hi	p	
				7						
32. CAUSE OF MA Jumper stated th mentarily and in the initial report	nat h iterr	ne had a weal upted the dep	exi oloyi	t and this caused nent sequence a	l th nd	e static line caused the s	to be	ecome	e caug o brea	ht mo- k. This is
							-			

WHAT WAS THE MALFUNCTION?

Broken static line

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Weak exit.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

- Proper exit.
 Jumpmaster check door.

								_			
I. 1. UNIT BEING AIRLIFTED		ī	2. DEPARTU	RE AIR	GENERAL	3 1	DATE	Δ.	TYPE ACFT	1	S. ACFT SER NO.
1. ONLI BEING AIREIFTED			Z. DEPARTO	NE MIN	ritto	 	DAIL	1			S. ACT SER NO.
6. OPERATION/EXERCISE		1			7. DZ AND LOCATION	<u> </u>		Ц	Casa 2 8. date a	· · · · · · · · · · · · · · · · · · ·	
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEE	D (Knots)	11	. DZ ELEVATION (Feet)		12. SURFACE WIN	DS (A	(nots)	13. VISIBIL	ITY (Feet/Miles)
12,500 Feet AGL		90 Kı	nots		490 Feet		5 Knot	ts		3	0 Miles
II.	-				PERSONNE	L					
14. NAME (Last, First, MI), GR	ADE,	SSAN, & L	INIT	15	EQUIPMENT WORN BY J	UMPI	ER		16. JUMPER	's POSITIO	N IN ACFT
	1				None				12	2th Jun	nper
17. TYPE PARACHUTE (Specify)	18.				TYPE MALFUN	CTIO	N				19. NO. JUMPS
		SEMI-IN	VERSION '	\vdash	INVERSION	4	CIGARETTE ROLL		OTHER (SPECIFY)	1600
F 1 265		PILOT	HUTE		BLOWN SECTION	ı	BROKEN SUSPEN- SION LINE		Cm		Approxi-
Falcon 265	21	DECEDITE 7	UNCTION-	Ш	22. RESULTING INJUR	,	J.OH LINE		SII	ivel	mately
ES. TIPE OF RESERVE	۵۱.	ED PROPE "No" exp	RLY (H		22. RESOLING MOOR	•					
Raven IIII		item 31)				1	None				
Kaveniiii		X v	'ES	NO		1	NOTIC				
					7						
parachute failed procedures at ab about 750 meter 32. CAUSE OF MALI After a TRI (tecl possible cause for example pulling	S W FUN nnic	est of t CTION/ cal rigg ne mal	The inter FAILURE ger insper	e (If	l landing area w more space is nee on) nothing was	ded for	out injury. , continue on	rev vitl	verse.) h the m	ain car	пору. А
			CO	NT	INUED ON N	EX	T PAGE				

WHAT WAS THE MALFUNCTION?

Falcon 265 canopy failed to fully inflate. Jumper performed proper cutaway procedures.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- Questionable pack procedures.
 More information needed.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

No recommendation for non-standard equipment.

1. UNIT BEING AIRLIFTED		··· 1	2. DEPARTU	RF AID	GENERAL	3 /	DATE	4 T	YPE ACFT	1.	S. ACFT SER NO.
I. OWN BEING AIRLITTED			L. DEPARTU			֓֓֓֟֟֓֓֓֓֓֟֟֓֓֓֟֟֓֓֓֟֟֓֓֟֟֓֓֟֟֓֓֟֟֓֓֟ <u>֟</u>	70.1	_			ACT SER NO.
6. OPERATION/EXERCISE		i			7. DZ AND LOCATION	L	l	_	Casa 2 8. date a		
								ľ	-: -: ··· · ·		
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEE	D (Knots)	11	. DZ ELEVATION (Feet)		12. SURFACE WIND	S (Kn	oots)	13. VISIBIL	ITY (Feet/Miles)
12,500 Feet AGL		90 K	nots		490 Feet		5 Kno	ts		30	Miles
И.					PERSONNE	-					
14. NAME (Last, First, MI), GR	ADE,	SSAN, & L	JNIT	15	EQUIPMENT WORN BY J	MPE	ER .	16	6. JUMPER	's Positio	N IN ACFT
				ı							
					•	ne				5th J	umper
17. TYPE PARACHUTE (Specify)											
			VERSION '	Н	INVERSION	+	CIGARETTE ROLL		OTHER (SPECIFY)	200
Ealaan 265		PILOT	HUTE		BLOWN SECTION	ı	BROKEN SUSPEN- SION LINE		Homa	aa l aa	Approxi- mately
Falcon 265 20. Type of reserve		DECEDVE	UNCTION-		22. RESULTING INJUR		JON LINE		Hors	eshoe	matery
EU. ITTE OF NESERVE	41.	ED PROPE "No" exp	RLY (H		22. RESULTING INJUR	•					
D 777		item 31)				_					
Raven III		X v	'ES	NO		N	one				,
Jumper was exec chute system). M throw out pilot pa this type of paracl	utir alfi arac	ng his t unction chute.	thirteen n was ca The use	th ju ause e of	ump with a ICRA d by improper d	APS epl	S (instructor loyment of n	cei naii	rtified n pilot	paracl	nute/
								-			
							-				
			CO	NT	INUED ON N	EΧ	T PAGE				

WHAT WAS THE MALFUNCTION?

Falcon 265 bridle entanglement with throw out arm/horseshoe malfunction.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Improper pilot deployment.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Additional training.

l .					GENERAL						
UNIT BEING AIRLIFTED			2. DEPARTU	RE AIF	 	3.	. DATE	4. T	YPE ACFT	Ŧ	5. ACFT SER NO.
									C-13	0	
. OPERATION/EXERCISE			•		7. DZ AND LOCATION				8. DATE A		
ACFT ALTITUDE (Feet)	10.	ACFT SPEE	D (Knots)	1	1. DZ ELEVATION (Feet)		12. SURFACE WIN	DS (K	nots)	13. VISIBI	LITY (Feet/Miles)
1.000 Feet	ı	130 K	Cnots		UNK		0-5	Kno	ots	7	' +
l.		1001	2310 00		PERSONNI	L					
4. NAME (Last, First, MI), G	RADE,	SSAN, & L	JNIT	19	S. EQUIPMENT WORN BY	JUMI	PER	1	6. JUMPER	R'S POSITIO	IN IN ACFT
					Assault pack, Mod Case	M1	1950 Saw		P	JM/Ri	ght
7. TYPE PARACHUTE	18.				TYPE MALFU	ICTIC	ON .			-	19. NO. JUMP
(Specify)		SEMI-IN	IVERSION '	П	INVERSION	П	CIGARETTE ROLL		OTHER ((SPECIFY)	-
T-10C		PILOT	HUTE		BLOWN SECTION		BROKEN SUSPEN-			vation IIRPS	100+
0. TYPE OF RESERVE	21	RESERVE	UNCTION		22. RESULTING INJU	RY			OI IV	пкгз	100+
	"	ED PROPI	ERLY (H		222302	•••					
T 10 MIDDO	1	item 31)		ı			Τ	" D	1r		
T-10 MIRPS		<u> </u>	rES	NO			Lowe	r Ba	ack		
								_			
The A-21 cargo premature activ	bun	ıdle sta	atic line	bec	ame misrouted	arc	ound jumper	''s e	quipm	ent res	sulting in
The A-21 cargo	bungation	ndle stan of the	ntic line HE MIRI N/FAILUE The A-2	bec PS.	f more space is no argo bundle becaurred with jump	eede	ed, continue of	n re	verse.)	While	attempting
The A-21 cargo premature active 32. CAUSE OF MA During deploym to dislodge the box	bungation	ndle stan of the	ntic line HE MIRI N/FAILUE The A-2	bec PS.	f more space is no argo bundle becaurred with jump	eede	ed, continue of	n re	verse.)	While	attempting

WHAT WAS THE MALFUNCTION?

INCIDENT - MIRPS activation in aircraft..

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- Loss of control of equipment.
 Loss of ripcord grip awareness.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Additional bundle jettison procedure training IAW FM 57-320.

1. UNIT BEING AIRLIFTED					GENERAL	_					
			2. DEPARTU	RE AIR		3.	DATE	4.	TYPE ACFT		5. ACFT SER NO.
								11	H-60 B	lack	
6. OPERATION/EXERCISE					7. DZ AND LOCATION	-			8. DATE AN		
ACFT ALTITUDE (Feet)	10.	ACFT SPE	ED (Knots)	11	. DZ ELEVATION (Feet)		12. SURFACE WIN	IDS (A	(nots)	13. VISIB	ILITY (Feet/Miles)
1,500 Feet AGL		70	KIA		1476 Feet MSI	-	0-1 K	no	ts		Unlimited
II.					PERSONNE						
14. NAME (Last, First, MI), GI	RADE,	SSAN, &	UNIT	15	. EQUIPMENT WORN BY J	JMP	ER		16. JUMPER'	S POSITIO	ON IN ACFT
					Day non-tactica	1 w	/out equip-				
					ment		1 · 1		4	lth/1s	tlift
17. TYPE PARACHUTE (Specify)	18.				TYPE MALFUN	CTIO	N				19. NO. JUMPS
ISDECIIVI		SEMI-I	NVERSION '		INVERSION	floor	CIGARETTE ROLL		OTHER (S	PECIFY)	
		PILOT	СНИТЕ		BLOWN SECTION		BROKEN SUSPEN-		Risers	connec	ted
MC1-1C	<u>L</u>					\perp	SION LINE		reverse		Over 100
20. TYPE OF RESERVE	21.		FUNCTION- PERLY (IF		22. RESULTING INJUR	Y					
			plain in								
T-10 Reserve			YES	NO	j		None				
	_										,
	CLINI										
The risers were of than a forward d quality assurance issue that should	coni rive	nected since specti	d crossed e the can on system	d ov lopy m di	er giving the pa was reversed. I uring the final pa	rac Pos	chute the eff ssible cause ess of inspe	fect e is a	of a rev a breaking parac	down chutes	in the ready for
The risers were of than a forward diquality assurance	coni rive	nected since specti	d crossed e the can on system	d ov lopy m di	er giving the pa was reversed. I uring the final pa	rac Pos	chute the eff ssible cause ess of inspe	fect e is a	of a rev a breaking parac	down chutes	in the ready for

WHAT WAS THE MALFUNCTION?

INCIDENT - MC1-1C orfice was in the front.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Stated that risers were reversed.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

- Quality control.
 Follow/enforce packing procedures.

l.				GENERAL					
1. UNIT BEING AIRLIFTED		2. DEPARTUR	E AIR	FIELD	3.	DATE	4. TYPE ACF	5	ACFT SER NO.
6. OPERATION/EXERCISE				7. DZ AND LOCATION			C-17	AND TIME	
B. OPERATION/EXERCISE				7. DZ AND LOCATION			B. DATE	ANDTIME	
0.4657.41.7171405.45	1	A CET CREED (#)	1	03.51.51/4.71011./5		las cuesa es annas	<i>"</i>	lan Lucinus	The second of the second
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEED (Knots)	["	DZ ELEVATION (Feet)		12. SURFACE WINDS	-	1	TY (Feet/Miles)
1,250 feet		130 Knots		280 Feet		5 Kno	ts	<u> </u>	nlimited
ll. 14. NAME (Last, First, MI), G	0405	CCAN A HAUT	Lie	PERSONN EQUIPMENT WORN BY		250	Tec mass	R'S POSITION	IN ACCT
14. NAME (Last, First, Mil), G	RADE,	SSAIR, & URIT		. EQUIPMENT WORN BY	JOIMIT	EN	16. JOMPE	K 3 POSITION	I IN ACT
			l	· No	ne			2/13th	
17. TYPE PARACHUTE	18.			TYPE MALFU	-	N.		2/1541	19. NO. JUMPS
(Specify)		SEMI-INVERSION	_	INVERSION	П	CIGARETTE ROLL	OTHER	(SPECIFY)	1
		PILOT CHUTE		BLOWN SECTION	H	BROKEN SUSPEN-		(SFECII 1)	1
T-10C		11201 611012		BEOWN SECTION		SION LINE	Pa	artial	1
20. TYPE OF RESERVE	21.	RESERVE FUNCTION		22. RESULTING INJU	RY		1 10	atiai	1
		ED PROPERLY (If "No" explain in		Ì					
MDDC		item 31)				NT			
MIRPS		YES	NO			None			
						 			
32. CAUSE OF MALA A complete inspect was found on the a wear and tear on it Suspension line 11 tears in canopy, go section 5, had a sm gore 19 sections 3, had 1 square of the involved with the rat an awkward ang the deployment ph with the suspension found that the canoriser assembly was tional check.	tion ircra and 5 re 13 hall h 4, and halfu e anti malfu ase on line opy r	was conducted of the harness had to percent of the section 5, had a cole, suspension and 5, canopy was inversion net to unction and talking hich somehow con the parachute.	on the ent no ant a smalline s riporn from the smalline s riporn from the ause ause wa	he parachute, har bag had normally deficiencies. The i-inversion net to all hole, gore 14 15 had 2 square oped all the way from the line. Aft with the jumper, ed his left should is believed that the premature releases not properly se	rnes weal e pal orn f sec s of expo er a it is ler t he c ated	s, deployment by and tear on it. rachute had the rom the line, gotion 4, small structure the anti-inversioning the radial careful inspectively believed that the obelower that anopy release a of the assembly.	oag and a The stati followir ore 7 sect ess tears on net to tape and ion of all e jumper the rest assembly There wanger exit	ic line had a damag damag tion 5. Sn in canopy orn from the suspension of his body profits became was no eviting the a	d normal e found: nall stress y, gore 15 he line, ton line 30 pment position was dy during entangled idence ircraft. The
		COM	NT	INUED ON N	NEX	KT PAGE			

WHAT WAS THE MALFUNCTION?

T10-C canopy release assembly (LF) activated.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Poor exit led to interaction between canopy release and deployment parachute causing activation of release and parachute damage.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Proper exit procedures.

								·				
l.						GENERAL						
1. UNIT BEING AIRLIFTED			2. DEPARTU	PRE A	IRFIEL	.D	3.	DATE	1	TYPE ACFT		5. ACFT SER NO.
							1		Ц	Casa 2		
6. OPERATION/EXERCISE					ľ	. DZ AND LOCATION				8. DATE A	ND TIME	
9. ACFT ALTITUDE (Feet)	10	A CET COE	ED (Knots)	1.	11 0	Z ELEVATION (Feet)		12. SURFACE WINE	DC /#	(note)	12 1/16/10	LITY (Face) Miles
				ľ	11. 04					inotsj		LITY (Feet/Miles)
10,000 Feet AGL	L	130 K	Knots			490 Feet	:1	UNK			L	30 Miles
14. NAME (Last, First, MI), GR	ADE.	SSAN. &	UNIT	11	5. EO	UIPMENT WORN BY		ER	1	16. JUMPER	'S POSITIO	ON IN ACFT
,	·					C-4 Parachu			١			
				1		icksack, O-2		ysiciii,	١	1st P	Pass/41	h Jumper
17. TYPE PARACHUTE	18.					TYPE MALFUI		N		1501	4 00/	19. NO. JUMPS
(Specify)	SEMI-INVERSION INVERSION C									OTHER (SPECIFY)	
		PILOT	CHUTE	T	В	LOWN SECTION	\top	BROKEN SUSPEN-		AR2 H	ligh	7
MC-4	<u> </u>							SION LINE		Activa	-	15
20. TYPE OF RESERVE	21.		FUNCTION- PERLY (#			22. RESULTING INJU	RY					
		"No" ex item 31)	plain in		-							
MC-4			, YES] NO				None				
	_							110110				.
fired. The AR2 w bered within tole 97 feet during the 32. CAUSE OF MALE The following ar in the jump posit properly as per u position prior to a completely to the cycling may not a exceeds 80 feet p Casa 212 causing	runce so so of the solution of	ce. The control of th	/FAILURE ossible of to reach Jumper When cy tion and e unit to a	est m lest. (If caussing s an velir l the	ses gas as and jung t	re space is need for this AR2 safe arming a sumpmasters the AR2 jumpsters to the jumpstereby allowing the area of the the jumpstereby allowing the the properties of the jumpstereby allowing the the the jumpstereby allowing	ded, highlitituees np	continue on the firing. The ade. The AR ad to verify the need to veriposition. However, to ache unit to ache unit to ache unit to ache and to the unit to ache and the unit to ac	reve 2 r hat ify	erse.) R2 was not the AF that the ing on tate once	s accid t have 22 is it e unit	ently placed been cycled the off s rotated switch while
			CO	NT	ΓIN	IUED ON N	EX	T PAGE				

WHAT WAS THE MALFUNCTION?

Premature activation of main canopy.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

AR2 fired at improper altitude.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Need AR2 setting 8. Proper cycling of AR2.

		·									
l.					GENERAL						***************************************
1. UNIT BEING AIRLIFTED			2. DEPARTU	RE AIR	FIELD	3.	DATE		PE ACFT	1	ACFT SER NO.
									C-130		
6. OPERATION/EXERCISE					7. DZ AND LOCATION		<u> </u>	T	B. DATE AN	D TIME	
9. ACFT ALTITUDE (Feet)	10.	ACFT SPE	ED (Knots)	11	. DZ ELEVATION (Feet)		12. SURFACE WIND	S (Kn	ots)	13. VISIBILI	TY (FeetiMiles)
1,000 Feet		130) Knots	$oldsymbol{\perp}$	1446 Feet		8 Kn	ots		3]	Miles
II.					PERSONNE	L					
14. NAME (Last, First, MI), GR	ADE,	SSAN, &	UNIT	15	EQUIPMENT WORN BY J	UMP	ER	16	. JUMPER'	S POSITION	IN ACFT
					Alice, M195	0.1	B-7. LCE		Le	ft Doo	r AJ
17. TYPE PARACHUTE	18.				TYPE MALFUN						19. NO. JUMPS
(Specify)		SEMI-I	NVERSION '		INVERSION	T	CIGARETTE ROLL		OTHER (S	PECIFY)]
		PILOT	CHUTE		BLOWN SECTION	Т	BROKEN SUSPEN-		Activat	ion of	1
T-10C		1					SION LINE		reserve		70
20. TYPE OF RESERVE	21.		FUNCTION-		22. RESULTING INJUR	Υ					•
T-10R		"No" ex			1						
JM/mix w/ MIRPS		item 31)					Doole/I + A	****			
MIKES		Ш	YES	NO			Back/Lt A	ATIII			
						_					
bundle from the bundle. By doing line. The jumper the edge of the ju attempts to dislo pull back on the the bundle went rearbut before sucked out of the two parachutes of	so and amp dgo upp out he de	, the job distributed the control of	umper unesses statements the door burdes and purned to leget com. What h	nkn atec wi ndle oush look ple e ca	owingly crossed that as he contind caught the do, he rocked and forward while at the primary tely around he fun recall after the	l hi nu kic kic jun elt at i	is static line ved to position bundle and leaded it. He alcking at the bundle small tug, as that he had	vith n th lod lso ase ith a ha	n the bune door ged it i stated to dislout clear ard tug	indle's bundle in the country that he lodge is aring to and he	static e toward loor. In e had to t. After o the e was
								•			
			CO	NT	INUED ON N	EX	KT PAGE				

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

Jumper's ripcord was pulled by the door bundle's static line as the bundle was ejected. After the ripcord was pulled, the (reserve) pilot parachute was exposed. As the pilot parachute caught air, it pulled the jumper out of the aircraft. The jumper crossed his static line with the bundle static line when he moved around the bundle as he positioned it for the drop. As the jumper was deployed, the bundle's static line and D-bag passed between his upper body and his upper body and his inner left arm, from back to front. The jumper landed on the DZ with both canopies fully inflated and sustained injuries to his back, left arm, and minor bruising. The reserve had two broken suspension lines, frayed lines on the left side, and the pack tray was damaged. The ripcord grip was not found. The main parachute and D-bag were shipped out before they could be inspected. The T-10 cargo static line was broken (in two) at 32 inches from the clevis. The jumper's static line was also broken, but not separated into two, at 35 inches from the snap hook. The trail edge of the parachute door was slightly damaged.

ANALYSIS: 23

WHAT WAS THE MALFUNCTION?

Extracted from aircraft by reserve (T-10R) activation.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Door bundle static line interacted with ripcord grip deploying and extracting jumper.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Door control of static line by safety practicing door procedures. Policy should be followed: i.e. Waiver is for USASOC ONLY!!

•						_					
. UNIT BEING AIRLIFTED			2. DEPARTU	RE AIR	GENERAL	13	DATE	ΙΔ	TYPE ACET	1	5. ACFT SER NO.
J BEING PINER IED			1 227 3110			1]	C-13	į.	J. J.C. 1 JER NO.
5. OPERATION/EXERCISE				-	7. DZ AND LOCATION				8. DATE A		
9. ACFT ALTITUDE (Feet)	10.	ACFT SPI	EED (Knots)	11	. DZ ELEVATION (Feet)		12. SURFACE W	INDS ((nots)	13. VISIBI	LITY (Feet/Miles)
1000 AGL		13	0		UNK		6 - 8			:	Unlimited
II.					PERSONN	L					
14. NAME (Last, First, MI), G	RADE,	SSAN, &	UNIT	15	. EQUIPMENT WORN BY	JUMI	PER		16. JUMPER	'S POSITIO	IN IN ACFT
					LBE, Alic						
	T			1	1950 WC	B	7			8th.	R Door
17. TYPE PARACHUTE (Specify)	18.			·	TYPE MALFUI	ICTIC	ON				19. NO. JUMPS
	_	 	NVERSION '	╁	INVERSION	4	CIGARETTE ROLI		OTHER (SPECIFY)	4
T 100		PILOT	CHUTE		BLOWN SECTION	١	BROKEN SUSPEN	1-	MIRE		
T-10C	 _		P. (A)	Ш	I as pressure as		SION LINE		Deple	oyment	8
20. TYPE OF RESERVE	21.	ED PRO	FUNCTION- PERLY (If oplain in		22. RESULTING INJU	×Υ					
		item 31									
MIRPS			YES	NO					None		
32. CAUSE OF MA Jumper had a ba				Ì	-				,	e of the	e door.
								_			
			CO	NT	INUED ON N	ΈΣ	KT PAGE				

WHAT WAS THE MALFUNCTION?

Dual deployment. T-10C and MIRPS activation without deployment.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Ripcord grip contact with the door.
 Two parachutes (reserve and main) were opened upon deployment.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Exhausted soldier on the aircraft led to error.

<u> </u>					CENTRAL						
: I. UNIT BEING AIRLIFTED			2. DEPARTU	JRE AIF	GENERAL RFIELD	3.	DATE	1 4	TYPE ACFT		5. ACFT SER NO.
				,,,,		1		Γ	C-130	n	3.7.6.1.32.1.10.
5. OPERATION/EXERCISE			L .		7. DZ AND LOCATIO				0-130 8. DATE A		
). ACFT ALTITUDE (Feet)	10.	ACFT SPE	ED (Knots)	1	1. DZ ELEVATION (Feet)		12. SURFACE V	VINDS	(Knots)	13. VISIB	LITY (Feet/Miles)
1000 Feet		130 k	Knots		335 Feet		3-5 k	Cnot	S	Ur	limited
ı.					PERSONN	EL					
14. NAME (Last, First, MI), G	RADE,	SSAN, &	UNIT	15	. EQUIPMENT WORN B	JUMI	PER		16. JUMPER	'S POSITIO	ON IN ACFT
				ł	I CE D		1			4 . 5	
	T				LCE, Ru					1st P	ass, 1st
17. TYPE PARACHUTE (Specify)	18.			·	TYPE MALFL	NCTIC	ON				19. NO. JUMPS
	_	SEMI-I	NVERSION '	4	INVERSION	Н	CIGARETTE RO	LL	OTHER (SPECIFY)	4
T 100		PILOT	CHUTE		BLOWN SECTION	H	BROKEN SUSPI	N-	Rese		7
T-10C	 	<u> </u>		لــلـ		Ш	SION LINE		Activ	vation	//
20. TYPE OF RESERVE	21.	ED PRO I	FUNCTION- PERLY (#		22. RESULTING INJ	IRY					
		item 31)	plain in 	_							
MIRPS			YES	NO					None		
					7						
Jumper said that felt that he was reserve reacted	at he falli	had t	wists af ster than	ter h	ne exited the ai	rcra	ft and who	en he	e correc	ted the	em he
							_				
			CO	NT	INUED ON I	NEΣ	XT PAGE				

WHAT WAS THE MALFUNCTION?

INCIDENT - Intentional activation.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Soldier error.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Training.

					-				
I. 1. UNIT BEING AIRLIFTED		2. DEPARTUE	E AII	GENERAL	Т,	. DATE	4. TYPE	ACET	5. ACFT SER NO.
I. ONIT BEING AIRLIFTED		2. DEPARTOR	ie An	RFIELD.	'	. DATE	1	-130	S. ACFT SER NO.
6. OPERATION/EXERCISE				7. DZ AND LOCATIO	<u></u>			ATE AND TIME	
							1		
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEED (Knots)	1	1. DZ ELEVATION (Feet)		12. SURFACE WIN	DS (Knots	i) 13. VISIB	ILITY (Feet/Miles)
1,500 AGL		130 Knots		1000 Feet		6 Kn	ots	U	nlimited
II.				PERSONN	EL				· · · · · · · · · · · · · · · · · · ·
14. NAME (Last, First, MI), (RADE,	SSAN, & UNIT	19	5. EQUIPMENT WORN B	/ JUM	PER	16. JU	JMPER'S POSITI	ON IN ACFT
								6p,	
	T		1			Telmet		4th Jum	
17. TYPE PARACHUTE (Specify)	18.			TYPE MALFL	NCTI	ON			19. NO. JUMPS
	_	SEMI-INVERSION		INVERSION	₽	CIGARETTE ROLL	0	THER (SPECIFY)	4
MC1-1C		PILOT CHUTE		BLOWN SECTION	П	BROKEN SUSPEN- SION LINE		Iid Air	UNK
20. TYPE OF RESERVE	+-	RESERVE FUNCTION	L	22. RESULTING INJ		SION LINE	Eı	ntanglement	OIVIX
20. TYPE OF RESERVE	121.	ED PROPERLY (If "No" explain in		22. RESULTING INJ	JKT				
	i	item 31)							
T10-R	j	YES	NO			Non	e		
				77					
This was an inclower jumper by 32. CAUSE OF MA This was an inclohimself headed but had turned jumpers turned suspension line deployed their down and then into the wind. A Both jumpers a foot and could jumper execute equipment or a awareness.	LFUI LFUI iden towatowarigh ss be reser infla fter ttem not { ed a l	ning into his sunction/FAILUR at not a malfundard the second and him was sunctioned the second putterning he saw upted to turn right free. Both justeft PLF and the	usp E (I ctic I ju I light I th I um I th	f more space is a con. Jumper statemper. Second htly lower and woid each other are states he was a first jumper has a collist pers activated irst jumper a rist jumper a r	es the wood in Figure 1 in Figure 2 in Fig	ed, continue or nat he was ru- per who had ald have pass rst jumper st Both jumper immediately inning with t ing towards first jumper erves as prev PLF. Both ju	nning been; sed to ruck so had y, the so he winhim ar becamviously amper	with the v running v the right. econd jun a good ca econd jun nd and tur nd slightly ne entang y stated. S	vind, found vith the wind Both nper's nopy and nper's fell ned right higher. led by one second injured. No
		CO	NT	'INUED ON I	NEX	XT PAGE			

WHAT WAS THE MALFUNCTION?

INCIDENT - Entanglement between jumpers under canopy.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- Failure to maintani contact of canopy.
 Improper procedures.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

SAT conducted properly.

1. UNIT BEING AIRLIFTED			2. DEPARTU	DE AIR	GENERAL	2	DATE	A -	YPE ACFT		5. ACFT SER NO.
1. UNIT BEING AIRLIFTED			Z. DEPARTU	KE AIN	FIELD]*	DATE	4. 1		_	S. ACFT SER NO.
6. OPERATION/EXERCISE					7. DZ AND LOCATION	1		Ц	C-13		
, or Electronic Actions					TO DE AND ESCANON				0. 0. 1. 1.		
9. ACFT ALTITUDE (Feet)	10.	ACFT SPE	ED (Knots)	11	. DZ ELEVATION (Feet)		12. SURFACE WINE	os (K	nots)	13. VISIB	LITY (FeetiMiles)
10,000		135	Knots		670		5 Kr	ots	S	C	lear
II.					PERSONNI	L					
14. NAME (Last, First, MI), G	RADE,	SSAN, &	UNIT	15	EQUIPMENT WORN BY	JUMP	ER	1	6. JUMPER	'S POSITIO	IN IN ACFT
				1		lone	2	١			7.7
17. TYPE PARACHUTE	18.			ļ	TYPE MALFUI					UN	19. NO. JUMPS
(Specify)	-	65,44,5	NVERSION '	· T 1	INVERSION	T. T.	CIGARETTE ROLL		OTHER	- 19. NO. JOMPS	
	-		CHUTE	╅	BLOWN SECTION	╅	BROKEN SUSPEN-		OTHER	SPECIFY)	4
MC-4	1	1	CHOTE		BEOWN SECTION	- 1	SION LINE		Cut Away 400		
20. TYPE OF RESERVE	21.		FUNCTION-	لببيا	22. RESULTING INJU	RY			<u> </u>	1 Ivia,	
	ļ	"No" ex									
MC-4		item 31)	YES	NO	-						
											
noticed that his reconducted his er landed safely on feet. The AR2 distribution of the safely of the	LFUN	drop etting ECTION f the r cond	zone. Tl was 27: N/FAILUR malfunct	ne ju 50 N E (If tion it to	more space is ne could be that the fire at it's setti	eded	I, continue on R2 was still of 2750 MS	rev ser	rerse.)	n exce	ely 2000
			CO	NT	INUED ON N	EX	T PAGE				

WHAT WAS THE MALFUNCTION?

MC4 dual activation of main and reserve due to AR2 firing at 2000 feet.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Premature activation of AR2.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Change AR2 setting to 1500 if mounting on reserve.

						GENERAL	_					
UNIT BEING AIRLIFTED		1:	2. DEPARTU	RE All	RFII		3.	. DATE	4.	TYPE ACFT		5. ACFT SER NO.
							1			Casa	212	
OPERATION/EXERCISE			•		T	7. DZ AND LOCATION	<u> </u>			8. DATE A		
ACFT ALTITUDE (Feet)	l	ACFT SPEE	-	1	11. [OZ ELEVATION (Feet)		12. SURFACE W		Knots)		LITY (Feet/Miles)
2,500 Feet AGL	<u> </u>	130 K	nots			490 Feet		UN	K		3	0 Miles
1. NAME (Last, First, MI), GF	ADE	CCAN 0 11	MIT	111	5 6	PERSONNE QUIPMENT WORN BY		DED		16 11184055	o's positiv	ON IN ACFT
4. NAME (Last, First, Mij, Gr	AUE,	33AN, Q U	MII		J. E	QUIPMENT WORN BY	I VIWI	ren		10. JUMPER	. 3 703111	JN IN ACT
				ı		MC-4 Para	ch	ute System			1s	t
7. TYPE PARACHUTE	18.					TYPE MALFUN						19. NO. JUMP
(Specify)		SEMI-IN	version '			INVERSION		CIGARETTE ROL		OTHER ((SPECIFY)	
MC-4		PILOT C	HUTE			BLOWN SECTION		BROKEN SUSPER	1-	AR2		$\frac{1}{1}$
0. TYPE OF RESERVE	21	RESERVE F	UNCTION.	<u> </u>	Ч	22. RESULTING INJU	<u>.</u>	3,014 2,1142		activ	ation	1
e or nedere	•	ED PROPE "No" expl	RLY (H			NESOCINO 11901	••					
MC-4		item 31)								Non	ie.	
WIC-4		<u> </u>	ES	NO						1 (01)		
32. CAUSE OF MAI Cause was jump lost altitude awa	er iı	nexper	ience.	Γhe	jι	ımper was un	sta	ble at his p	ılla	ltitude	of 400	0 feet and
									_			
			co	NT	ſΙΊ	NUED ON N	ΈΣ	XT PAGE				

WHAT WAS THE MALFUNCTION?

INCIDENT - Failure to pull.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Jumper error.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

More training.

										*
1.				GENERAL						
1. UNIT BEING AIRLIFTED		2. DEPARTU	RE Al	RFIELD	3.	DATE	4. TY	PE ACFT	1	S. ACFT SER NO.
					_			asa 21		
6. OPERATION/EXERCISE				7. DZ AND LOCATION			8	B. DATE A	ND TIME	
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEED (Knots)	1	1. DZ ELEVATION (Feet)		12. SURFACE WINE	DS (Kn	ots)	13. VISIBIL	ITY (Feet/Miles)
12,500 Feet AGL	Ĺ	130 Knots	ı	490 Feet		UNK			30	Miles
II.				PERSONNE	L					
14. NAME (Last, First, MI), G	RADE,	SSAN, & UNIT	1:	S. EQUIPMENT WORN BY J	UMP	ER	16	. JUMPER	's POSITIO	N IN ACFT
				ICRAP Javelin	ı J-	5			1	
17. TYPE PARACHUTE	18.			TYPE MALFUN	CTIQI	N				19. NO. JUMPS
(Specify)	П	SEMI-INVERSION	Г	INVERSION	Т	CIGARETTE ROLL		OTHER (SPECIFY)	٦
Performer	П	PILOT CHUTE	1	BLOWN SECTION	十	BROKEN SUSPEN-		Aggida	ntal acti-	7
design SP-190	'				1	SION LINE			of MIRP	
20. TYPE OF RESERVE	21.	RESERVE FUNCTION-	-	22. RESULTING INJUR	Y					1000
	ļ	ED PROPERLY (If "No" explain in		į						
D 1	l	item 31)				NT				
Raven 1		X YES	NO			None	2			
							,			
The jumper is a failed to deploy feet deploying the studiest the reserve partic activation 1020 feet AGL. reserve canopy. were found. 32. CAUSE OF MAI The CYPRES fiscribed pull altitude of 1020	his ne n ent a para dev The No	own main parnain canopy. Tand experience chute deploying (CYPRES) injury. After a section/FAILUR when the instact of 2500 feet A	ach The ed ang S) fed a 10	nute. The studen instructor stated a slow opening. and performed or ired and deployed approximately 5 to percent TRI of the form of the space is new toor deployed his	t's As I that As cutaed by the As I that a cutae by the As I that a cut	AR2 actuate at he deploy his main paraway proces is reserve p meters off the jumper's off, continue on ain parachute	ed at red h rach dure arac he d equi	appropriate appropriate was The chute a rop zo pmen	eximatin para as deple jumpe at approne with the definition of the	ely 2000 chute after oying he er's auto- oximately h the efficiencies
		СО	NT	'INUED ON N	EX	T PAGE				

WHAT WAS THE MALFUNCTION?

INCIDENT - (Dual Deployment) SP 190 nonstandard Javelin container low and slow opening.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- Maintaining student control caused low pull but slow opening.
 Entered CYPRESS opening window.
 CYPRESS fired.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Ensure instructors follow SOP.

TAR&M/SA VOL II

			r		GENERAL	_					
. UNIT BEING AIRLIFTED			2. DEPARTU	KE AIR	FIELD	3.	DATE	4.	TYPE ACFT		5. ACFT SER NO.
ORTON TION EVEN CICE					7. DZ AND LOCATION	1_			UNK	ND 7945	
5. OPERATION/EXERCISE					7. DZ AND LUCATION				8. DATE A	NUTIME	
. ACFT ALTITUDE (Feet)	10.	ACFT SPE	ED (Knots)	11	. DZ ELEVATION (Feet)		12. SURFACE WI	NDS (I	Knots)	13. VISIB	LITY (Feet/Miles)
UNK		Uì	NK		UNK		U	NK	-	Uì	ΝK
ı.					PERSONNI	L					
4. NAME (Last, First, MI), (GRADE,	SSAN, &	UNIT	15.	EQUIPMENT WORN BY	IUMI	PER		16. JUMPER	'S POSITIO	ON IN ACFT
					· UNK					τ	INK
17. TYPE PARACHUTE (Specify)	18.				TYPE MALFU	ICTIC	N				19. NO. JUMPS
	<u> </u>	SEMI-I	NVERSION '	Ш	INVERSION	_	CIGARETTE ROLL		OTHER (SPECIFY)	_
UNK		PILOT	CHUTE		BLOWN SECTION		BROKEN SUSPEN	•	ŀ		UNK
20. TYPE OF RESERVE	21.	RESERVE	FUNCTION-		22. RESULTING INJU						01(1)
		ED PROF	PERLY (If		1						
LINIZ		item 31)			ļ						
UNK			YES	NO							
32. CAUSE OF MAI Jumper stepped by ripcord grip.										picked	d up MIRP
							_				
			CO	NT.	INUED ON N	ΈΣ	KT PAGE				

WHAT WAS THE MALFUNCTION?

INCIDENT - Reserve activation on ground.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- Reserve improperly handled.
 Carried by ripcord grip.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Train soldiers on handling procedures.

TAR&M/SA VOL II

					GENERAL					***	
UNIT BEING AIRLIFTED		2. DEPA	RTURE	AIRF		3.	DATE	4	. TYPE ACFT		5. ACFT SER NO.
									C-17		
OPERATION/EXERCISE					7. DZ AND LOCATION				8. DATE A	ND TIME	
ACFT ALTITUDE (Feet)	110.	ACFT SPEED (Knot	s)	I 11.	DZ ELEVATION (Feet)		12. SURFACE N	WINDS	(Knots)	13. VISIB	LITY (Feet/Miles)
	"	130 Knots	•	1					-	1	
800 Feet		130 Kilots		1_	360 Feet PERSONNE		0-3	Kno	Jis	l	Mile
4. NAME (Last, First, MI), (SRADE,	SSAN, & UNIT		15.	EQUIPMENT WORN BY J		PER		16. JUMPER	R'S POSITIO	ON IN ACFT
					Comb	ot			р	1 0 /Cl	J1- 0
7. TYPE PARACHUTE	18.				TYPE MALFUN	_	N		<u> </u>	18/Ch	11K. O 19. NO. JUMP
(Specify)		SEMI-INVERSIO	· T	T	INVERSION	T	CIGARETTE RO	LL	OTHER	SPECIFY)	-
		PILOT CHUTE	1		BLOWN SECTION	1	BROKEN SUSP	EN-	Enta	ngle-	1
T-10C	+-	OF CERNIE FUNCTIO			22 PECHTING NAME		SION LINE		ment		13
0. TYPE OF RESERVE	21.	RESERVE FUNCTIO ED PROPERLY (If "No" explain in	TN -		22. RESULTING INJUR	1					
		item 31)	_						_		
MIRPS		YES _		NO			2	pine	e Factur	e	
32. CAUSE OF MAI Failure of jumpe				`	-	deo	l, continue	on re	everse.)		
								_			

WHAT WAS THE MALFUNCTION?

INCIDENT - Low altitude entanglement.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- Improper air awareness.
 Failure to maintain distance.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Upon collapsing of both canopies, jumpers should activate reserves.

I.		2 85848		GENERAL		DATE I		(05.4657		ACCTCCCNO
1. UNIT BEING AIRLIFTED		2. DEPARTUR	t All	CHELD	3.	DATE		PE ACFT		. ACFT SER NO.
6. OPERATION/EXERCISE		_		7. DZ AND LOCATION			_	Casa 21		
or and the state of the state o							ľ			
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEED (Knots)	11	1. DZ ELEVATION (Feet)		12. SURFACE WIND	s (Kn	ots) 13	. VISIBIL	ITY (Feet/Miles)
8000 feet AGL		90 Knots		490 Feet		6 Knots				0 Miles
II.		70 Kilots	1.	PERSONNEL		O IXIIOL	3	L		O IVIIICS
··· 14. NAME (Last, First, MI), G	RADE,	SSAN, & UNIT	119	5. EQUIPMENT WORN BY JU	MP	ER	16	i. JUMPER'S F	POSITIO	N IN ACFT
			1							
			1	MC-4 Ram Air	·P	arachute			5th	
17. TYPE PARACHUTE	18.			TYPE MALFUNCT	rio	N		•		19. NO. JUMPS
(Specify)		SEMI-INVERSION		INVERSION	T	CIGARETTE ROLL		OTHER (SPE	CIFY)	1
		PILOT CHUTE		BLOWN SECTION	T	BROKEN SUSPEN-		Line		1
MC-4					I	SION LINE		Twists	;	20
20. TYPE OF RESERVE	21.	RESERVE FUNCTION ED PROPERLY (IF		22. RESULTING INJURY						
	1	"No" explain in item 31)								
MC-4	1	X YES	NO			None				
1/16 1					_	TVOILE				
					Ξ					
parachute was spread in the up jumper performed group on the interposition, pilot palines. After a 10 found. 32. CAUSE OF MAINTHIS malfunction. This caused multiple in the product of inflate products.	poinn posi ed c ende aracl 0 pe LFUN n wa tiple operir	ing and twistin tion. The jump utaway proced ad drop zone. Chute and bridle reent TRI of the CTION/FAILURE as due to the jure line twists that ly. Due to the extension.	er urce line (If mp	mper stated that he is it deployed. The went into a hard es. Reserve deployed opy was found when were wrapped MC-4 system, no more space is need er's unstable bod ept the slider in the essive line twists, procedures after	regritlar o	te to four cellight turn, after ed normally. In multiple line to und suspend ther deficient, continue on a position while up position can imper had	s in rate and Jurne to sion cie	out four four four four four four land wists, slin lines a es or danderse.) ulling the sing the nuncontrol for the four four four four four four four four	The sir rotanded ider i ider i ind stand stand stand stand mage	lider tions, the with the n the up eering was in ripcord. canopy ble right
		CON	Tr	'INUED ON NE	EX	T PAGE				

WHAT WAS THE MALFUNCTION?

MALFUNCTION - MC4 failed to fully inflate or deploy.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Unstable opening leading to line twists.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Stable opening sequence.

1. UNIT BEING AIRLIFTED					GENERAL						
			2. DEPARTU	RE All	<u> </u>	3	DATE	4.	TYPE ACFT	I	5. ACFT SER NO.
									C-13	0	
. OPERATION/EXERCISE					7. DZ AND LOCATION	.			8. DATE A		
. ACFT ALTITUDE (Feet)	10.	ACFT SPE	ED (Knots)	1	1. DZ ELEVATION (Feet)		12. SURFACE W	ANDS (Knots)	13. VISIBI	LITY (Feet/Miles)
800 Feet			Knots		360 Feet		0-5	_		1	Miles
800 PCCt		130	XIIOts		PERSONN	F L	0-3	IXIIO	ıs	/	WITIES
4. NAME (Last, First, MI), (GRADE,	SSAN, &	UNIT	11	S. EQUIPMENT WORN BY		PER	1	16. JUMPEI	R'S POSITIO	ON IN ACFT
					Combat					#19 ch	valle 1
7. TYPE PARACHUTE	18.				TYPE MALFU	NCTIO	ON			#19 CI	19. NO. JUMP
(Specify)		SEMI-II	VERSION '	Т	INVERSION		CIGARETTE ROL	L	OTHER	(SPECIFY)	_
T 10C		PILOT	СНИТЕ		BLOWN SECTION		BROKEN SUSPE	N-		wed	17
T-10C	+-	05650145	FUNCTION		22 85011 7110 1111		JON LINE		10	mper	17
20. TYPE OF RESERVE	21.	ED PROP			22. RESULTING INJU	ĸΥ					
_	1	item 31)									
MIRPS			YES	NO			Ŋ	Jeck	/Back		
					7						
32. CAUSE OF MAI Statements from underneath his r continuing.	n jun	npers	in his sti	ck i	ndicate that the	jui	nper (towe	ed), r	nisrout	ed his stigatio	static line on is
Statements from underneath his	n jun	npers	in his sti	ck i	ndicate that the	jui	nper (towe	ed), r	nisrout	ed his stigatio	static line on is

WHAT WAS THE MALFUNCTION?

Towed jumper by static line (T-10C).

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Improper routing of static line underneath right risers by jumper prior to hook up.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Safety failed to properly insure static line routing.

						-					
1. UNIT BEING AIRLIFTED			2. DEPARTU	DE AIF	GENERAL	T 2	DATE	1 4	TYPE ACFT		5. ACFT SER NO.
I. ONII BEING AIRLIFTED			Z. DEPARTU	RE AIT	FIELD	'	DATE	1		12	S. ACFT SER NO.
6. OPERATION/EXERCISE					7. DZ AND LOCATIO			L	Casa 2		
U. O. ERATION/EXERCISE					DE AND LOCATION				D. DATE A		
9. ACFT ALTITUDE (Feet)	10.	ACFT SPEI	ED (Knots)	11	I. DZ ELEVATION (Feet)		12. SURFACE V	VINDS	(Knots)	13. VISIBI	LITY (Feet/Miles)
1,500 Feet AGL	ı		Knots		269 Feet			Kno			5 - 7 Miles
II.	L	1031	XIIUIS		PERSONN	EL	1 0	XIIO		L	J - / WILLS
14. NAME (Last, First, MI), GR	ADE,	SSAN, & U	JNIT	15	EQUIPMENT WORN B		PER		16. JUMPER	'S POSITIO	IN IN ACFT
					Ballistic helm	et. N	/IC1-1C,				
					MIRPS				6th	2nd	
17. TYPE PARACHUTE (Specify)	18.				TYPE MALFL	NCTIC	ON				19. NO. JUMPS
		SEMI-IN	IVERSION '	_	INVERSION	Ш	CIGARETTE RO	LL	OTHER	SPECIFY)	_
MC1-1C Troop		PILOT	CHUTE		BLOWN SECTION	ΙI	BROKEN SUSPE	N-		ved	
Back Parachute		<u> </u>				Ш	SION LINE		Jun	nper	60
20. TYPE OF RESERVE	21.	ED PROPI			22. RESULTING INJ	JRY					
		item 31)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,								
MIRPS		<u> </u>	res	NO	<u> </u>			N	one		,
32. CAUSE OF MAI According to the instead jumper k	e st	ateme	nt made	by	the 7th jumpe	r, sc	oldier did r		-	a 45 de	gree angle
								_			
			со	NT	INUED ON I	NEX	XT PAGE				

WHAT WAS THE MALFUNCTION?

MALFUNCTION - Towed jumper from CASA 212.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- Obstruction in suspension lines/delay in deployment sequence.
 Misrouting of static line.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Safety inspection of static line routing.

CARGO MALFUNCTION REPORTS AND ANALYSES

I.		G	ENERAL				
1. UNIT BEING AIRLIFTED	2. DEPARTUR	E AIRFIELD	3. D	ATE	4. TYPE ACF	T	5. ACFT SER NO.
	ŀ				MC-1	30	
6. OPERATION/EXERCISE	•	7. DZ AND	LOCATION		8. DATE	AND TIME	
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVAT	ION (Feet)	12. SURFACE WIN	D\$ (Knots)	13. VISIB	ILITY (Feet/Miles)
673 MSL	140	118	MSL	Calm		20	000/3
			7				
III.			CARGO				
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/	NAVAIR No.)	25.	A C DI A L	SEL BUEBU EVE	TEMALICED	
WEIGHT	FM 10-500-2	2/	23.	ACRIALI	DELIVERY SYS	TEM USED	
	TO 13C7-1-5	5	DUAL RAIL	. CDS REL	EASE GATE	OTHER (Explain)
HE	FM 10-512/		NO. PLATFORMS	NO. CON	TAINERS	1	
3020 LBS	TO 13C7-1-8	8	1				
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		RACTION/RE- PARACHUTE	29. LENGTH O	REEFING	30. POSI AIRCI	TION OF LOAD IN RAFT
Type V	G-12 (2)	1:	5				FS 617

31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.)

At the green light call during a HE airdrop, the 15-foot extraction parachute released from the bomb rack and fell on the ramp of the aircraft resulting in a malfunction. No damage was incurred except a piece of type IV coreless nylon cord (pendulum line).

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

The knot in the running end of the pendulum line where it is spliced/chinese braided to itself around the attachment loop came undone causing the extraction parachute to fall on the ramp when it was released from the bomb rack at green light. The pendulum line remained hanging from the pivot arm. There was no knot in the tapered end of the pendulum line, it was unraveled about 1/2 inch and there was no sign of any seared/burnt threads on the tapered end. There were a few broken threads where the line had been spliced/braided together. The line appears to be fairly new. I suspect the knot was loosely tied and/or not 1 inch back from the seared tapered end, resulting in the knot coming undone and slipping through the cord casing releasing the pendulum line from the deployment bag attaching loop.

· · · · · · · · · · · · · · · · · · ·
CONTINUED ON NEXT PAGE

WHAT WAS THE MALFUNCTION?

15-foot extraction parachute did not deploy. Fell to the floor of the aircraft.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Pendulum line came untied or misrouted possibly broken.
- 2. Possibly too much tape.
- 3. Could not properly inspect.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Not given.

I.		G	ENERAL				
1. UNIT BEING AIRLIFTED	2. DEPARTUR	E AIRFIELD	3. D	PATE	4. TYPE ACF C-13		5. ACFT SER NO.
6. OPERATION/EXERCISE	<u> </u>	7. DZ AND	LOCATION		8. DATE	AND TIME	
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVAT	TION (Feet)	12. SURFACE WIND	\$ (Knots)	13. VISIBII	LITY (Feet/Miles)
1300 Feet AGL	130	42	6 Feet	2 Knot	ts	30	000 Feet
		-	7_				
111.			CARGO				
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/N	VAVAIR No.)	25.	AERIAL D	ELIVERY SYS	TEM USED	
DEUCE			DUAL RAIL	. CDS RELE	ASE GATE	OTHER (E	xplain)
40,700 LBS	FM 10-521/		NO. PLATFORM	S NO. CON	TAINERS	1	
rigged weight	TO 13C7-6-2	1					CVR
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		TRACTION/RE- PARACHUTE	29. LENGTH OF LINE	REEFING	30. POSITI AIRCR	ION OF LOAD IN AFT
Type V (24-Foot)	G-11C (8)	28-Fo	ot (2 each)			1 0	of 1

31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.)

Malfunction NCO stated that the load had a good exit, seven of the eight parachutes deployed normally. One G-11C failed to fully inflate. The load landed with seven parachutes and sustained no damage. The damaged parachute was in the third position on the release, bottom right. Once the load made contact with ground, the M-2 release failed to release the parachutes. Inspection of the deployment bags revealed that the number one and number three D-bags were fused together at the bridle assembly. On the malfunctioned G-11, one riser (lines 51 through 60) was broken and the remaining suspension lines of that riser group were broken at the connector link. The inspection also revealed damage to canopy around the lower lateral band and ripped stitching on the radial seams in the first 3 sections of gores 26 to 84. The other parachutes suffered some damage to suspension lines due to added strain. Initial inspection of the M-2 release revealed that the timer keys had retracted properly but the timer did not fall. In 10 tests after the drop, the timer fell at approximately 12 - 14 seconds. The nuts on the face plate of the release were tightened flush with the bolts but still allowed movement within the release.

CONTINUED ON NEXT PAGE

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

Analysis of photographs taken during the deployment phase indicates that the parachute began to inflate before the others causing it to take the full stress of the opening shock before the others. The age of the parachute may have been a contributing factor, the date of manufacture was Aug 1963. TRI of the release revealed the timer keys extending out of the timer block approximately 1/8 inch, one key had rust on the end of it, a release timer face plate screw was missing. This allowed the face plate to partially separate from the timer body. This allowed the timer to jam inside the release body not allowing the keys to fully retract into the timer. The rust on the end of the one key could jam inside the release body not allowing the keys to fully retract into the timer. The rust on the end of the one key could have also prevented the keys from retracting.

ANALYSIS: 36

WHAT WAS THE MALFUNCTION?

G-11 did not deploy and M-2 release did not release.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Failure to perform proper maintenance on timer.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Provide proper training on M-2 inspection and repair.

	***		·							
				NERAL						
. UNIT BEING AIRLIFTED		2. DEPARTURE	AIRFIELD	l	3. DA1	ΓE		PE ACFT		5. ACFT SER NO.
			1					C-17		
5. OPERATION/EXERCISE			7. DZ AND	LOCATION			*	. DATE A	ND TIME	
	·		i						,	
ACFT ALTITUDE (Feet)	10. ACFT SPE		11. DZ ELEVATI		12	. SURFACE WIN	D\$ (Kn	ots)	1	BILITY (Feet/Miles
550	14	5	110	63	1	8			U	nlimited
			"	7_						
111.			(CARGO	•					
3. TYPE LOAD AND	24. RIGGE	NAW (TMITOINA	VAIR No.)	35		450(4)	251 1145	DV 5V5T		
WEIGHT	1			25.		Atkial i	PELIVE	KY 5Y51	EM USED	
				DUAL	RAIL	. CDS REL	EASE	ATE	OTHER	(Explain)
Heavy Type V	j			NO. PLATFO	ORMS	NO. CON	ITAINE	RS		
3000 LBS				1						
26. TYPE PLATFORM/AIR-	27. TYPE P	ARACHUTE		RACTION/RE-		29. LENGTH O	F REEFI	NG	30. POS	ITION OF LOAD IN
DROP CONTAINER		IUMBER	LEASE P	ARACHUTE		LINE			AIRC	RAFT
			1							
Type V	G-1	2E(2)	15-Foo	t Drogue	2					
mined. 32. CAUSE OF MAL	FUNCTION	n/failure	(If more spa	ace is need	led, c	ontinue on		rse)		
				ice is nece			rever	30.,		
U 1				lefinite o					n can	not be
The drogue parac determined. The				lefinite o					n can	not be

WHAT WAS THE MALFUNCTION?

Drogue parachute failure.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Excessive stress due to multiple use.
- 2. Excessive air speed.
- 3. Drogue parachute not designed for use behind C-17. (Possibly not enough information to make a determination.)

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Enhanced drogue parachute designed for C-17 and modify parachutes according to modification guidelines before using in C-17.

I.	 	· · · · · · · · · · · · · · · · · · ·	GE	NERAL						
1. UNIT BEING AIRLIFTED		2. DEPARTURE A	RFIELD		3. DA1	ΓE	4.	TYPE ACF	T	5. ACFT SER NO
6. OPERATION/EXERCISE			12.02.442	OCATION			L	C-17	AND TIME	
6. OPERA HON/EXERCISE			7. DZ AND I	OCATION				8. DATE	AND HMI	:
9. ACFT ALTITUDE (Feet)	10. ACFT SPE	ED (Knots)	11. DZ ELEVATI	DN (Feet)	12	. SURFACE W	INDS (Knots)	13. VISI	BILITY (Feet/Mile
1300 Feet	130	Knots	274	Feet		3	Kno	ots		7
				7_						
III.			(CARGO						
23. TYPE LOAD AND WEIGHT	24. RIGGE	DIAW (TMITOINAV	/AIR No.)	25.		AERIA	L DEL	VERY SYS	TEM USEC)
130G Motor	EV/	I 10-573/		DUAL	RAIL	. CDS	RELEAS	SE GATE	OTHER	(Explain)
Grader	l .	110-373/ 13C7-27-	1/11	NO. PLATF	ORMS	NO. C	ONTAI	NERS	1	
36589 Lbs	1	apter 3	171	1						
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE P	ARACHUTE	28. SIZE EXT LEASE P	TACTION/RE- ARACHUTE		29. LENGTH LINE	OF RE	EFING		ITION OF LOAD IN
DIO. CONTRIBER										
Т И 20 Г4	C 1	10 (0)	28-Foo		tion	1			1	- C 1
Type V, 28 Foot	G-1	1C (8)	Parachu	ite					1	of 1
extracted as intenappeared to be del severed/broken at other G-11C did not tangle within itself. Further damages of clevis broken in his caused two left reported on the 13	ayed up out 18 i ot fully i f. The ris of equipr alf. Due ar tires t	oon deployr inches from inflate due t ser extension ment are a g to no lift of o blow out	ment phase to six brolen has seven uillotine- two cand causing of	se. The chute recent suspers burn type knopies the lamage	120 f eleaso ensi s alo ife sp e load	foot/2 lose connection lines on lines on the endit open dimpact	op retor cau ntire and ted v	of the sing the length a nut with gr	M2 re M2 re ne para n of the from a reater t	on was elease. The achute to e outside plands a clustering force and
		CONT	INUED	ON NE	XT	PAGE				

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

G11C's were inspected and found the following damage. 1st G11C serial #219, DOM Jan 87, PIS Oct 90, had the following lines broken: 89-94. Possible cause of broken lines causing the malfunction are due to an entanglement with the rear towing pintle link on the 130G. Upon deployment phase the five suspension lines snagged on that part of the load causing the lines to break. Second G11C serial #1060, DOM Nov 53, PIS Jan 65. Lower lateral band damage as follows: Line 60, sections 1-4 blown and separated from radial seam. Sections 5 and 6 burnt canopy. Line 61 fire wall cutter bracket separated from lower lateral band. Lines exposed in sections 3 and 4. Lines 59-63 pocket bands separated from lower lateral band. The cause of the second G11C to malfunction is not known. The cause of damage to the riser extension is unknown.

ANALYSIS: 38

WHAT WAS THE MALFUNCTION?

- 1. One each G11 failed to properly deploy.
- 2. One each G11 failed to completely inflate.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Latch sticking.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

- 1. Possible proper tightening on latch.
- 2. Incomplete information to make an exact determination.

	·					
I. 1. UNIT BEING AIRLIFTED	2. DEPARTURE		ENERAL 3. DA	TE 4.	TYPE ACFT	5. ACFT SER NO
					C-1	
6. OPERATION/EXERCISE	<u> </u>	7. DZ AND	LOCATION		8. DATE A	AND TIME
						_
9. ACFT ALTITUDE (Feet) $779\mathrm{AGL}$	10. ACFT SPEED (Knots) 145	11. DZ ELEVAT	ION (Feet) 13	2. surface winds (1 15 Knot)		13. VISIBILITY (Feet/Miles $5000/15$
TITIGE	173			13 141100		3000/13
111.			CARGO			
23. TYPE LOAD AND	24. RIGGED IAW (TM/TO/NA		·	·		
WEIGHT			25.	AERIAL DELI	VERY SYST	EM USED
Heavy equip-			DUAL RAIL	. CDS RELEAS		OTHER (Explain)
ment	FM 10-512/		NO. PLATFORMS	NO. CONTAI	NEKS	
3500 Lbs	TO 13C7-1-		1			
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		TRACTION/RE- PARACHUTE	29. LENGTH OF RE	EFING	30. POSITION OF LOAD IN AIRCRAFT
Type V	G-12E(2)	15-Foo	ot Ring Slot			1 of 2
	ALFUNCTION/FAILURI	T/DAMAGE	DICHEDED (16	·		`
32. CAUSE OF MALI	FUNCTION/FAILURE	(If more sp	pace is needed,	continue on rev	verse.)	

ANALYSIS: 44

WHAT WAS THE MALFUNCTION?

One parachute failed to inflate.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Insufficient information to make a determination.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Evaluate rigging procedures.

I.		GE	NERAL			
1. UNIT BEING AIRLIFTED	2. DEPARTUR	E AIRFIELD	3. DA	TE	4. TYPE ACFT	5. ACFT SER NO.
					C-17	
6. OPERATION/EXERCISE		7. DZ AND I	OCATION		8. DATE	AND TIME
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVATI	· '	. SURFACE WINI	• •	13. VISIBILITY (Feet/Miles,
1,500 AGL	145 KIAS	2,618	Feet	290 ժջ	g 8 mph	Unlimited
			7			
			CARGO			
23. TYPE LOAD AND	24. RIGGED IAW (TM/TO/			~		
WEIGHT			25.	AERIAL I	DELIVERY SYST	'EM USED
			DUAL RAIL	. CDS REL	EASE GATE	OTHER (Explain)
LVAD, Test Tub	FM 10-500-2)/	NO. PLATFORMS	NO. CON	ITAINERS	
3,240 Lbs	TO 13C7-1-5		1	,	2	
	10 13C/-1	28. SIZE EXT	1	29. LENGTH O	Z DEFENS	30. POSITION OF LOAD IN
26. TYPE PLATFORM/AIR- DROP CONTAINER	AND NUMBER		ARACHUTE	LINE	REEFING	AIRCRAFT
Tuno V	C 10E (2)	15 Eo	at Dingalat			1
Type V	G-12E(2)	13-60	ot Ringslot			<u> </u>
31. DESCRIPTION OF M	ALFUNCTION/FAILU	RE/ DAMAGE	NCURRED (if m	ore space is n	eeded, conti	nue on reverse.)
chute. The load d nated. Minor (nor		-	•		•	•
32. CAUSE OF MALE The locks, 17-18, the ADS LOCK O LOCK BACKUP heavy aircraft mai instead of just char	did not release. To ANG CONTR properties witch without a ntenance personate.	The loadmas panel witho release. Ma nel are going	ster activated ut a release. alfunction w	d the right He also a as called a	lock relectivated at that tim	the ADS GANG ne. NOTE: The
					-	
	CON	TINUED	ON NEXT	PAGE		

ANALYSIS: 40

WHAT WAS THE MALFUNCTION?

Submitted for tracking and review. Aircraft malfunction.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Not given.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Not given.

l.	···	GI	NERAL			
1. UNIT BEING AIRLIFTED	2. DEPARTURI	AIRFIELD	3. DA	ΓE	4. TYPE ACF	5. ACFT SER NO.
					C-17	
6. OPERATION/EXERCISE		7. DZ AND	LOCATION		8. DATE	AND TIME
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVATI	ON (Feet) 12	. SURFACE WII	ND\$ (Knots)	13. VISIBILITY (Feet/Miles)
1215 AGL	135 Knots	1175	MSL	8 kı	nots	Unlimited
			=			
111.	T		CARGO			
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/A	IAVAIR No.)	25.	AERIAL	DELIVERY SYS	TEM USED
						1
			NO. PLATFORMS		LEASE GATE	OTHER (Explain)
Training	FM 10-5		NO. PLATFORMS	NO. CO	NTAINERS	
3300 LBS	TO 13C7	7-1-5	2			Drogue
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		RACTION/RE- ARACHUTE	29. LENGTH (OF REEFING	30. POSITION OF LOAD IN
DROP CONTAINER	AND NUMBER	LEASE	AKACHUTE	LINE		AIRCRAFT
LVAD Type V				i		
8 Foot	G-12E(2)	15-Foo	ot Standard			FS 850
1. DESCRIPTION OF M	<u> </u>					<u>^</u>
32. CAUSE OF MAL Drogue parachute parachute and ha chute had not bee	e malfunctioned. T	This parach s. It was the	ute was conv e first drop a	verted from s a C-17	om a C-14	
					_	

WHAT WAS THE MALFUNCTION?

Drogue parachute failure.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Excessive stress due to multiple use.
- 2. Excessive air speed.
- 3. Drogue parachute not designed for use behind C-17. (Possibly not enough information to make a determination.)

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Enhanced drogue parachute designed for C-17 and modify parachutes according to modification guidelines before using in C-17.

			NERAL				
I. UNIT BEING AIRLIFTED	2. DEPARTURE	AIRFIELD	3. DA	TE	4. TYPE AC		5. ACFT SER NO.
					C-13		
6. OPERATION/EXERCISE		7. DZ AND	LOCATION		8. DAT	E AND TIME	
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVATI		2. SURFACE WIN	• •		BILITY (Feet/Miles
550 Feet AGL	137 Knots	1737	7 Feet	6 Kno	ots	U	nlimited
			7				
114.		· · · · · · · · · · · · · · · · · · ·	CARGO				
23. TYPE LOAD AND	24. RIGGED IAW (TM/TO/NA						
WEIGHT			25.	AERIAL	DELIVERY SY	STEM USED	
			X DUAL RAIL	. CDS RE	LEASE GATE	OTHER	(Explain)
Heavy Equipment	FM 10-512/	/	NO. PLATFORMS	NO. CO	NTAINERS	7	
2900 LBS	TO 13C7-1		1				
· · · · · · · · · · · · · · · · · · ·	10 13C/-1 27. TYPE PARACHUTE		L RACTION/RE-	20 (5007): 6	NE DEEE IN C	20.000	TION OF LOAD
26. TYPE PLATFORM/AIR- DROP CONTAINER	AND NUMBER	LEASE P	ARACHUTE	29. LENGTH C	OF REEFING		TION OF LOAD IN
		·					
T V	C 10F (0)	15 E	4 D.: C1 - 4			,	1 // 7
Type V	G-12E(2)	15-F00	t Ring Slot			Lo	ck # 5
31. DESCRIPTION OF M	ALFUNCTION/FAILUR	E/ DAMAGE	INCURRED (if n	nore space is	needed, con	tinue on re	everse.)
degree angle rende	ad landed on the a ering the EFTC un FUNCTION/FAILURE	serviceabl	e.				e at a 90
_	ormally and clearing	_	1 /				
* *	ne top of the platfor		•				
started, the paracl	hute D-bags and M	/11 release	were drug a	icross the	top rear	of the p	platform
until the M1 caug	ht against the edge	of a piece	e of plywood	l causing	damage	to the p	lywood.
The sudden tension	on on, and odd ang	gle of the N	/11, was suff	icient to	ause on	e of the	parachute
connnectors to sn	ap free of the M1.						
					_		
	CONT	TINUED	ON NEXT	PAGE			

WHAT WAS THE MALFUNCTION?

One of the fingers came out of the M1 parachute.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Latch sticking.
- 2. Fingers not seated properly.
- 3. M1 being drug/beat and banged on load due to load angle during extraction.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Suspect EFTC delayed transfer from extraction to deployment.

		·	GE	NERAL					
. UNIT BEING AIRLIFTED	2. DEPAR	RTURE AIRFIEL	.D	3. DA	TE	4. 1	YPE ACFT	r	5. ACFT SER N
	<u>}</u>			_			C-130)	
. OPERATION/EXERCISE		7.	DZ AND I	OCATION			8. DATE	AND TIME	
. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots) 11. DZ	Z ELEVATIO	ON (Feet)	. SURFACE W	INDS (K	nots)	13. VISI	BILITY (Feet/Mile
1200	140		1:	50	N	ΙA		1	NA
		1 .						ı	
						-			
II.	L 24 DISCEDIANI/THE	UTO/AL/AL/AID A		CARGO					
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM	I I OINAVAIR N	Vo.)	25.	AERIA	AL DELIN	ERY SYST	rem used)
					T			1	
Heavy Equip-				DUAL RAIL		RELEAS		OTHER	(Explain)
ment	FM 10-51	12/		NO. PLATFORMS	NO. C	ONTAIN	IEK)		
3750 LBS	TO 13C7	'-1-8		1					
26. TYPE PLATFORM/AIR-	27. TYPE PARACHUT	E 28.	SIZE EXT	RACTION/RE-	29. LENGTI	OF REE	FING		ITION OF LOAD
DROP CONTAINER	AND NUMBER		LEASE P	ARACHUTE	LINE			AiRC	RAFT
					ł				
Type V	G-12E _. (2	5)		15-Foot					FS 610
- 1) PC 1	0 121.(2			13 - 1.00t	L			<u></u>	
Four out of the labent or twisted p	ast five heavy e	equipme	nt trai	ning loads v	ve have o	dropp	oed ha	ve res	
Four out of the la	ast five heavy e	equipme	nt trai	ning loads v	ve have o	dropp	oed ha	ve res	
Four out of the la	ast five heavy e archute release	equipme e knife. F	nt trai Picture	ning loads v es will follov	ve have o	dropp parat	oed ha e e-ma	ve res ail.	
Four out of the labent or twisted p	ast five heavy e parchute release	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI te is striking the	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a seg	dropp parat	e e-ma	ve res	ulted in a
Four out of the labent or twisted p 32. CAUSE OF MAI The release knife	ast five heavy e parchute release LFUNCTION/FAI e is striking the m as it strikes t	equipment e knife. F	nt trai	ning loads ves will follow	ve have ov in a sej	dropp parat	e e-ma	ve res	ulted in a

ANALYSIS: 43

WHAT WAS THE MALFUNCTION?

- 1. Clustered G-12s.
- 2. AF bending knives.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Not Given.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Not Given.

. UNIT BEING AIRLIFTED									
. UNIT BEING AIRLIFTED			GE	NERAL					
	2. DEPAR	TURE All	RFIELD	3.	DATE		TYPE ACFI		5. ACFT SER N
i. OPERATION/EXERCISE	<u> </u>		7. DZ AND	LOCATION			C-17	AND TIME	
. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)) 1	1. DZ ELEVATI	ON (Feet)	12. SUR	FACE WINDS ((nots)	13. VISIE	BILITY (Feet/Mile
550 AGL	145 KCA	S	11	67		190m/6		6]	Miles
				7					
11.				CARGO					,
3. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM)	ITOINAV.	AIR No.)	25.		AERIAL DELI	VERY SYST	EM USED	
P Foot Training				DUAL RA		CDS RELEAS	E GATE	OTHER	(Explain)
8-Foot Training Type V	FM 10-	512/		NO. PLATFORM	ıs	NO. CONTAI	NERS	1	
2950 Lbs	TO 130	C 7-1-	8		l				HVY
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER			RACTION/RE- ARACHUTE		LENGTH OF RE	EFING	30. POSI AIRC	TION OF LOAD
Type V	G-12E (2)	`	1.5	Foot				1	of 1
1 ypc v 1. DESCRIPTION OF N		·	•	-Foot				I	
			_					. 1	T) 1
The drogue parac parachute was NO	hute was recov OT a prior extra	ered.	Evidenc parachu	e of equip ite. This di	ment ogue	failure w parachut	as dete		_
32. CAUSE OF MAI The drogue parac parachute was NO had been dropped	hute was recov OT a prior extra	ered.	Evidenc parachu	e of equip ite. This di	ment ogue	failure w parachut	as dete		_

WHAT WAS THE MALFUNCTION?

Drogue parachute failure.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Excessive stress due to multiple use.
- 2. Excessive air speed.
- 3. Drogue parachute not designed for use behind C-17. (Possibly not enough information to make a determination.)

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Enhanced drogue parachute designed for C-17 and modify parachutes according to modification guidelines before using in C-17.

							· · · · · · · · · · · · · · · · · · ·
l			NERAL				
1. UNIT BEING AIRLIFTED	2. DEPARTUR	E AIRFIELD	3. DA	TE	4. TYPE AC		5. ACFT SER NO.
6. OPERATION/EXERCISE	<u> </u>	7. DZ AND I	OCATION		C-17	AND TIME	<u> </u>
, OF ERATION/EXERCISE		7. DZ AND I	.CATION		6. UAT	AND HIME	
ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVATI	ON (Feet)	2. SURFACE WIND	S (Knots)	13. VISI	BILITY (Feet/Miles
1214 AGL	145	1163	AGL	290/	6		10 Miles
			7				
III.		(CARGO				
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/)	VAVAIR No.)	AERIAL D	ELIVERY SY	STEM USED	ı	
			DUAL RAIL	CDS RELI	EASE GATE	OTHER	(Explain)
			NO. PLATFORMS	NO. CON		-	(Explain)
Training Type V	FM 10-50					1	
3140 Lbs	TO 13C7-1	1-5	1			<u> </u>	
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER	28. SIZE EXT LEASE P	RACTION/RE- ARACHUTE	29. LENGTH OF LINE	29. LENGTH OF REEFING LINE		ITION OF LOAD IN RAFT
Type V	G-12E(2)	15	Foot			EC	903
Type v	U-12E (2)	1.3-1	1001	<u> </u>		Γb	903
32 CAUSE OF MAI	LFUNCTION/FAILUF	RE (If more s	nace is needed	continue on	reverse)	<u> </u>	
Drogue parachut were broken and	there were several of there were several his was the first of	on the DZ. T	The parachunels. The pa	te did oper	n. 10 of	18 sus	
				_	-		
			ON NEXT				

WHAT WAS THE MALFUNCTION?

Drogue parachute failure.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Excessive stress due to multiple use.
- 2. Excessive air speed.
- 3. Drogue parachute not designed for use behind C-17. (Possibly not enough information to make a determination.)

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Enhanced drogue parachute designed for C-17 and modify parachutes according to modification guidelines before using in C-17.

		GI	NERAL				
. UNIT BEING AIRLIFTED	2. DEPARTURE	AIRFIELD	3. DA	E	4. TYPE ACF	Т	5. ACFT SER NO
					C-17		
5. OPERATION/EXERCISE		7. DZ AND	LOCATION		8. DATE	AND TIME	
					1		
). ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVATI		. SURFACE WIF	NDS (Knots)	13. VISIB	BILITY (Feet/Mile
900 AGL	145 Knots	100	Feet	6 Kno	ots	Cl	lear
		•				*	
			CARCO				
II. 23. TYPE LOAD AND	24. RIGGED IAW (TMITOIN		CARGO I				
WEIGHT	24. RIGGED IAW (TMITTOIN	A V AIN INO.)	25.	AERIAL	DELIVERY SYS	TEM USED	
			DUAL RAIL	CDS BE	LEASE GATE	OTHER ((Explain)
23 Foot (M998/			NO. PLATFORMS		NTAINERS	۱۳۰۰۰۳٬	LAPIGINI
M119)	FM 10-519/						
20480 LBS	TO 13C7-10-3	31	2				CVR
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		RACTION/RE- ARACHUTE	29. LENGTH OF REEFING LINE		30. POSITION OF LOAD	
Ditor Contrained	7.115 115 11752.11						
	l						
Type V	G-11B (4)	28-Foo	ot Ring Slot			Α	Aft Load
1. DESCRIPTION OF M	AL EUNICTION/EAU UD	E/DAMACE	INCLIDED (:£	:			
parachute and line 32. CAUSE OF MALI At this time unabl inspected.		•			ŕ	is reco	vered and
					•		

ANALYSIS: 46

WHAT WAS THE MALFUNCTION?

INCIDENT.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Camera malfunction. Loadmaster could not see drogue so loadmaster cut drogue loose.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Make sure camera is working prior to drogue deployment.

2. DEPARTURE AI SPEED (Knots) 145 GED IAW (TMITOINAV M 10-512/ D 13C7-1-8 napter 11 PE PARACHUTE NUMBER G-12E (2) CTION/FAILURE/	7. DZ AND L 11. DZ ELEVATIO 1175 (AIR No.)	ON (Feet)	2. SURFACE WIN Cal AERIAL	DS (Knots) M DELIVERY SYS' LEASE GATE NTAINERS	13. VISIBI Clo	5. ACFT SER NO. LITY (FeetiMiles) Ear
SPEED (Knots) 145 145 M 10-512/ D 13C7-1-8 napter 11 PE PARACHUTE ND NUMBER G-12E (2)	7. DZ AND L 11. DZ ELEVATIC 1175 (AIR No.)	ON (Feet) 1 CARGO 25. DUAL RAIL NO. PLATFORMS 1 RACTION/RE- ARACHUTE	2. SURFACE WIN Cal AERIAL . CDS RE NO. COI	C-17 8. DATE DS (Knots) M DELIVERY SYS: LEASE GATE NTAINERS	13. VISIBI Clo	LITY (FeetiMiles) Car
145 M 10-512/ D 13C7-1-8 napter 11 PE PARACHUTE NUMBER G-12E (2)	11. DZ ELEVATIO 1175 (AIR No.)	CARGO 25. DUAL RAIL NO. PLATFORMS 1 RACTION/RE- ARACHUTE	AERIAL . CDS RE NO. COI	DS (Knots) M DELIVERY SYS' LEASE GATE NTAINERS	13. VISIBI Clo	ear
145 M 10-512/ D 13C7-1-8 napter 11 PE PARACHUTE NUMBER G-12E (2)	11. DZ ELEVATIO 1175 (AIR No.)	CARGO 25. DUAL RAIL NO. PLATFORMS 1 RACTION/RE- ARACHUTE	AERIAL . CDS RE NO. COI	DS (Knots) M DELIVERY SYS' LEASE GATE NTAINERS	13. VISIBI Clo	ear
145 M 10-512/ D 13C7-1-8 napter 11 PE PARACHUTE NUMBER G-12E (2)	28. SIZE EXTILEASE P.	DUAL RAIL NO. PLATFORMS 1 RACTION/RE- ARACHUTE	AERIAL . CDS RE NO. COI	M DELIVERY SYS' LEASE GATE NTAINERS	Cle	ear
145 M 10-512/ D 13C7-1-8 napter 11 PE PARACHUTE NUMBER G-12E (2)	28. SIZE EXTILEASE P.	DUAL RAIL NO. PLATFORMS 1 RACTION/RE- ARACHUTE	AERIAL . CDS RE NO. COI	M DELIVERY SYS' LEASE GATE NTAINERS	Cle	ear
M 10-512/ D 13C7-1-8 napter 11 PEPARACHUTE ND NUMBER G-12E (2)	28. SIZE EXTILEASE P.	DUAL RAIL NO. PLATFORMS 1 RACTION/RE- ARACHUTE	AERIAL . CDS RE NO. COI	DELIVERY SYS LEASE GATE NTAINERS	TEM USED OTHER (E	
M 10-512/ D 13C7-1-8 napter 11 PE PARACHUTE ND NUMBER G-12E (2)	28. SIZE EXTI LEASE P.	DUAL RAIL NO. PLATFORMS 1 RACTION/RE- ARACHUTE	. CDS RE NO. COI	LEASE GATE	OTHER (E	explain)
M 10-512/ D 13C7-1-8 napter 11 PE PARACHUTE ND NUMBER G-12E (2)	28. SIZE EXTI LEASE P.	DUAL RAIL NO. PLATFORMS 1 RACTION/RE- ARACHUTE	. CDS RE NO. COI	LEASE GATE	OTHER (E	Explain)
M 10-512/ D 13C7-1-8 napter 11 PE PARACHUTE ND NUMBER G-12E (2)	28. SIZE EXTI LEASE P.	DUAL RAIL NO. PLATFORMS 1 RACTION/RE- ARACHUTE	. CDS RE NO. COI	LEASE GATE	OTHER (E	ixplain)
D 13C7-1-8 napter 11 PE PARACHUTE ND NUMBER G-12E (2)	LEASE PA	DUAL RAIL NO. PLATFORMS 1 RACTION/RE- ARACHUTE	. CDS RE NO. COI	LEASE GATE	OTHER (E	ixplain)
D 13C7-1-8 napter 11 PE PARACHUTE ND NUMBER G-12E (2)	LEASE PA	NO. PLATFORMS 1 RACTION/RE- ARACHUTE	NO. CO	NTAINERS		Explain)
napter 11 pe parachute nd number G-12E (2)	LEASE PA	1 RACTION/RE- ARACHUTE	29. LENGTH O		30. POSIT	
PE PARACHUTE ND NUMBER G-12E (2)	LEASE PA	ARACHUTE		F REEFING	30. POSIT	
G-12E (2)	LEASE PA	ARACHUTE		F REEFING	30. POSIT	
G-12E (2)	15-				AIRCR.	ION OF LOAD IN
		·Foot	i			
		-Foot				
CTION/FAILURE/				FS 1030		
followers or A pace/gap was ll gap visible a	ADS link s visible. T	sensors. Dur This was che nalfunction.	ring the JA ecked aga . Regardin	AI, the car in prior to g the AD	o the pro S link s	e-slow ensors, the
rop logic sequ ds prior to dro	ience dro p. It appe	pped out 3- eared to rem	4 times. T nain throug	the last tingh out the	me it dr e rest of	opped ou
r	was visibly of op logic sequence of the logi	was visibly damaged, op logic sequence dro ls prior to drop. It appe	was visibly damaged, but checked to logic sequence dropped out 3-ds prior to drop. It appeared to rem	was visibly damaged, but checked good dur top logic sequence dropped out 3-4 times. This prior to drop. It appeared to remain through	was visibly damaged, but checked good during the property logic sequence dropped out 3-4 times. The last times are prior to drop. It appeared to remain through out the	was visibly damaged, but checked good during the preflight op logic sequence dropped out 3-4 times. The last time it dr is prior to drop. It appeared to remain through out the rest of round the TRM showed signs of a lot of dirt build up.

ANALYSIS: 47
WHAT WAS THE MALFUNCTION?
TRM anneiator failed to release.
WHAT COLUDINATE CALICED THIC TO HADDENO
WHAT COULD HAVE CAUSED THIS TO HAPPEN?
Equipment failure.
WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?
Equipment function checks.

										_
			GI	NERAL						_
I. UNIT BEING AIRLIFTED	2.	DEPARTURE A	IRFIELD		3. DAT	E	4. TYPE A	CFT	5. ACFT SER N	Ю.
	ŗ						C-			
6. OPERATION/EXERCISE			7. DZ AND	LOCATION			8. DA	TE AND TIN	A E	
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED	· · · · · · · · · · · · · · · · · · ·	11. DZ ELEVATI	ON (Feet)	12	. SURFACE W	INDS (Knots)	13. VI	SIBILITY (Feet/Mi	les)
800	130 Knc	nots 360 Feet				0-5	Knots	2	Miles	
				7_						_
N.				CARGO						=
23. TYPE LOAD AND	24. RIGGED IA	D IAW (TMITOINAVAIR No.)								
WEIGHT				25.		AERIA	L DELIVERY S	YSTEM USI	D	
32-Foot Gun/					RAIL	. CDS RELEASE GATE		ОТНЕ	R (Explain)	
HMMWV	FM 10	0-519/		NO. PLATFO	ORMS	NO. C	NO. CONTAINERS		1	
21,000 LBS		3-31 <i>)</i> / 3C7-10-:	· ·						LVAD	
21,000 LDS	27. TYPE PARA			I RACTION/RE-		29. LENGTH OF REEFING		20.00	LVAD SITION OF LOAD	181
DROP CONTAINER	AND NUM		LEASE P	ARACHUTE		LINE	OF REEFING		RCRAFT	IN
			15 E.							
T V	C 11	D (4)		oot and					1 of 1	
Type V	G-II	B _. (4)	22-F	oot					1 01 1	
32. CAUSE OF MAL			_						th no evi-	
dence of a malfund	ction.									
						_				_
		CONT	INUED	ON NE	XT	PAGE				

ANALYSIS: 48

WHAT WAS THE MALFUNCTION?

INCIDENT.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Camera malfunction. Loadmaster could not see drogue so loadmaster cut drogue loose.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Make sure camera is working prior to drogue deployment.

<u>. </u>					ΝĒ	RAL								
1. UNIT BEING AIRLIFTED		2. DEPARTURE	AIR	FIELD		I	3. D.	ATE		j	4. 1	TYPE ACFT		5. ACFT SER NO
				•						L	_	C-13		<u></u>
6. OPERATION/EXERCISE				7. DZ AND I	.00.	ATION					ı	8. DATE A	ND TIME	
		r	_										,	
9. ACFT ALTITUDE (Feet)	10. ACFT SP	11	11. DZ ELEVATION (Feet) 450 Feet			ŀ	12. SURFACE WINDS (Knots)					13. VISIBILITY (Feet/Mi		
5000 Feet AGL	0 Feet AGL 140 Knots					t		3-5 Knots					Unlimited	
				10.0	Z	7			_					
111.				(CAF	RGO								
23. TYPE LOAD AND	24. RIGGE	DIAW (TM/TO/N	ÄVA	AIR No.)										
WEIGHT	i				25). T				AERIAL DE	LIV	ERY SYST	FW O2FF)
				I.		DUAL	RAIL			CDS RELE	ASI	E GATE	OTHER (Explain)	
Weight Tub	FN	1 10-500-	2/		NC). PLATFO	RMS			NO. CONT	AIN	IERS		
15,000 LBS	4) 13C7-1				1		l						
26. TYPE PLATFORM/AIR-	27. TYPE F	ARACHUTE	Ť	28. SIZE EXT						29. LENGTH OF REEFING			30. POSITION OF LOA	
DROP CONTAINER	AND	NUMBER		LEASE P	ARA	LACHUTE			L	INE			AiR	CRAFT
	94-F	oot Test	ı	•				1						
Type V, 16 Foot	(3 ea			22-Foot		Ring S	Slot	t I					Mid	
31. DESCRIPTION OF M			17.7	DAMAGE	NIC	unnei						. 1		
The load rigged (IA performed before ar The aircraft flew an parachute opened fur from extraction to discussed the platform in the negative directload to the ground. In malfunction. Damage by the load shifting clevis and frayed at damaged from the load. 32. CAUSE OF MAL	nd after lo ormal LV illy and the eployment to rotate ection alm Although ge: Was u on landing the lower oad shifti	pading. EFT AD flight properties actuator and did not one in the opposit 180 degratest parachanable to doing. One ply resuspensioning on landing.	roffarn arm ecu osit rec at on n li ng.	functiona ile to the connection of the Eur for approxed directions. The threshold not function colleft front nk, the front function of the fun	l cl dro FT rox on. ree pe che sli ont	p zone C rota imatel The fr e 94 fo erform eck afte ng bro t left p	wer Lotted y on toont oot to exa er d ke a latte	e per pond e upo ne se edg est pactly rop, apprrorm	rf ex e e e a p d d	cormed a attraction clearing cond. The of the prachutes perfect it lue to the ximately amaged	w g the collate th	I function as normal her ramp delay in the term of the	oned a nal, exton Force force ropped and to the om surator br	as designed. traction ce transfer transfer d and rotated recovered th ce with the cable cause spension racket was
	The EFT	C system w	as	sent to Na	atic	ck for f	urtl	her a	ın	alysis. (17 :	deo ava	. 11.1.1.	.)
The latch assembly.	·										V 1	deo ave	anabie	·)
											V I	uco ava	aliable	

CONTINUED ON NEXT PAGE

WHAT WAS THE MALFUNCTION?

Not Given.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Possible bolts too tight on 3-point link assembly.
- 2. Possible damage to cable.
- 3. Possible failure of EFTC to transfer.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Not given.

1.		GI	ENERAL					
1. UNIT BEING AIRLIFTED	2. DEPARTURE	AIRFIELD	3.	. DATE		4. TYPE ACFT	Т	5. ACFT SER NO.
			1			C-17		
6. OPERATION/EXERCISE		7. DZ AND	LOCATION			8. DATE	AND TIME	
						į		
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVATI	ION (Feet)	ION (Feet) 12. SURFACE W			13. VISII	BILITY (Feet/Miles)
1300 AGL	145	11	175	Calm			Clear	
				_				
111.			CARGO					
	T		T	—				
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TMITOIN	AVAIR No.)	25.		AERIAL [DELIVERY SYST	TEM USED	J
Hoove Equip	FM 10-512/		DUAL RA	AIL	. CDS REL	EASE GATE	OTHER	(Explain)
Heavy Equip-			NO. PLATFOR			TAINERS	d	
ment/Type V	TO 13C7-1-	8						
3000 LBS	Chapter 11		1					
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		TRACTION/RE- PARACHUTE	25	9. LENGTH OI	REEFING		ITION OF LOAD IN
					_			
				i				
Type V	G-12E(2)	15-Foc	ot Ring Slo	ot L				FS 1030

31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.)

At release point, the drogue parachute was deployed by the co-pilot and was okay. Two seconds prior to green light, the tow release (TRM) armed annunciator at the forward loadmaster panel extinguished, causing the loss of airdrop logic. According to published procedures, the loadmaster then jettisoned the drogue parachute without any problems.

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

The aircraft lost airdrop logic three times between the slowdown checklist and approximately 1 1/2 minutes from green light. Suspect the cam lock followers or the ADS link sensors as the cause for loss of airdrop logic. During the JAI, the cam lock followers were adjusted to ensure that they were flush against the body of the link. They checked fine during flight prior to the pre-slowdown checklist. The cam lock followers were checked again after the drogue parachute was jettisoned and there was a small gap visible between the cam lock followers and the link. Prior to flight it was noticed that the right ADS link sensor had visible damage. It checked good during the pre-flight.



CONTINUED ON NEXT PAGE

WHAT WAS THE MALFUNCTION?

TRM extinguished.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Equipment failure.

$\underline{\textbf{WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?}}$

Equipment function check.

				·			_
1.	.		NERAL				
1. UNIT BEING AIRLIFTED	2. DEPARTURE A	RFIELD	3. D	ATE	4. TYPE ACF1		0.
6. OPERATION/EXERCISE	<u> </u>	7. DZ AND	LOCATION			AND TIME	
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVATI	ON (Feet)	12. SURFACE WIND	S (Knots)	13. VISIBILITY (Feet/Mile	es)
650 AGL	140	59	0	Calı	n	7 Miles	
			7_				
111.			CARGO				
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/NAV	/AIR No.)	25.	AERIAL D	ELIVERY SYST	TEM USED	
1			X DUAL RAIL	1 1	ASE GATE	1	
III) () GG	EN 10 510/		NO. PLATFORMS			OTHER (Explain)	
HE MASS	FM 10-518/		1				
2659 LBS	TO 13C7-1-8		ACTION/RE-	29. LENGTH OF	DEEEING	30. POSITION OF LOAD II	N
DROP CONTAINER	AND NUMBER	LEASE P	ARACHUTE	LINE	REEFING	AIRCRAFT	N
		•					
Type V	G-12E(2)	15-Foo	ot Ring Slot	:		Lock #9	
21 DESCRIPTION OF M	ALFUNCTION/FAILURE	<u> </u>		•	adad santi		_
	ly. No damage incu		pace is needed	, continue on	reverse.)		
	CONT	INUED	ON NEXT	T PAGE	-		
	CONT	INUED	ON NEXT	Γ PAGE			

ANALYSIS: 51

WHAT WAS THE MALFUNCTION?

Not given.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Improper packing procedures.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Not given.

1.		G	ENERAL					
1. UNIT BEING AIRLIFTED	2. DEPARTUR	LE AIRFIELD	3	3. DATE	E	4. TYPE ACFT	Γ	5. ACFT SER NO.
						MC-13	30H	
6. OPERATION/EXERCISE		7. DZ AND	LOCATION			8. DATE	AND TIME	
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVAT	/ION (Feet)	12.	. SURFACE WIND	S (Knots)	13. VISI	BILITY (Feet/Miles)
673	140 Knots	12:	.3	Ì	Caln	1]	>7 Miles
			<u> </u>					
				==				
111.			CARGO					
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/	NAVAIR No.)	25.		AFRIAL C	ELIVERY SYST	TEM USED	<u> </u>
	FM 10-50	00-2/			F		T	
	TO 13C7-		X DUAL RA	AIL	. CDS REL	EASE GATE	OTHER	(Explain)
Heavy equipment	. [NO. PLATFOR	(MS	NO. CON	TAINERS]	
3200 lbs	1 10-31		! ,	ı				
3200 IUS	TO 13C7-	<u>-1-8</u>	1				1	
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		TRACTION/RE- PARACHUTE		29. LENGTH OF LINE	REEFING		ITION OF LOAD IN
				- 1				
Type V	G 12F (2)	1	5-Foot				EC	637

During a heavy equipment drop, during the extraction phase, the 15-foot parachute fully elongated after departing the aircraft, however, it cigar-rolled. After several seconds an emergency was called. As loadmasters were proceeding aft to chain the platform, the parachute opened and extractaed the heavy equipment. No problems with the deployment phase of the airdrop were identified.

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

After inspecting the 15-foot extraction parachute, the following was found. On the deployment bag right stowage flap there is a rip in the nylon 1 by 1/2 inch about the size of the connector link assembly (L bar) and a 1/2 inch by 1/2 inch hole right beside it. On the left flap the nylon has been scratched (possibly by the face of the L bar screw) and one suspension line was broken. A possible cause of this malfunction is that when the extraction parachute stopped in the airstream during normal extraction the L bar got caught in the right flap causing excessive stress on the suspension lines when the flap ripped releasing the L bar it caused a possible line dump. The parachute was packed on 14 May 01 and appeared in good shape other than the items mentioned above.



ANALYSIS: 52

WHAT WAS THE MALFUNCTION?

Not Given.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Rigger error.
- 2. Did not follow proper packing procedures.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Not given.

1. 1. UNIT BEING AIRLIFTED 6. OPERATION/EXERCISE 9. ACFT ALTITUDE (Feet) 600 Feet	2. DEPARTURE A D. ACFT SPEED (Knots) 130 Knots	7. DZ AND I		TE 4.	TYPE ACFT C-13(8. DATE A	
6. OPERATION/EXERCISE 9. ACFT ALTITUDE (Feet) 10	D. ACFT SPEED (Knots)	7. DZ AND	LOCATION	4.	C-130	0
9. ACFT ALTITUDE (Feet) 10		11. DZ ELEVATI				
9. ACFT ALTITUDE (Feet) 10		11. DZ ELEVATI				
			ON (Feet)			
600 Feet	130 Knots	335		2. SURFACE WINDS (Knots)	13. VISIBILITY (Feet/Mile
			Feet	16 Knc	ots	Unlimited
			<u> </u>			
III.			CARGO			
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/NA	VAIR No.)	25.	AERIAL DELI	VERY SYSTE	EM USED
			DUAL RAIL	. CDS RELEAS	··· Y	OTHER (Explain)
CD C		- /	NO. PLATFORMS	NO. CONTAI		OTHER (Explain)
CDS	FM 10-500-					
1855 LBS	TO 13C7-1			14		CVR
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		RACTION/RE- ARACHUTE	29. LENGTH OF RE LINE	EFING	30. POSITION OF LOAD II AIRCRAFT
Low-V		·		}		
A-22	G-12E	68-Ir	nch Pilot			1st Load/Let
31. DESCRIPTION OF MAI		-				
adapter webs were 32. CAUSE OF MALF					everse)	
52. CAUSE OF MALF	ONCTION/FAILURI	(11 more 8)	pace is necueu	, continue on I	. , (1 35.)	
Multiple loads mak	ting contact with	each other	•			
1						
	CONT	INUED	ON NEXT	PAGE		

WHAT WAS THE MALFUNCTION?

Load separation.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Load contact in air.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Not given.

6. OPERATION/EXERCISE 7. DZ AND LOCATION 8. DATE AND TIME 9. ACFT ALTITUDE (Feet) 250 Feet AGL 240 Knots 250 Feet AGL 240 Knots 250 Feet Calm 7 Miles CARGO 23. TYPE LOAD AND WEIGHT Modified A-21/ HSLLADS 380 LBS FM 10-542/ 380 LBS TO 13C7-51-21 28. SIZE EXTRACTION/RE- DROP CONTAINER Modified A-21 AGRICAL CDS RELEASE GATE OTHER (Explain) High Veloci 28. SIZE EXTRACTION/RE- LEASE PARACHUTE Modified A-21 AGRICAL CDS RELEASE GATE OTHER (Explain) High Veloci 29. LENGTH OF REEFING AGRICAL COLOR 30. POSITION OF LOAD AIRCRAFT MODIFIED AIRCRAFT AGRICAL COLOR AGRICAL							
8. ACET ALTITUDE (Feet) 2.40 Knots 2.550 Feet AGL 2.40 Knots 2.5550 Feet Calm 7 Miles CARGO 23. TYPE LOAD AND WEIGHT Modified A-21/ HSLLADS 380 LBS TO 13C7-51-21 NO. PLATFORM AIR DOWN MEIGHT Modified A-21 22-Foot Roing Slot (1) Container Ring Slot (1) Aft edge FS 7 After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)			GI	ENERAL			
8. DATE AND TIME 9. ACET ALTITUDE (Feet) 250 Feet AGL 240 Knots 250 Feet AGL 240 Knots 250 Feet 250 Feet 250 Feet 250 Feet 260 Thill Substitute (Feet) 7 Miles 260 Feet AGL 261 Feet AGL 262 Feet AGL 263 Feet AGL 263 Feet AGL 264 RIGGED IAW (TM/TO/NAVAIR No.) 265 AERIAL DELIVERY SYSTEM USED 265 DUAL RAIL COS RELEASE GATE OTHER (Explain) 266 High Velocit Container 267 TO 13C7-51-21 267 FEET IND. PLATFORMS 268 FEARACHUTE CHASE PARACHUTE LEASE PA	1. UNIT BEING AIRLIFTED	2. DEPARTURE A	RFIELD	3. D	ATE		
9. ACFT ALTITUDE (Feet) 250 Feet AGL 240 Knots 250 Feet 240 Knots 25550 Feet 250 Feet 240 Knots 25550 Feet 250 Feet 250 Feet AGL 260 To Miles 7 Miles CARGO 25. AERIAL DELIVERY SYSTEM USED Modified A-21/ HSLLADS 380 LBS						C-130	
250 Feet AGL 240 Knots 5550 Feet Calm 7 Miles CARGO 23. TYPE LOAD AND WEIGHT Modified A-21/ HSLLADS TO 13C7-51-21 AGRICATION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)	6. OPERATION/EXERCISE		7. DZ AND	LOCATION		8. DATE	AND TIME
MI. CARGO WEIGHT Modified A-21/ HSLLADS TO 13C7-51-21 TO 13C7-51-21 AGRICATION/REI Modified A-21 EASSUE EXTRACTION/REI LEASE PARACHUTE Modified A-21 Aft edge FS 7 B1. DESCRIPTION OF MALFUNCTION/FAILURE / DAMAGE INCURRED (if more space is needed, continue on reverse.) After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)			1			İ	
MOdified A-21/ HSLLADS FM 10-542/ BNO. PLATFORMS NO. CONTAINERS TO 13CT-51-21 22-E-Type PLATFORM.AIR ROLD PRACECUTE LEASE PARACHUTE LOCA	9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVATI	ION (Feet)	12. SURFACE W	INDS (Knots)	13. VISIBILITY (Feet/Mile
Modified A-21/ HSLLADS FM 10-542/ BOUAL RAIL TO 13C7-51-21 TO 13C7-51-21 AFRIAL DELIVERY SYSTEM USED DUAL RAIL CDS RELEASE GATE NO. PLATFORMS NO. CONTAINERS TO 13C7-51-21 High Velocity 22. Type Platform.air. DROP CONTAINER 27. Type Platform.air. PROP CONTAINER AND NUMBER 27. Type Platform.air. CDS RELEASE GATE NO. PLATFORMS NO. CONTAINERS High Velocity 1. High Velocity Aft edge FS 7 Aft edge FS 7 BI. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)	250 Feet AGL	240 Knots	5550	Feet	Cal	m	7 Miles
Modified A-21/ HSLLADS FM 10-542/ TO 13C7-51-21 21. Type parachute Drop Container Modified A-21 Modified A-21 Experimental Proposition of Load And Number Proposition of Load And Received agriculture and an anomal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 24. RIGGED IAW (FM/TO/NAVAIR No.) 25. AERIAL DELIVERY SYSTEM USED DUAL RAIL CDS RELEASE GATE OTHER (Explain) High Veloci 26. SIZE EXTRACTION/RE LEASE PARACHUTE 27. LENGTH OF REEFING Aft edge FS 7 After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)				7			
Modified A-21/ HSLLADS FM 10-542/ TO 13C7-51-21 21. Type parachute Drop Container Modified A-21 Modified A-21 Experimental Proposition of Load And Number Proposition of Load And Received agriculture and an anomal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 24. RIGGED IAW (FM/TO/NAVAIR No.) 25. AERIAL DELIVERY SYSTEM USED DUAL RAIL CDS RELEASE GATE OTHER (Explain) High Veloci 26. SIZE EXTRACTION/RE LEASE PARACHUTE 27. LENGTH OF REEFING Aft edge FS 7 After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)				CARGO			
Modified A-21/ HSLLADS SOLBS TO 13C7-51-21 26. Type platformiair. Drop platformiair. Drop process and modified A-21 (Lease parachute process) Modified A-21 (22-Foot Ring Slot (1)) 31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)	· · · · · · · · · · · · · · · · · · ·	24 RIGGED IAW (TMITOINA)		LARGO			
HSLLADS TO 13C7-51-21 1 High Velocity of Platform. Air. 27. Type Parachute and Number 28. Size extraction. Release parachute 29. Length of Reefing 30. Position of Load Aircraft 22-Foot Aft edge FS 7 B1. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)		24. RIGGED IAW (TMITOTION	Ain 180.)	25.	AERIA	L DELIVERY SYS	TEM USED
HSLLADS TO 13C7-51-21 1 High Velocity of Platform. Air. 27. Type Parachute and Number 28. Size extraction. Release parachute 29. Length of Reefing 30. Position of Load Aircraft 22-Foot Aft edge FS 7 B1. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)	> 6 1 1 C 1 4 C 1 /			DILAL PAU	cns	DELEASE GATE	OTHER (Evoluin)
HSLLADS 380 LBS TO 13C7-51-21 1 High Veloci 26. TYPE PLATFORMAIR 27. TYPE PARACHUTE AND NUMBER 28. SIZE EXTRACTION/RE-LEASE PARACHUTE 29. LENGTH OF REEFING ARCRAFT 30. POSITION OF LOAD ARCRAFT 41 High Veloci 28. SIZE EXTRACTION/RE 29. LENGTH OF REEFING 30. POSITION OF LOAD ARCRAFT ARCRAFT 30. POSITION OF LOAD ARCRAFT ARCRAFT 30. POSITION OF LOAD ARCRAFT 41 High Veloci 30. POSITION OF LOAD ARCRAFT 428. SIZE EXTRACTION/RE LEASE PARACHUTE 29. LENGTH OF REEFING 30. POSITION OF LOAD ARCRAFT ARCRAFT 428. SIZE EXTRACTION/RE LEASE PARACHUTE 29. LENGTH OF REEFING 30. POSITION OF LOAD ARCRAFT 428. SIZE EXTRACTION/RE LEASE PARACHUTE 29. LENGTH OF REEFING 30. POSITION OF LOAD ARCRAFT 428. SIZE EXTRACTION/RE LEASE PARACHUTE 29. LENGTH OF REEFING 30. POSITION OF LOAD ARCRAFT 428. SIZE EXTRACTION/RE LEASE PARACHUTE 29. LENGTH OF REEFING 30. POSITION OF LOAD ARCRAFT 428. SIZE EXTRACTION/RE 10 LEASE PARACHUTE 29. LENGTH OF REEFING 30. POSITION AFT CALLED 30. POSITION OF LOAD ARCRAFT 429. LENGTH OF REEFING 30. POSITION AFT CALLED 30. POSITION AFT							OTHER (Explain)
26. TYPE PLATFORM.AIR. 27. TYPE PARACHUTE 28. SIZE EXTRACTION.RE. LEASE PARACHUTE 29. LENGTH OF REEFING 30. POSITION OF LOAD AIRCRAFT AND NUMBER 22. Foot Ring Slot (1) 31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)						011771112113	
Modified A-21 22-Foot Container Ring Slot (1) Aft edge FS 7 31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)	380 LBS	TO 13C7-51-	21			1	High Velocit
Modified A-21 Container Ring Slot (1) Aft edge FS 7 31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)		27. TYPE PARACHUTE	28. SIZE EXT	RACTION/RE-		OF REEFING	30. POSITION OF LOAD I
Aft edge FS 7 31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)							
After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)	Modified A-21	22-Foot			Ì		
After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)	Container	Ring Slot (1)					Aft edge FS 72
After the high speed, low level aerial delivery system (HSLLADS) exited the aircraft and the parchute deployed in a normal manner, the opening shock and pressure exerted on the A-21 container caused the horizontal webbing to snap. This seems to have put undue stress on the skidboard ties, having them break and allowing the load to slide from the remaining A-21 straps. The load then free-fell to the ground while the parachute, now separated from the load, drifted away from the load. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)	1 DESCRIPTION OF M	A L EUNICTION/E A IL LIDE	/DAMACE	INCHIDDED (:£			·
	straps. The load the load, drifted away	hen free-fell to the g y from the load.	ground w	while the par	cachute, n	ow separa	ted from the

WHAT WAS THE MALFUNCTION?

Material failure.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Weak material (worn material) could not withstand the opening shock.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

- 1. Properly rigged, material inspected and replaced when worn.
- 2. Submit QDR for material.

1.		GE	NERAL					
1. UNIT BEING AIRLIFTED	2. DEPARTURE	AIRFIELD	3.	DATE	4.	TYPE ACFT		5. ACFT SER NO.
	ŀ					C-13	30	
6. OPERATION/EXERCISE	-	7. DZ AND	LOCATION			8. DATE	AND TIME	
			,					
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVATI	ON (Feet)	12. SUR	FACE WINDS (#	(nots)	13. VISI	BILITY (Feet/Miles)
400 AGL	130 Knots	0 Knots 580 I			8 Knots	S	1	0+ Miles
			7_					
111.			CARGO					
23. TYPE LOAD AND	24. RIGGED IAW (TM/TO/NA	VAIR No.)	35		458(4) B5(4)	45BV 6V6T		
WEIGHT			25.		AERIAL DELI	AEKA 2A21	EW OZED	
İ	FM 10-500-3	3/	DUAL RAI	L .	CDS RELEASE GATE		OTHER	(Explain)
CDS	TO 13C7-1-	11	NO. PLATFORM	ıs	NO. CONTAIL	NERS		
778 LBS	Chapter 9				1			CVR
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER				LENGTH OF REE	FING		ITION OF LOAD IN RAFT
		68-In	68-Inch Pilot					
A-22	G-12E(1)	Parac	hute					FS 613

31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.)

Load exited aircraft normally. It appeared the G-12E deployment bag was slow to pull off the parachute. As the load descended the G-12E extended but never opened. Upon inspection of the G-12E parachute on the ground, the following items were noted:

- 1. Parachute canopy was free of any damage or other problems.
- 2. Parachute skirt was not damaged or showed any other problems.
- 3. Second Ticket 3 suspension line tie from the clevis was unbroken.
- 4. Six suspension lines were burnt together approximately 3/4 of the way up from the clevis.
- 5. No burns or abnormalities were noted on the G-12E deployment bag.
- 6. No other abnormalities were found.

Inspection of the aircraft immediately after the drop found that the aircraft systems functioned normally and no discrepancies were noted.

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Unknown.

CONTINUED ON NEXT PAGE

WHAT WAS THE MALFUNCTION?

Parachute failed to deploy.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Packing procedures for 68-inch pilot parachute.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

- 1. Follow appropriate packing procedures in TM.
- 2. Specify if the G-12 deployment bag was a new G-12E bag or an old G-12D bag.

							_
ł.		G	ENERAL				
1. UNIT BEING AIRLIFTED	2. DEPARTURE	AIRFIELD	3. DA	TE	4. TYPE ACF	5. ACFT SER I	NO.
					C-13		
6. OPERATION/EXERCISE		7. DZ AND	LOCATION		8. DATE	AND TIME	
					1		
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVAT	ION (Feet)	2. SURFACE WIN	D\$ (Knots)	13. VISIBILITY (Feet/Mi	les)
570	130 KIAS	1	040	Ca	alm	10+	
3.70						10	
							=
111.	T		CARGO				
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/N	AVAIR No.)	25.	AERIAL I	DELIVERY SYS	TEM USED	
				1 1		1	
			DUAL RAIL	 	EASE GATE	OTHER (Explain)	
CDS	FM 10-50	0-3/	NO. PLATFORMS	NO. CON	ITAINERS		
700 LBS	TO 13C7-	1-11	i	1		High Velocity	Į
26. TYPE PLATFORM/AIR-	27. TYPE PARACHUTE	28. SIZE EX	TRACTION/RE-	29. LENGTH O	REEFING	30. POSITION OF LOAD	IN
DROP CONTAINER	AND NUMBER	LEASE	PARACHUTE	LINE		AIRCRAFT	
		1					
A-22	26-Foot HV (1					FS 530	
11 22	201000111 (7	· · · · · · · · · · · · · · · · · · ·			10 330	
did not cut occau	se the Type-1 80 ll	————					
The airdrop malforpanel determined	LEUNCTION/FAILUR unction review par I that the western g ras due to the time	nel determ ear static l	ined that the ine retriever	release ga did not fur	te was pr action pr	operly. The	Γhe
							1
	CON	ΓINUED	ON NEXT	PAGE			

ANALYSIS: 56

WHAT WAS THE MALFUNCTION?

Release gate did not cut.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Western gear failure.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Replace western gear.

1. UNIT BEING AIRLIFTED 2. DEPARTURE AIRTHELD 2. DEPARTURE AIRTHELD 3. DATE NA 6. OPERATIONEXERCISE 7. DZ AND LOCATION 8. DATE AND TIME 8. DATE AND TIME 9. ACFT ALTITUDE (Feet) 10. ACFT SPEED (Knots) 11. DZ ELEVATION (Feet) 800 AGL 130 Knots 328 ASL 0-5 Knots 13. VISIBILITY (Feet/Mine) 13. VISIBILITY (Feet/Mine) 13. VISIBILITY (Feet/Mine) 14. VISIBILITY (Feet/Mine) 15. AERIAL DELIVERY SYSTEM USED 16. DUAL RAIL 17. DUAL RAIL 18. COS RELEASE GATE 19. OPHATIORMS 19. O										
ACFT ALTITUDE (Feet) 10. ACFT SPEED (Knots) 130 Knots 11. DZ ELEVATION (Feet) 12. SURFACE WINDS (Knots) 13. VISIBILITY (Feet)Miles 800 AGL 130 Knots 1328 ASL 0-5 Knots 13. VISIBILITY (Feet)Miles WEIGHT 81mm Mortar System FM 10-500-3/ TO 13C7-1-11 1000 FUNDATIONALER 20. TYPE PARTICHMANIAR 21. TYPE PARTICHMANIAR 22. TYPE PARTICHMANIAR 23. TYPE PARTICHMANIAR 23. TYPE PARTICHMANIAR 24. TYPE PARTICHMANIAR 25. TYPE PARTICHMANIAR 26. SIZE EXTRACTIONIRE 18. SIZE EXTRACTIONIRE 19. LENGTH OF REEFING 30. POSITION OF LOAD IN ARCRAFT 31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunction, if it was caused during the malfunction, or caused during recovery. We believe the following happene When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and				GE	NERAL					
8. DATE AND TIME 9. ACET ALTITUDE (Feet) 10. ACET SPEED (Rnots) 11. DZ ELEVATION (Feet) 12. SURFACE WINDS (Rnots) 13. VISIBILITY (Feet/Miles) 13. VISIBILITY (Feet/Miles) 14. VISIBILITY (Feet/Miles) 15. AERIAL DELIVERY SYSTEM USED 16. DATE AND TIME 17. DUAL RAIL 1 COS RELEASE GATE 10. DOORD THER (Explain) 18. DOORD THER (Explain) 19. DOORD THER (Explain) 19. DOORD THER (Explain) 19. DOORD THER (Explain) 19. DOORD THER (Explain) 10. DOO	1. UNIT BEING AIRLIFTED	2. DEP	ARTURE AIR	FIELD	3. 1	DATE			Т	5. ACFT SER NO
9. ACFT ALTITUDE (Feet) 800 AGL 130 Knots 328 ASL 0-5 Knots Unlimited CARGO 23. TYPE LOAD AND WEIGHT 81mm Mortar System 9. ACFT ALTITUDE (Feet) 81mm Mortar System 10. ACFT SPEED (KNOTS) 12. SURFACE WINDS (KNOTS) 13. VISIBILITY (Feet/Miles) 12. AERIAL DELIVERY SYSTEM USED 12. AERIAL DELIVERY SYSTEM USED 12. AERIAL DELIVERY SYSTEM USED 12. AERIAL DELIVERY SYSTEM USED 12. AERIAL DELIVERY SYSTEM USED 12. AERIAL DELIVERY SYSTEM USED 12. AERIAL DELIVERY SYSTEM USED 12. AERIAL DELIVERY SYSTEM USED 12. AERIAL DELIVERY SYSTEM USED 13. DOOD THANK (KNOTA) 14. COS RELEASE GATE (FEE) 15. AERIAL DELIVERY SYSTEM USED 16. ALTO THERE (Explain) 16. DOOD THANK (KNOTA) 17. TYPE PARACHUTE (FEE) 18. ALTO THERE (Explain) 19. DOOD THANK (KNOTA) 19. LEASE PARACHUTE (IF more space is needed, continue on reverse.) 19. LENGTH OF REEFING (IS more space is needed, continue on reverse.) 20. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) 21. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) 22. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) 23. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) 24. Type Parachute (III more space is needed, continue on reverse.) 25. AERIAL DELIVERY SYSTEM USED 26. TYPE PARACHUTE (IS more space is needed, continue on reverse.) 26. LEASE PARACHUTE (IS more space is needed, continue on reverse.) 27. TYPE PARACHUTE (IS more space is needed, continue on reverse.) 28. SIZE EXTRACTION/RE 19. LEASE PARACHUTE (IS more space is needed, continue on reverse.) 29. LENGTH OF REEFING (IS NOTAL THE (IS NOTA		<u> </u>					l			
SOUAGL 130 Knots 328 ASL 0-5 Knots Unlimited	5. OPERATION/EXERCISE			7. DZ AND	LOCATION			8. DATE	AND TIMI	Ē
RIMM Mortar System FM 10-500-3/ TO 13C7-1-11 28. SIZE EXTRACTION.RE LEASE PARACHUTE AND NUMBER 29. LENGTH OF REEFING A-21 T-10CGO 10. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunction, if it was caused during the malfunction, or caused during recovery. We believe the following happened When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stot loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove). ACFT ALTITUDE (Feet)	10. ACFT SPEED (Kno	ots) 11	. DZ ELEVATI	ON (Feet)	12. SU	RFACE WIND	S (Knots)	13. VIS	IBILITY (Feet/Mile
R1 mm Mortar System FM 10-500-3/ TO 13C7-1-11 R26- DROP CONTAINER 27- TYPE PLATFORMAIR: A-21 T-10CGO T-10CG	800 AGL	130 Knot	s	328	ASL		0-5 Kr	ots		Unlimited
81mm Mortar System 260 LBS TO 13C7-1-11 28 SYZE EXTRACTION/RE- LEASE PARACHUTE AND NUMBER T-10CGO 1. DESCRIPTION OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctioning, if it was caused during the malfunction, or caused during recovery. We believe the following happenew When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitiching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stoy loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove					7				1	
RIMM MORTAT System System FM 10-500-3/ TO 13C7-1-11 TO 13					CARGO					
81mm Mortar System 260 LBS TO 13C7-1-11 1 Doorbundle 27. Type parachute A-21 T-10CGO 1. DESCRIPTION OF MALFUNCTION/FAILURE / DAMAGE INCURRED (if more space is needed, continue on reverse.) Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunction, gif it was caused during the malfunction, or caused during recovery. We believe the following happene. When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the striching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove	3. TYPE LOAD AND	24. RIGGED IAW (1	MITOINAVA				AFRIAL D	ELIVERY SYS	TEM USEC)
System 260 LBS TO 13C7-1-11 28. SIZE EXTRACTIONIE LEASE PARACHUTE AND NUMBER 27. TYPE PARACHUTE LEASE PARACHUTE LEASE PARACHUTE AND NUMBER 28. SIZE EXTRACTIONIE LEASE PARACHUTE 29. LENGTH OF REEFING ARCRAFT 30. POSITION OF LOAD IN ARCRAFT ARCRAFT 30. POSITION OF LOAD IN ARCRAFT ARCRAFT ARD NUMBER 31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunction, if it was caused during the malfunction, or caused during recovery. We believe the following happene. When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitiching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, w					-		1		ī	
260 LBS TO 13C7-1-11 1 Doorbundle 27. TYPE PARACHUTE PARACHUTE AND NUMBER 28. SIZE EXTRACTION/RE-LEASE PARACHUTE 19. LENGTH OF REEFING PARACHUTE PARACHUTE A-21 T-10CGO 30. POSITION OF LOAD IN AIRCRAFT T-10CGO 31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunction, gif it was caused during the malfunction, or caused during recovery. We believe the following happened When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stoy loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove		EM 10	500.2/			_	<u> </u>		1	. , ,
27. TYPE PLATFORM/AIR. PROPOSITION OF LEASE PARACHUTE 29. LENGTH OF REEFING 30. POSITION OF LOAD IN AIRCRAFT A-21 T-10CGO 31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.) Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safer clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctioning, if it was caused during the malfunction, or caused during recovery. We believe the following happene. When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove	•	1			ł		1			Doorbundla
A-21 T-10CGO BI. DESCRIPTION OF MALFUNCTION/FAILURE / DAMAGE INCURRED (if more space is needed, continue on reverse.) Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safer clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctioning, if it was caused during the malfunction, or caused during recovery. We believe the following happened When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove							<u> </u>			
Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctio ing, if it was caused during the malfunction, or caused during recovery. We believe the following happene. When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove				REEFING						
Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctio ing, if it was caused during the malfunction, or caused during recovery. We believe the following happene. When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove						1				
Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctioning, if it was caused during the malfunction, or caused during recovery. We believe the following happene When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove	Δ_21	T-10CC	o.							
Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke. 32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctiong, if it was caused during the malfunction, or caused during recovery. We believe the following happene When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove		<u> </u>							<u> </u>	
32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.) Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunction ing, if it was caused during the malfunction, or caused during recovery. We believe the following happene. When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stoy loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove	31. DESCRIPTION OF N	MALFUNCTION/F.	AILURE/	DAMAGE	INCURRED (i	f more	space is ne	eded, conti	nue on r	reverse.)
Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safet clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctioning, if it was caused during the malfunction, or caused during recovery. We believe the following happened When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove	Bundle tumbled (fli	pped) and was t	owed pr	eventing	normal depl	oyme	ent. The s	tatic line	broke.	
Upon closer inspection of the container (unit derigged the load and the mortar system was not available for inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safer clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctioning, if it was caused during the malfunction, or caused during recovery. We believe the following happened When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stiching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove										
inspection), the following was found; the stitching on the left spreader bar was ripped, the right riser show burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safet clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctio ing, if it was caused during the malfunction, or caused during recovery. We believe the following happened when the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove				_						
burns, the static line protective sleeve has been forced up to the D-bag and is fused in place, and the safe clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctioning, if it was caused during the malfunction, or caused during recovery. We believe the following happene When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the sttiching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove										
clip lanyard is seared off with a piece of lanyard remaining inside the quick release assembly. The bundle itself has tears and rips but we could not determine if this damage was present prior to the load malfunctioning, if it was caused during the malfunction, or caused during recovery. We believe the following happene When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the sttiching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stoy loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove	I //	_	-	_				11	_	•
itself has tears and rips but we could not determine if this damage was present prior to the load malfunction ing, if it was caused during the malfunction, or caused during recovery. We believe the following happened when the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the sttiching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove										
ing, if it was caused during the malfunction, or caused during recovery. We believe the following happene When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the sttiching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stoy loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove										
When the AJ pushed the doorbundle out, he pushed it top first (as he stated in his statement) causing the bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the sttiching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove		1			•	-				
bundle to go out "head" first. This caused the parachute to be on the outside of the bundle causing it to tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the stitching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stoy loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove										
tumble in the air. When the parachute started its deployment sequence, the static line was forced from the opposite side of the load causing the burns on the right riser. The left riser may have caught on the quick release depositing the foreign substance on the release and breaking the sttiching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stoy loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove										
release depositing the foreign substance on the release and breaking the sttiching on the riser. It is possib that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stov loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove										
that, during its deployment, the static line protective sleeve caught the right (second) locking stow or stow loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove	opposite side of the	e load causing the	he burns	on the ri	ght riser. Th	e left	riser ma	y have ca	aught c	on the quick
loop and prevented the stow from deploying as prescribed, This cause the load to be towed and the static line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove	release depositing t	the foreign subs	stance on	the relea	ase and brea	king	the sttich	ing on th	ne riser	: It is possib
line to break. Because this is a broken static line, we are sending the equipment to Natick to disprove										
equipment failure.		use this is a brol	ken statio	c line, we	are sending	the e	equipmen	it to Nati	ck to d	isprove
	equipment failure.							-		
						_	_			

CONTINUED ON NEXT PAGE

WHAT WAS THE MALFUNCTION?

Bundle tumbled (flipped) and was towed preventing normal deployment. The static line broke.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Improper exit of bundle.
- 2. Locking fork lanyard misrouted over riser causing bundle to flip.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Proper rigging procedures and exit procedures.

				Z						
1.			·	GENERA	L			****		
1. UNIT BEING AIRLIFTED		2. DEPARTURE	AIRFIELD		3. D	ATE		4. TYPE ACF	T	5. ACFT SER NO.
								MC-13	30P	
6. OPERATION/EXERCISE		•	7. DZ AI	ID LOCATIO	N			8. DATE	AND TIM	
9. ACFT ALTITUDE (Feet)	10. ACFT SP	EED (Knots)	11. DZ ELEV	ATION (Feet)	12. SUR	FACE WIN	D\$ (Knots)	13. VIS	BILITY (Feet/Miles)
600 AGL	140	140 KIAS 282 N				010	(a) 12	2 Knots		Unlimited
		•	—							
111.				CARGO)					
23. TYPE LOAD AND	24. RIGGE	24. RIGGED IAW (TMITOINAVAIR No.)					A EDIAL	DEL WEBY 6V6	TE 5.4 115 55	
WEIGHT				25.			ACRIAL	DELIVERY SYS	TEM USE	
High Velocity				_ lo	UAL RAIL		CDS RE	EASE GATE	OTHER	(Explain)
CDS	F	M 10-500)-3/	NO. PL	ATFORMS		NO. CON	TAINERS		
800 LBS		TO 13C7-1-11				1	2			gh Velocity
26. TYPE PLATFORM/AIR- DROP CONTAINER		. TYPE PARACHUTE 28. SIZE EXT		XTRACTION E PARACHU			LENGTH O	F REEFING		SITION OF LOAD IN CRAFT
		_	1.							
A-22	26-	-Foot								
Containor	Rit	Ring Slot (1)							1 2r	nd/centerline

31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse,)

The MC-130P aircrew airdropped a two bundle, single stick high velocity CDS. Statements from the aircrew indicate that all airdrop procedures, to include aircraft airdrop rigging, were accomplished according to standards. The two CDS bundles exited the aircraft properly and the loadmasters noted nothing unusual about the drop. After the crew recovered to the airfield they were informed by the DZ party that the 2nd bundle to exit the aircraft came down faster than it should have and did not appear to have a full canopy. Upon inspection of the load the DZ party found that 2 of the 4 water barrels and the skid board were destroyed. The 26-foot RS parachute was found to have 2 broken suspension lines. The parachute was brought back to home station and inspected by a parachute packer, the JAI loadmaster, and the tactics loadmaster. The damage to the 26-foot RS parachute is as follows: Suspension lines 2 and 3 were broken approximately 38 inches from the canopy skirt; 15 other suspension lines had 6-12 inch long nylon burns adjacent to the broken lines. There was no other damage to the parachute. The D-bags were recovered from the aircraft and there was no damage to either. It should be noted that the AFSOC Supplement 1 to AFI 11-231 allows airdrop of high velocity CDS rigged in A-22 containers below 1100 feet AGL.

CONTINUED ON NEXT PAGE

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

Inspections by myself, the parachute packer, and the JAI loadmaster seem to indicate that this malfunction may have been caused by a line dumpage from the #1 suspension line stowage location. When the parachute was repacked in the original D-bag, the burn marks and the break centered directly between the #1 and #2 suspension line stowage locations. This parachute was put into service in Mar 2001 and this was its second airdrop. It had been repacked on 12 Jun 01 and was then placed upon the shelf. It was palletized with other parachutes and airdrop equipment for the deployment and was placed upon the CDS load when it was rigged at the deployed location. This is probably when the suspension lines fell from their stowage location.

ANALYSIS: 58

WHAT WAS THE MALFUNCTION?

Failure of canopy to fully inflate due to 2 broken suspension lines.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Possible load contact in the air based on comments from loadmaster in the aircraft.
- 2. Winds at altitude were high 20 knots.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Not Given.

I. 1. UNIT BEING AIRLIFTED	2. DEPARTURE		ENERAL 3.	DATE	4	TYPE ACFT	•	5. ACFT SER NO.		
						C-130)			
6. OPERATION/EXERCISE	•	7. DZ AND	LOCATION			8. DATE	AND TIME			
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVAT		12. SUI	RFACE WINDS	•	13. VISI	BILITY (FeetiMiles)		
600	135	3	35		6 Knots	S		Unlimited		
			7							
III.	The Discontinuous (Tables)	(A)(A(D 41-)	CARGO							
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/N		25.		AERIAL DEL	IVERY SYST	EM USED			
105 MM (III)	FM 10-500-3 TO 13C7-1-1		DUAL RAI	ι.	CDS RELEA	SE GATE	OTHER	(Explain)		
105 MM HE	FM 10-500-5		NO. PLATFORM	ıs	NO. CONTA	INERS				
(replicated) 2040 LBS	TO 13C7-18		ł		6			CVR		
26. TYPE PLATFORM/AIR- AND NUMBER 28. SIZE EXTRACTION/RE- LINE LINE LINE AND NUMBER 1. LEASE PARACHUTE LINE LINE AIR										
DROPCONTAINER	AND NUMBER	, LEASE	PAKACHUTE	1	LINE		Airc	KATI		
		68-in	ch Pilot	Ì			_			
Single A-22	G-12E(1)	Parac	chute				3r	d to exit		
31. DESCRIPTION OF M	MALFUNCTION/FAILUF	RE/ DAMAGE	INCURRED (i	f more	space is need	led, conti	nue on r	everse.)		
Load went through	gh extraction and d	lenlovmen	t phase nor	mall	v As load	l transit	tioned	into		
	the G-12E separat		•							
• 1	he adapter web, or					_				
	was missing com	•						-		
the tourth D-ring	΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄ ΄				_			\mathcal{C}		
_	nere was no damas	ge to the G	12E. The <i>A</i>	1 22 v	vas comi	oletely	aesirc	ved. Load		
was attached. Th	nere was no damag ntact with any othe	-		122 v	vas com _l	oletely	aesirc	yed. Load		
was attached. Th		-		A22 v	vas com _ļ	oletely	desirc	yed. Load		
was attached. The did not make cor	ntact with any othe	er loads at a	any time.				destro	yed. Load		
was attached. The did not make cor	ntact with any othe	er loads at a	any time.				destro	oyed. Load		
was attached. The did not make cor	ntact with any othe	er loads at a	any time.				destro	oyed. Load		
was attached. The did not make cor	ntact with any othe	er loads at a	any time.				destro	oyed. Load		
was attached. The did not make cor	ntact with any othe	er loads at a	any time.				destro	oyed. Load		
was attached. The did not make cor	ntact with any othe	er loads at a	any time.				destro	oyed. Load		
was attached. The did not make cor	ntact with any othe	er loads at a	any time.				destro	oyed. Load		
was attached. The did not make cor	ntact with any othe	er loads at a	any time.				destro	oyed. Load		

CONTINUED ON NEXT PAGE

ANALYSIS: 59

WHAT WAS THE MALFUNCTION?

Load separation at suspension webs.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Material failure.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Proper inspection of air items.

·													
1.			· · · · · · · · · · · · · · · · · · ·	GENE	RAL								
1. UNIT BEING AIRLIFTED		2. DEPARTURE	AIRFIELD			3. DA	NTE		4. TYPE A	ACFT		5. ACFT SER NO	0.
									C-1	30			
6. OPERATION/EXERCISE			7. DZ /	ND LOC	ATION				8. DA	TE AN	D TIME		
9. ACFT ALTITUDE (Feet)	10. ACFT SPI	ED (Knots)	11. DZ ELE	VATION	(Feet)	Ţ	2. SUR	FACE WIN	ID\$ (Knots)	1	13. VISIB	BILITY (Feet/Mile	es)
800 Feet	130 Knots				et	- 1		3 Kn	ots		U	nlimited	
					7_								
111.			· . · · · · · · · · · · · · · · · · · ·	CA	RGO								
23. TYPE LOAD AND	24. RIGGED IAW (TM/TO/NAVAIR No.)												
WEIGHT			,	25. AERIA					DELIVERY S	YSTEN	M USED		
				Γ	DUAL	RAIL		CDS RE	LEASE GAT	E (OTHER ((Explain)	
CDS	FN	И 10-500-	-53/	N	O. PLATFO	ORMS		NO. CONTAINERS			F	High	
1500 LBS	FM 10-500-53/ TO 13C7-1-11								2			Velocity	
26. TYPE PLATFORM/AIR- DROP CONTAINER		ARACHUTE NUMBER		EXTRAC	TION/RE-			LENGTH C	F REEFING	3	30. POSIT	TION OF LOAD I	N
			1.				1						
							1						
A-22	26-Fo	ot HV (1)											

31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.)

The load extraction properly from the aircraft, however, the breakcord tie broke prior to the deployment of the parachute. The parachute, still contained within the deployment bag, streamed behind the load during descent. As it fell the CDS turned over into a head down configuration and impacted the Drop Zone under no lift capability.

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

Upon inspection of the parachute some suspension lines were found to be wrapped around four suspension line stows which had never deployed. The parachute was packed in accordance with TM 10-1670-276-23&P (Sep 90). A message dated June 1996 changes the riser ties from 1/4 inch cotton webbing to ticket #5. The parachute was packed using the 1/4 inch cotton webbing riser ties. This packing procedure may have also contributed to the bag lock, which caused the breakcord tie to break the parachute was fully deployed. The message was unavailable at the time the parachute was packed.

CONTINUED ON NEXT PAGE

WHAT WAS THE MALFUNCTION?

Failure of parachute to deploy from the D-bag.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Improper pack procedures.
- 2. Can not use breakaway below 10,000 feet.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

- 1. Use proper procedures.
- 2. Proper JAI.

				-	7						
ł.				SENER	RAL						
1. UNIT BEING AIRLIFTED		2. DEPARTURE	AIRFIELD		3. [ATE		4. TYPE	ACFT		5. ACFT SER NO.
	ŀ							C-1	130)	
6. OPERATION/EXERCISE			7. DZ AN	D LOCA	TION			8. D	ATE A	ND TIME	
			1					1			
9. ACFT ALTITUDE (Feet)	10. ACFT SPEE	D (Knots)	11. DZ ELEVA	TION (F	eet)	12. SUF	RFACE WIN	VINDS (Knots) 13. VISIB			BILITY (Feet/Miles)
1200	UN	K		320			()		U	Inlimited
					7					•	
101.				CAR	60						
23. TYPE LOAD AND	24 RIGGED	IAW (TM/TO/N/	AVAIR No.)	T	<u></u>						
WEIGHT	24.1110020	IA 66 (1 MI/ 1 O/M)	~ · · · · · · · · · · · · · · · · · · ·	25.	AERIAL	DELIVERY	SYST	EM USED			
					DUAL RAIL	. .	CDS RE	LEASE GA	ſΕ	OTHER	(Explain)
A22-Wire	F	M 10-50	0-3/	NO.	PLATFORM	S	NO. CO	NTAINERS			
1050 LBS	4	FM 10-500-3/ TO 13C7-1-11				ı		3		Hig	gh Velocity
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PA AND NU		28. SIZE E LEAS	XTRACTI PARAC		29.	LENGTH O	F REEFING			TION OF LOAD IN
						1					
Λ_22	1.26-Foo	st HIV (1) I								1 -62

31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.)

On the first pass, the CDS came out of the aircraft, the cargo parachute failed to deploy. The load impacted the ground with no lift. Inspection of the parachute on site found the parachute on the ground next to the CDS load. The canopy was still in the deployment bag with a little part exposed to the ground with all pack closing ties broken. All suspension lines were still stowed, the static line was fully extended. The parachute and the load were returned to the shop where further inspection revealed burn marks on the static line 45 inches from clevis attaching point, burn mark on the deployment bag suspension line protector flap. The burn mark on the protector flap is the same width as the static line the whole width of the flap. No other damage to the parachute or deployment bag was noted. The A22 container has no noticable damage not caused by impact.

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

The possible cause of the malfunction is an interruption of the deployment force to the parachute. The 550 tie at the clevis broke before the parachute could even get out of the deployment bag possibly caused by the static line getting wrapped around the parachute during tipoff.

CONTINUED ON NEXT PAGE

ANALYSIS: 61

WHAT WAS THE MALFUNCTION?

Parachute failed to deploy.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Can not use breakaway below 10,000 feet.
- 2. Tie broke prematurely.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

Use proper procedures.

1.				NERAL						
1. UNIT BEING AIRLIFTED		2. DEPARTURE A	AIRFIELD	3.	DATE	i "	TYPE ACFT	5.	ACFT SER N	10.
6. OPERATION/EXERCISE		<u> </u>	7. DZ AND	LOCATION			C-17	AND TIME		• • • •
9. ACFT ALTITUDE (Feet)	10. ACFT SP	EED (Knots)	11. DZ ELEVATI	ON (Feet)	12. SUI	RFACE WINDS (#	(nots)	13. VISIBILI	TY (Feet/Mil	les)
500 AGL		Knots		I MSL		5 Knots		1	estricte	
SOUTISE	113	Terroto	300	7		3 Ithlots		l Om	CSUICIC	<u>u</u>
111.				CARGO				***************************************		
23. TYPE LOAD AND	24. RIGGE	DIAW (TMITOINA		I		-				
WEIGHT				25.		AERIAL DELI	VERY SYST	EM USED		
CDS Supply				DUAL RA	ı.	CDS RELEAS	E GATE	OTHER (Ex	plain)	
Load	Fl	M 10-500-	-3/	NO. PLATFORM	IS	NO. CONTAIL	NERS			
2300 LBS	1	O 13C7-1			1	2				
26. TYPE PLATFORM/AIR-	27. TYPE P	PARACHUTE	28. SIZE EXT	RACTION/RE-	29.	. LENGTH OF REE	FING		N OF LOAD	IN
DROP CONTAINER	AND	NUMBER	LEASE P	ARACHUTE	1	LINE		AIRCRAI	FT	
					i					
CDS	G-	12E(1)								
31. DESCRIPTION OF M	ALFUNCT	ION/FAILURI	E/ DAMAGE	INCURRED (i	f more	space is need	ed, contir	iue on reve	rse.)	
32. CAUSE OF MAI During exit the se caught on the Van	cond co	ntainer sta	rted movi	ng aft and	the lo	oop on the	forwa		_	got
		CONT	TINUED	ON NEX	T PA	AGE				

WHAT WAS THE MALFUNCTION?

Load did not exit the aircraft.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Loop on forward release gate caught on Van Zelm ratchet of aft release gate.
- 2. Type XXVI was too long or ratchet was improperly positioned.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Proper rigging in the aircraft and proper JAI.

AIRCRAFT MALFUNCTION REPORTS AND ANALYSES

1.			GE	NERAL								
1. UNIT BEING AIRLIFTED		2. DEPARTURE AI	RFIELD		3. DA1	ΓE		1	TYPE AC		5. ACFT SER N	٥.
6.0050.470.470.47			1.0	0647:00				L	C-13		<u></u>	
6. OPERATION/EXERCISE			7. DZ AND I	.OCATION					8. DAT	E AND TIM	E	
9. ACFT ALTITUDE (Feet)	10. ACFT SPI	EED (Knots)	1. DZ ELEVATIO	DN (Feet)	I ₁₂	. SUR	FACE WII	NDS ((nots)	13. VIS	BILITY (Feet/Mile	es)
300 AGL		Knots		0 Feet			N		,	1	10 Miles	,
0001102				7							101.11100	
III.			(CARGO								_
23. TYPE LOAD AND	24. RIGGEI	DIAW (TMITOINAV					450141	DELL	W58W 5W	CTEAN		
WEIGHT				25.		,				STEM USE	<u> </u>	
				DUAL		Ŀ			E GATE	OTHER	R (Explain)	
Heavy equipment	FM	10-517/		NO. PLATF	JKM3		NO. CO	NIAI	NEK5			
8300 LBS	TO	13C7-1-11	1	1								
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE P AND I	ARACHUTE NUMBER	28. SIZE EXT LEASE P	RACTION/RE- ARACHUTE			ENGTH (OF RE	EFING	30. POS	SITION OF LOAD I	N
T 1/												
Type V 16-Foot	l ,	~ 11 ·	\sim	2 Foot							EG 550	
31. DESCRIPTION OF M		G-11,									FS 550	
in progress locks tacted the cargo r noted and no train 32. CAUSE OF MALF Right hand locks nance performed released at 400 prit releas	amp and ing was unction #6 and #6 and took took took took took took took too	d on to the F s lost. N/FAILURE (I #7 failed allo test on both nd#7 releas	f more spa pwing pla #6 and # ed at 118	rce is need atform to \$7 right \$8 pound	ded, coroll	dar conti l aft d locaint	nage nue on . Afte cks L	rev r th	he airce airce 33D	raft lar 2-37-9 hecked	ramp was nded maint 9-1. Lock # d lock #8 a	‡6 .nd
		CONTI	NUED	ON NE	XT	PA	GE	_				

WHAT WAS THE MALFUNCTION?

INCIDENT - Loose platform locks #6 and 7 set at 2.75.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Not enough information (test results foot pounds or pounds?).
- 2. Preflight of locks or bad locks.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Complete preflight and after loading/JAI.

I.			GI	NERAL							_
1. UNIT BEING AIRLIFTED 2. DEPA		2. DEPARTURE AI	DEPARTURE AIRFIELD 3. DA			ATE 4.		4. TYPE ACFT		5. ACFT SER NO).
C OPERATION SYTPOSIC		.	1		L	C-13					
6. OPERATION/EXERCISE			7. DZ AND	LOCATION		8. DATE			AND TIME		
O ACCT ALTITUDE (FA)	40. 4667.600	55D (Warner) 1	1 07 51 51/4 71	ON (Face)	Lis	SUBSACE ME	NDC (Y44\	I 12 1/161	DU ITY /Face/Adila	۵)
9. ACFT ALTITUDE (Feet) 1225 MSL	10. ACFT SPEED (Knots)				'*	12. SURFACE WINDS (Knots)			13. VISIBILITY (FeetiMiles) Unlimited		<i>>)</i>
1223 WISL	130	30 KIAS 361 Feet 200/5 Unl							Jiminucu		
				<u> </u>							=
III. CARGO 23. TYPE LOAD AND 24. RIGGED IAW (TMITOINAVAIR No.)											
WEIGHT	24: 111002		25.		AERIAL DELIVERY SYST)	
				DUAL	RAIL	. CDS R	ELEAS	E GATE	OTHER (Explain) High Velocity		
CDS	FM	10-500-3/		NO. PLATF	ORMS	NO. C	IATAC	NERS			
1450 Lbs	1	13C7-1-11					1				5 7
26. TYPE PLATFORM/AIR-		ARACHUTE	28. SIZE EXT	RACTION/RE		29. LENGTH		EFING	30. POS	ITION OF LOAD I	_
DROP CONTAINER	AND	NUMBER	LEASE P	ARACHUTE		LINE			AIR	CRAFT	
	26-F	oot			:						
A-22	Ring	Slot(1)							F	S 667	
noticed at the points 32. CAUSE OF MALE Release knife was cut. Winch was no	functio not ver	n/FAILURE (If more spate 1	ace is nee	ded, o	ing up w	n rev	verse.) 00 mu	ch for		0
						PAGE					

WHAT WAS THE MALFUNCTION?

INCIDENT - CDS gate did not cut.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Not enough information (CVR or non).
- 2. Loose gate.
- 3. Knife not sharp.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

- 1. Use reporting guide.
- 2. Check CDS kits (i.e. knife not sharp).

I.				NERAL						
1. UNIT BEING AIRLIFTED		2. DEPARTURE A	IRFIELD		3. DA	ΓE		4. TYPE ACF	T	5. ACFT SER NO.
					Ĺ			C-17		<u> </u>
6. OPERATION/EXERCISE			7. DZ AND	LOCATION				8. DATE	AND TIMI	E
9. ACFT ALTITUDE (Feet)			11. DZ ELEVATION (Feet)		12. SURFACE WIN			1	IBILITY (Feet/Miles)	
800 AGL	800 AGL 145 KIAS		247 F	eet			060/9	Knots		5 Miles
				7_						
111.				CARGO						
23. TYPE LOAD AND 24. RIGGED IAW (TMITOINAVAIR No.)										
WEIGHT	1			25.			AERIAL (DELIVERY SYS	TEM USE	<u> </u>
				DUAL	RAIL		CDS REL	EASE GATE	OTHER	t (Explain)
DEUCE	FI	M 10-521/	,	NO. PLATE	ORMS		NO. CON	ITAINERS		
40,400 Lbs		O 13C7-6		1					EFTC	
26. TYPE PLATFORM/AIR	27. TYPE P		· V	RACTION/RE		29	LENGTH O	DEFEING	30 00	SITION OF LOAD IN
DROP CONTAINER		UMBER	LEASE P	ARACHUTE			LINE			CRAFT
24-Foot			Dra/Ex	rt Chuta						
	G_{-11}	IC (8)	_	Ext Chute				F	S 950	
Type V	G-11	(6)	13 T/L	BL 28					1	3 930
32. CAUSE OF MALI	FUNCTION	N/FAILURE (If more spa	ace is nee	ded, c	conti	inue on	reverse.)		
Consulted with 43 occurred.	37 AW S1	tan/Eval or	n possible	causes	. Una	ıble	e to det	ermine h	ow da	amage
							_			
		CONT	INUED	ON NE	УT	D A	CF			
		CONT	HULL	ON INE	ΛI	1 A	ML			

WHAT WAS THE MALFUNCTION?

INCIDENT - Bridge assembly damaged. Rails had metal shavings.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Improper alignment of platform prior to loading.
- 2. Wrong rail bridge assembly used (possibly).

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

- 1. TCTO for rail fix.
- 2. Assure proper alignment of platform.

				<u> </u>					
1.			ENERAL						
1. UNIT BEING AIRLIFTED	2. DEPART	URE AIRFIELD	3. D	ATE	1. TYPE ACF				
	<u> </u>				C-130	· · · · · · · · · · · · · · · · · · ·			
6. OPERATION/EXERCISE		7. DZ AND	LOCATION		8. DATE	AND TIME			
A ACET AL TITUDE (F)	10. ACFT SPEED (Knots)	11. DZ ELEVAT	1011 (54)	43 (11854)55 (41818)	(1/1-)	Las Meinnary (5			
9. ACFT ALTITUDE (Feet)		i i		12. SURFACE WINDS (Knots VRB02		13. VISIBILITY (Feet/Miles)			
1600 MSL	130	000	MSL	VKD	002	7+ Miles			
		·	7						
III.	24. RIGGED IAW (TMIT	O(A)A)/A(B A)	CARGO						
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/T	OINAVAIK NO.)	25.	25. AERIAL DELIVERY SYSTEM					
			DUAL RAIL	. CDS RELEA	ASE GATE	OTHER (Explain)			
			NO. PLATFORMS	NO. CONTA	AINERS	7			
Not Given	Not G	iven	ŀ						
	27. TYPE PARACHUTE		TRACTION/RE-	29. LENGTH OF R	EEFING	30. POSITION OF LOAD IN			
26. TYPE PLATFORM/AIR- DROP CONTAINER	AND NUMBER	LEASE	PARACHUTE	LINE	EEFING	AIRCRAFT			
		,							
Not Given	Not Given	No	t Given			Not Given			
31. DESCRIPTION OF M				<u> </u>		<u> </u>			
32. CAUSE OF MAL Wear and tear on connecting them	the aft anchor c	able support	and the act	tuator arm ca	aused tl	he two bolts			
	СО	NTINUED	ON NEXT	T PAGE					

WHAT WAS THE MALFUNCTION?

Ramp and door unable to close from flight deck or loadmaster panel.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Microswitch on aft anchor support.
- 2. Not enough information.
- 3. Did the aircraft land with ramp and door open or did door release from uplock?

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Report to be complete by host tactics unit.

										_
I.				NERAL			7,25 4.65		I	_
1. UNIT BEING AIRLIFTED		2. DEPARTURE A	IKFIELD	3. DATE			TYPE ACF. C-17		5. ACFT SER NO.	•
6. OPERATION/EXERCISE			7. DZ AND	LOCATION		i.		/ AND TIME		
9. ACFT ALTITUDE (Feet)	10. ACFT SP	EED (Knots)	11. DZ ELEVATI	ON (Feet)	12. SURF	FACE WINDS	(Knots)	13. VISI	BILITY (FeetiMiles	s)
800 AGL	L 130		360	Feet 6 Knots			s Unrest		Inrestricted	1
				72						
111.			ı	CARGO						
23. TYPE LOAD AND WEIGHT	24. RIGGE	DIAW (TMITOINA)	/AIR No.)	25.		AERIAL DEI	IVERY SYS	TEM USEC)	
					1 1			ī		
				NO. PLATFORM		NO. CONTA		OTHER	(Explain)	
		N C'						1		
Not Given		Not Give	· · · · · · · · · · · · · · · · · · ·							
26. TYPE PLATFORM/AIR- DROP CONTAINER		ARACHUTE NUMBER		RACTION/RE- ARACHUTE		ENGTH OF R	EEFING	30. POSITION OF LOAD IN AIRCRAFT		4
	l									
Not Given	Not	Given							Not Given	
31. DESCRIPTION OF M							,			
32. CAUSE OF MAI The actuator rod t clearance panel o tor.	hat retra	acts and ext	ends the	pod faring	broke	e. The p	od fairi	_		
		CONT	INUED	ON NEX	ΓPA	GE				

ANALYSIS: 67

WHAT WAS THE MALFUNCTION?

Pod fairing broke.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Actuator broke.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Not Given.

I.	· · · · · · · · · · · · · · · · · · ·	GI	NERAL				
1. UNIT BEING AIRLIFTED	2. DEPARTURI	AIRFIELD	3. DA	ATE 4.	TYPE ACFT		
	<u> </u>				C-130		
6. OPERATION/EXERCISE		7. DZ AND	LOCATION		8. DATE A	AND TIME	
						•	
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVATI		2. SURFACE WINDS (Knots)		13. VISIBILITY (Feet/Miles)	
920	140	992	MSL	5 Knots		7+ Miles	
			<u> </u>				
101.			CARGO				
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TMITOIN	IAVAIR No.)	25.	EM USED			
				1 1			
			NO. PLATFORMS	. CDS RELEAS		OTHER (Explain)	
	FM 10-50	00-2/	NO. PLATFORMS	NO. CONTAI	NEK)		
Heavy Equipment	TO 13C7	-1-5	1				
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER	28. SIZE EXT	RACTION/RE- ARACHUTE	29. LENGTH OF RE	EFING	30. POSITION OF LOAD IN AIRCRAFT	
				ĺ			
Type V	G-12E (2)	1:	5-Foot			STA 560	
32. CAUSE OF MAL. Possible right han				continue on re	verse.)		
	CON	FINUED	ON NEXT	PAGE			

WHAT WAS THE MALFUNCTION?

INCIDENT - Right hand pull.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Bad lock. Not enough information.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Put -21's findings in malfunction report.

1.			ENERAL					
1. UNIT BEING AIRLIFTED	2. DEPARTUR	RE AIRFIELD	3. D	ATE 4	L TYPE ACF C-13			
6. OPERATION/EXERCISE	<u> </u>	7 DZ AND	LOCATION	L		AND TIME		
b. OFERATION/EXCREISE		7.02 4.10	LOCATION		0.0412	AND THE		
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVAT	ION (Feet)	12. SURFACE WINDS	(Knots)	13. VISIBILITY (FeetiMiles)		
1200	140	47		6-8				
1200	170		7	0.0		Стинтисс		
111.			CARGO					
23. TYPE LOAD AND	24. RIGGED IAW (TMITO)	,	LANGO					
WEIGHT			25.	AERIAL DEI	IVERY SYS	STEM USED		
			DUAL RAIL	. CDS RELEA	SE GATE	OTHER (Explain)		
HE Training	FM 10-512	/	NO. PLATFORMS	MS NO. CONTAINE				
2700 Lbs	TO 13C7-1	-8	1					
26. TYPE PLATFORM/AIR	27. TYPE PARACHUTE	28. SIZE EXT	RACTION/RE-	29. LENGTH OF R	EEFING	30. POSITION OF LOAD IN		
DROP CONTAINER	AND NUMBER	LEASE	PARACHUTE	LINE		AIRCRAFT		
				1				
Type V	G-12E(2)	1:	5-Foot			630		
32. CAUSE OF MAL Right lock #9 tes	FUNCTION/FAILUR	_						
	CON	TINUED	ON NEXT	Γ PAGE				

WHAT WAS THE MALFUNCTION?

INCIDENT - Right hand pull.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Lock released at high side of limits.
- 2. Possible bad lock. Did lock get replaced?

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Pressure right hand locks more often.

			7					 -
1.		GE	NERAL					<u> </u>
1. UNIT BEING AIRLIFTED	2. DEPARTURE	AIRFIELD	3.	. DATE	TE 4. TYPE AC		FT	5. ACFT SER NO.
						C-17	7	
6. OPERATION/EXERCISE	· ·	7. DZ AND	LOCATION			8. DAT	E AND TIME	
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)				SURFA	CE WINDS (Knots)	13. VISI	BILITY (Feet/Miles)
1275 AGL	145 KCAS	1175 AGL			2	20/07	1	10+ NM
			7			•	-	
111.			CARGO					
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/N/	AVAIR No.)	25.			ERIAL DELIVERY SY	CTESA 11CE	
WEIGHT			23.			TERIAL DELIVERY ST	STEINI OSEL	,
			DUAL RA	AIL		DS RELEASE GATE	OTHER	(Explain)
Training Load	FM 10-500-2)/	NO. PLATFOR	MS	NO. CONTAINERS			
3150 Lbs			1 62	- 1			j	Ъ
3130 L08	TO 13C7-1-5)	1 of 2				_1	Drogue
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		RACTION/RE- ARACHUTE		29. LEN LIN	IGTH OF REEFING E		SITION OF LOAD IN CRAFT
			_					
LVAD, Type V,		15.	-Foot				1	
8 Foot	G-12E(2)	Sta	ındard				Sta	1020

31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.)

This "Auto Drop" of a single heavy equipment platform had reached the 15 second point prior to TOT in which the drogue parachute was released into the air stream. The drogue parachute looked fully deployed and in good shape. At approximately 5 seconds prior to TOT the automatic countdown began and the drogue parachute suddenly went below the cargo ramp and out of sight. At approximately 2 seconds prior to TOT the drogue parachute reappeared and appeared to have a panel or some material torn away as the loadmaster could see daylight through the parachute. The loadmaster called malfunction at that point and proceeded to reach up and activate the drogue jettison switch and left locks. The aircraft in the meantime had reached TOT and had released the TRM and the extraction parachute at the same time or before the drogue jettison switch was activated. While the extraction package was being deployed the locks were engaging. The locks in the side of the platform did not engage in time to hold the platform but the locks just aft of the platform engaged and stopped the platform. The extraction parachute was fully deployed and was cut away.

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

The board concurred that the drogue parachute had failed which set events in motion, which resulted in a malfunction. The board agreed that the loadmaster failed to ensure the drogue parachute was released before initiating the rail locks. The board also agreed that there might not have been enough time for the loadmaster and pilot to react prior to TOT and the TRM was released.

WHAT WAS THE MALFUNCTION?

Extraction package cut away.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Loadmaster procedures.
- 2. Drogue parachute failure.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

- 1. Proper procedures.
- 2. Modified drogue parachutes.

I. 1. UNIT BEING AIRLIFTED		2. DEPARTURE A		NERAL 3. 0	ATE	Ι Δ	TYPE ACF	r	5. ACFT SER NO.	
NOME OF THE PROPERTY OF THE PR	i	2. 50. 44. 64.					C-14		J. Act 1 Seminor	
6. OPERATION/EXERCISE			7. DZ AND	LOCATION			8. DATE	AND TIMI		
								,		
9. ACFT ALTITUDE (Feet) $1000\mathrm{AGL}$	10. ACFT SPE	KIAS	11. DZ ELEVATI 530	· ·	12. SUR	FACE WINDS (Knots)	1 .	IBILITY (Feeti M iles) 7 +	
10001102						220,00	-		<u> </u>	
111.				CARGO						
23. TYPE LOAD AND WEIGHT	24. RIGGE	DIAW (TMITOINA	/AIR No.)	25.		AEDIAI DEL	MEDV CVC	TENA JICES	`	
				 	7			SYSTEM USED		
Standard Training Platform				DUAL RAIL NO. PLATFORMS		. CDS RELEASE GATE NO. CONTAINERS		OTHER	l (Explain)	
3100 LBS	N	ot Given			l					
26. TYPE PLATFORM/AIR-	27. TYPE P	ARACHUTE		RACTION/RE-	29. (LENGTH OF RE	EFING	30. POS	SITION OF LOAD IN	
DROP CONTAINER	AND	NUMBER	LEASE P	ARACHUTE	İ	LINE		AiR	CRAFT	
Type V					Ì					
8 Foot	G-	12E(1)]	15 Foot				<u></u>	FS 1150	
32. CAUSE OF MALE Investigation conc This allowed the ra phase.	luded th	e selector a	rm positi	on lock pin	was	worn an	d not p		•	
						_				
		CONT	INUED	ON NEX	Г РА	AGE				

WHAT WAS THE MALFUNCTION?

Load failed to extract.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Improper inspection by -21.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Complete proper inspection.

			7							
1.		G	ENERAL							
1. UNIT BEING AIRLIFTED	2. DEPARTURE	AIRFIELD		3. DATE 4.			4. TYPE ACF	Т	5. ACFT SER NO.	
							C-13	C-130		
6. OPERATION/EXERCISE	-	7. DZ AND	LOCATION				8. DATE	AND TIME		
				_				_		
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	ION (Feet)	12. SURFACE WINDS (Knots)				1	BILITY (Feet/Miles)		
800 AGL	130 KIAS	907	07 310 @ 7) 7	10 Miles		
			7_							
111.			CARGO							
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/N)	AVAIR No.)	25. AERIAL DELIVERY SYSTEM USED							
CDC Training			DUAL	RAIL		CDS REI	EASE GATE	OTHER	(Explain)	
CDS Training			NO. PLATFO	RMS	т'	NO. CO	ITAINERS	1		
Load	FM 10-500-3	/			1			1		
800 Lbs	TO 13C7-1-1	1					1	I	High Velocity	
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		TRACTION/RE- PARACHUTE			ENGTH O	F REEFING		ITION OF LOAD IN CRAFT	
	26-Foot High	<i>'</i>			ł					
A-22 Container	V(1)							1	of 2/FS 700	

31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.)

This malfunction occurred at green light. The retriever ran for 1 second and based on loadmaster interviews, the slip clutch engaged, failing to cut the release gate. The crew performed malfunction procedures and returned to base. The aircraft was impounded upon parking. There was no damage to the aircraft or the load.

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

The incident bundle was one of two independently scheduled CDS drops for that day. The CDS gate was rigged at FS 725 and the pulley installed at FS 737. The bundle was rigged in the airplane according to TO 1C-130-A-9. The pulley strap showed no signs of damage. The pulley assembly has a few knicks on the outer edges of the pulley wheel. Upon inspection the safety tie on the knife was still intact with less than 2 inches of slack in the cable. During the flight, the loadmasters noticed slight oscillations in the cable. The right side western gear retrieval was used. Upon inspection, the winch showed no signs of damage. Each beaded chain measured 4 3/4 inches. The setscrew was also properly set. The spring appeared normal and the cup fully seated. The cable wire had internal wire damage (5 broken strands) at the exact point where the cable ran through the pulley at the time of the initial rewind sequence. The loadmaster reports that the cable was extremely taut after the incident. The winch was then tested with the CDS bundle on the aircraft. The winch performed the gate cut with no malfunctions. We could not duplicate the malfunction. The static line

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

retriever winch was then removed from the aircraft, cable replaced, and bench tested. The slip clutch engaged 1800 pounds within the required limit of 1500-1800 pounds. There were no other signs of internal or external damage to the winch. Based on the evidence provided, at green light, due to the oscillation and amount of slack in the cable, the cable became partially wedged in the pulley preventing the cable from rewinding any further resulting in the slip clutch engaging and not breaking the safety tie on the CDS knife. WHAT MIGHT PREVENT THIS MALFUNCTION FROM REPEATING. Remove the pulley from service. Ensure the minimum amount of allowable slack is maintained in the static line retriever cable, especially when using the pulley location at FS 737. Add an additional safety tie around the cable at FS 550, to reduce the amount of oscillation experienced during flight and at the time of the drop.

ANALYSIS: 72

WHAT WAS THE MALFUNCTION?

Gate failed to cut.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Cable got jammed in pulley due to slack in cable and engaged slip clutch.

WHAT SHOULD YOU DO TO KEEP THIS FROM HAPPENING?

- 1. Ensure JAI checks minimum slack in cable.
- 2. Check CDS kits (i.e. pulley serviceable).

. HANT GEING AIDLIETED	4 11 1	2. DEPARTURE A		NERAL	3. DA	TC	1 4	TYPE ACE	· T	5. ACFT SER NO.
1. UNIT BEING AIRLIFTED		2. DEPARTURE A	MKFIELD		3. DATE			C-17	S. ACFT SER NO	
6. OPERATION/EXERCISE		<u> </u>	7. DZ AND	LOCATION			8. DATE AND TH			<u> </u>
9. ACFT ALTITUDE (Feet)	10. ACFT SP	EED (Knots)	11. DZ ELEVATION (Feet) 12. SURFACE WINDS (Knots)					13. VISIBILITY (Feet/Miles)		
1000 Feet AGL	130	Knots	2801	Feet		030/	5	Unlimited		
		·		7						
)II.				CARGO						
23. TYPE LOAD AND	24. RIGGE	DIAW (TMITOINA		· ·						
WEIGHT	WEIGHT			25.		AERIAL	DELI	VERY SYS	TEM USE)
				DUAL		 		E GATE	OTHER	l (Explain)
	1			NO. PLATE	ORMS	NO. CO	NTAI	NERS		
Not Given	N	Not Given								
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE P	ARACHUTE NUMBER	28. SIZE EXT LEASE P	RACTION/RE-		29. LENGTH C	OF RE	EFING		SITION OF LOAD IN
		~.								
Not Given	N	ot Given								
outward. The left releasing. Upon the All jumpers exite	further in	nvestigatio	n the para	troop d		-		•		•
32. CAUSE OF MAL										
When the loadma mechanism and b the spring latch/uj the weight being of	ent the plock me	track stops echanism.	on both s Γhe uploc	sides. Th k releas	ne pa e hai	nratroop d ndle did n	loo ot f	r then	restec	l on top of
							_			
		CONT	INUED	ON NE	EXT	PAGE				

WHAT WAS THE MALFUNCTION?

Troop door tracks damaged.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Loadmaster opening the door too vigorously.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Brief loadmasters on door procedures.

I.				ENERAL								
1. UNIT BEING AIRLIFTED		2. DEPARTURE AL	RFIELD		3. DA			I. TYPE	-130	5. ACFT SER NO.		
6. OPERATION/EXERCISE			7. DZ AND	LOCATION			8. DATE AN			E		
9. ACFT ALTITUDE (Feet)	10. ACFT SPE	ED (Knots)	11. DZ ELEVATION (Feet) 12. SURFACE WINDS (Knots)						13. VI	13. VISIBILITY (Feet/Miles)		
800	1	.30	110 080/08							8 to 10		
				7_								
III.				CARGO								
23. TYPE LOAD AND WEIGHT	24. RIGGED	IAW (TMITOINAV	AIR No.)	AERIAL DELIVERY SYSTEM USED								
				DUAL	RAII	П	CDS RELEA	SE GAT	т ОТНЕ	R (Explain)		
CDS	EN	1 10-500-3	1	NO. PLATE			NO. CONTA			(CAPIGIN)		
922 Lbs	1	1 10-300-3) 13C7-1-1					1					
26. TYPE PLATFORM/AIR-	27. TYPE P		·	RACTION/RE		29. LE	NGTH OF R	EEFING	30. PC	SITION OF LOAD IN		
DROP CONTAINER		UMBER	LEASE F	PARACHUTE		LI	NE		All	CRAFT		
A-22	26-Foo	ot HV (1)								FS 530		
without either if and the cable kep all systems work 32. CAUSE OF MAI There were no proloads and could not find any discrete.	ot rewind ted as ad LFUNCTIO evious w ot duplic	ing till it can vertised. No N/FAILURE rite ups in tate the prob	me in cor o damag	ntact with e to the pace is ne	h the	e pull aft o conti	ey. Dur r loads nue on r	and and the the t	the aircr no injur	aft pre-flight ies occurred.		

WHAT WAS THE MALFUNCTION?

Retriever winch ran when system not armed.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. System armed with cover down.
- 2. Not enough information.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

- 1. Follow reporting guide.
- 2. Check CDS arming switch with cover down.

1.			ENERAL					
1. UNIT BEING AIRLIFTED	2. DEPARTURE	AIRFIELD	3.	DATE	4. TYPE ACF	T 5. ACFT SER NO.		
			1		C-13	0		
6. OPERATION/EXERCISE	•	7. DZ AND LOCATION			8. DATE	AND TIME		
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	CFT SPEED (Knots) 11. DZ ELEVATION (Feet) 12. SURFACE WINDS (Knots)						
425	130		30	210	7 Miles			
			7_					
444			CARGO					
111.			T					
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/N	IAVAIR No.)	25.	AERIA	AERIAL DELIVERY SYSTEM USED			
			DUAL RAI	L CDS R	ELEASE GATE	OTHER (Explain)		
CDS	FM 10-500-	-3/	NO. PLATFORM	IS NO. CO	ONTAINERS	High		
860 LBS	TO 13C7-1-	-11			1	Velocity		
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		TRACTION/RE-	29. LENGTH LINE	OF REEFING	30. POSITION OF LOAD IN AIRCRAFT		
A-22	26-Foot HV (1				2 of 2			

31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.)

This incident occurred at green light. The retriever started to rewind. As soon as all the slack was removed from the static line retriever cable, the winch shut off, failing to cut the release gate. There was no damage to the aircraft or the load.

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

The incident bundle was the second of two independently scheduled CDS for that mission. The high velocity CDS weighed 860 pounds. The CDS pulley was rigged at FS 550. The safety tie on the knife was still intact. The right side western gear retriever was used. Upon inspection the winch showed no signs of damage. Each beaded chain measured 4 13/16 inches. The setscrew did not appear to be set correctly when compared to the measurement of the left side western gear retriever. The spring appeared normal and the cup fully seated. This winch was recently installed due to an aircraft ISO dock inspection. The winch was then tested and incident duplicated. Based on evidence found, the setscrew was improperly set, causing the winch to shut off prematurely and not cutting the safety tie on the knife. WHAT MIGHT PREVENT THIS INCIDENT FROM REPEATING: The electric shop adjusted the setscrew. The electric shop is inspecting all western gear retrievers to ensure the setscrew is properly set. The incoming western gear retrievers will be inspected to ensure the setscrew is properly set.

WHAT WAS THE MALFUNCTION?

Gate failed to cut.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

- 1. Improper maintenance procedures.
- 2. Timer set screw not within limits.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Training for maintenance section.

650 AGL	2. DEPARTURE ACFT SPEED (Knots)		LOCATION	3. DATE		4. TYPE ACFI		5. ACFT SER NO.		
9. ACFT ALTITUDE (Feet) 10. 650 AGL	ACFT SPEED (Knots)	7. DZ AND	LOCATION			~				
9. ACFT ALTITUDE (Feet) 10. 650 AGL	ACFT SPEED (Knots)	7. DZ AND	LOCATION	C-130						
650 AGL	ACFT SPEED (Knots)					8. DATE	AND TIME	<u> </u>		
		11. DZ ELEVATI	ION (Feet)	12. 9	SURFACE WINE)\$ (Knots)	13. VISII	BILITY (Feet/Miles)		
	140	590	590 Calm 7 Mile							
	· · · · · · · · · · · · · · · · · · ·		<u> </u>							
111.			CARGO							
23. TYPE LOAD AND WEIGHT	4. RIGGED IAW (TM/TO/NA	AVAIR No.)	25.		AERIAL E	ELIVERY SYST	re m used			
						EASE GATE	OTHER	(Explain)		
CDS	FM 10-500-	3/	NO. PLATFO	ORMS	NO. CONTAINERS					
1089 LBS	TO 13C7-1-	11			1	1				
26. TYPE PLATFORM/AIR- DROP CONTAINER	7. TYPE PARACHUTE AND NUMBER		RACTION/RE- 29. LENGTH OF PARACHUTE LINE			REEFING		ITION OF LOAD IN RAFT		
	26-Foot Ring	•		ł						
A-22	Slot(1)							FS 506		
31. DESCRIPTION OF MAL	FUNCTION/FAILUR	E/ DAMAGE	INCURREI) (if mo	re space is n	eeded, conti	nue on re	everse.)		
At green light, the w	inch only ran fo	r 1 second	l. Malfur	etion	checklis	t was rur	n and a	ircraft		
RTB. Reporting guid	•									
limits, cup seated. L				_	_					
checked good. Wind		~ ~			U 1			1		
anything, knife was							_	_		
turbulence. Last insp								v 1X, 110		
turburence. Last msp	occuon unknow.	n. mpact	oi illaitu	псио	11 - 1088 01	currenc _.	y 			
22 CAUCE OF MALEU	NOTION EARL WATER	. ae				,				
32. CAUSE OF MALFU	NC HON/FAILURE	. (II more sp	pace is nee	eded, c	ontinue on	reverse.)				
Per -21 there was no	problem with t	he winch	itself. Tl	ne ma	tter was i	then refe	rred to	the shop.		
According to them to										
placed.	:::::::::::::::::::::::::::::::::::		,							

ANALYSIS: 76

WHAT WAS THE MALFUNCTION?

Gate failed to cut.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Bad timer relay.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Not given.

I.			GENERAL							
1. UNIT BEING AIRLIFTED	2. DEPARTUR	RE AIRFIELD	RE AIRFIELD 3. D			TE 4. TYPE AC		YPE ACFT 5. AC		5. ACFT SER NO.
				<u></u>				C-13		
6. OPERATION/EXERCISE		7. DZ AND	DLOCATION				7	8. DATE A	AND TIME	
							丄			
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)						nots)	13. VISIBILITY (Feet/Miles)		
800 MSL	130	1	150 180-2403G8					7 Miles		
				_	_					
M.		,	CARGO							
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/	INAVAIR No.)					. DELIVI	ERY SYST	EM USED	
ĺ			DUA	L RAIL		CDS RE	ELEASE	GATE	OTHER	(Explain)
CDS	FM 10-50	00-3/	NO. PLATF	ORMS	·T	NO. CONTAINERS		ERS		
800 LBS	TO 13C7-	-1-11				1	L		H	igh Velocity
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		XTRACTION/RE E PARACHUTE	j-		LENGTH C	OF REEF	ING		ITION OF LOAD IN
A-22	26 Foot	<u> </u>]	FS 575
31. DESCRIPTION OF M	MALFUNCTION/FAILU	JRE/ DAMAGF	E INCURRE	ED (if	more	space is	neede	d, contir	nue on r	everse.)
				- (- I		-,		,
Gate failed to cut	t on single CDS co	ontainer. Ri	ight hand	l retr	rieve	er wind	ch ri	gged.	Winc	h activated

Gate failed to cut on single CDS container. Right hand retriever winch rigged. Winch activated on green light on approximately 1 second. Malfunction checklist was completed and aircraft RTB. No damage to aircraft or load. Right winch spring in good condition and beaded chains of equal length compression spring seated in cup. 1/4 cotton webbing safety tie did not break. Knife was sharp and pulley was rigged at FS 617 gate FS 600 Non CVR.

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

Dash 21 inspection of winch revealed no findings. Suspect limit switch engaged to cut off winch.

WHAT WAS THE MALFUNCTION?

Gate failed to cut.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Limit switch or timer/timer relay possibly bad.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

- 1. Replace winch.
- 2. Put maintenance findings in report.

1.				ENERAL						
1. UNIT BEING AIRLIFTED		2. DEPARTURE A	MRFIELD		3. DA	TE	4. TYPE ACFT		5. ACFT SER NO.	
					<u> </u>		C-13			
6. OPERATION/EXERCISE			7. DZ AND	LOCATION			8. DATE	AND TIME		
9. ACFT ALTITUDE (Feet)	10. ACFT SPE	EED (Knots)	11. DZ ELEVAT	, ,	12	. SURFACE WIND	DS (Knots) 13. VISIBILITY (FeetiMile			
650 AGL	1	40	59	90		Calm		7 Miles		
		-		74						
101.				CARGO						
23. TYPE LOAD AND	24. RIGGE	DIAW (TMITOINA	VAIR No.)							
WEIGHT		25.				AERIAL D	LIVERY SYST	TEM USED		
				DUAL	RAIL	. CDS RELE	ASE GATE	OTHER	(Explain)	
CDC	EV	И 10-500-:	2 /	NO. PLATE	ORMS	NO. CONT	AINERS	1		
CDS									CI ID	
1089 LBS	<u></u>) 13C7-1-		<u> </u>		6		<u> </u>	CVR	
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE P AND I	ARACHUTE NUMBER		RACTION/REPARACHUTE		29. LENGTH OF LINE	REEFING		ITION OF LOAD IN	
	26	E4								
		Foot				1				
A-22	Rın	ng Slot (1)						Gat	te @ FS 570	
gate. No damage gear. Spring cond switch did not en approximately 2 was sharp. Pulled Unknown. Impact another flight2 32. CAUSE OF MALI Unknown.	lition go gage to o seconds d rigged et of mal	ood. Beader cut off win . 80 pound at FS 530. function - I e winch ch	d chain 4 ch. Pull te did not b CVR wa Loss of tra ecked ou	3/4 inchest compreak. Krs used. Nining fo	es ar oletec nife d No tu or stud nd co	nd equal. Cd - Checked lid not get our bulence. I dent pilot. Yould not du	up was a d good.v caught o Last tim Will hav plicate t	seated winch on anythe e insp	l. Limit ran for thing. Knife ected: make up on	
		CONT	INUED	ON NE	EXT	PAGE				

WHAT WAS THE MALFUNCTION?

Gate failed to cut.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Timer/Timer relay possibly bad.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Replace winch.

,											
1.				NERAL			 				
1. UNIT BEING AIRLIFTED		2. DEPARTURE AII	RFIELD	3.	DATE	4.	TYPE ACF		5. ACFT SER NO		
6. OPERATION/EXERCISE		<u> </u>	7. DZ AND	LOCATION			C-13	O AND TIME	<u> </u>		
ı											
9. ACFT ALTITUDE (Feet)	10. ACFT SP	ED (Knots) 11. DZ ELEVATION (Feet) 12. SURFACE WINDS (Knots)						13. VISIBILITY (Feet/Miles)			
800 AGL	130	KIAS	IAS 2525 MSL Calm								
				7_							
III.				CARGO							
23. TYPE LOAD AND WEIGHT	24. RIGGE	D IAW (TMITOINAV	25. AERIAL DELIVERY SYSTEM USED								
High Vologity		10.500.2/		DUAL RA		. CDS RELEA	SE GATE	OTHER	(Explain)		
High Velocity CDS	I .	10-500-3/ 13C7-1-11		NO. PLATFORM	_	NO. CONTA		1	(
1100 LBS		13C/-1-11 pter 9				1					
26. TYPE PLATFORM/AIR-	27. TYPE 8	PARACHUTE		RACTION/RE-	29	LENGTH OF RE	EFING		SITION OF LOAD IN		
DROP CONTAINER	AND	NUMBER	LEASE P	ARACHUTE		LINE		AiR	CRAFT		
	26-F	oot Ring			1						
A-22	Slot	(1)						F	S 500		
The limit switch of winch to run for a much for the winch cut.	on the ab about ha	ove mention lf of a secon	ned retrie d then cu	ever winch ut off when	was n the	tuned inc	orrectl	y. Thi le bec	ame too		
		CONT		ON NEW	T. D.	A CE					
		CONTI	NUED	ON NEX	T P.	AGE					

ANALYSIS: 79

WHAT WAS THE MALFUNCTION?

Gate failed to cut.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Limit setscrew improperly set.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Replace winch.

1.		G	ENERAL			
1. UNIT BEING AIRLIFTED	2. DEPARTURI	E AIRFIELD	3. D	ATE	I. TYPE ACFT	
	<u> </u>		<u> </u>		C-13	
6. OPERATION/EXERCISE		7. DZ AND	LOCATION		8. DATE	AND TIME
9. ACFT ALTITUDE (Feet)	10. ACFT SPEED (Knots)	11. DZ ELEVAT	ΓΙΟΝ (Feet)	12. SURFACE WINDS	(Knots)	13. VISIBILITY (Feet!Miles)
500 130		2	30	4		12
			7			
111.			CARGO			
23. TYPE LOAD AND WEIGHT	24. RIGGED IAW (TM/TO/N	AVAIR No.)	25.	AERIAL DE	LIVERY SYST	EM USED
CDS			DUAL RAIL	. CDS RELEA	SE GATE	OTHER (Explain)
Low Velocity	FM 10-500)-3/	NO. PLATFORMS	NO. CONTA	NINERS	
1300 LBS	TO 13C7-1	l-11		2		SLR/Gate
26. TYPE PLATFORM/AIR- DROP CONTAINER	27. TYPE PARACHUTE AND NUMBER		TRACTION/RE- PARACHUTE	29. LENGTH OF R	EEFING	30. POSITION OF LOAD IN AIRCRAFT
		•				Gate 530
A-22	A-22 G-12E(1)					LD 520

31. DESCRIPTION OF MALFUNCTION/FAILURE/ DAMAGE INCURRED (if more space is needed, continue on reverse.)

Western gear static line retriever malfunction. Gate failed to cut. Winch ran for approximately 1.5 seconds and cut off <u>right retriever</u> used, spring condition okay. Cup was seated, limit switch did engage and cut winch off, limit switch was safetied, switch cap was .050. Pull test 1750 pounds good ran for approximately 1.5 seconds, 80 pound safety tie did not break, knife did not get caught on sling, knife was sharp, pulley located at FS 530 and gate was located at FS 520, non CVR, no turbulence, winch inspected. Impact was loss of drop, loss of follow on personnel drop, navigator check ride not finished, one missed route and one assault landing not accomplished and 1.5 flying hours lost.

32. CAUSE OF MALFUNCTION/FAILURE (If more space is needed, continue on reverse.)

Angle of winch retriever cable may have been too severe with the winch being set at a medium limit switch gap setting, ie, .050 instead of .065 using the right winch forward of flight station 550 can induce the limit switch to engage. We will in future try and use the left SLR winch at these stations.

WHAT WAS THE MALFUNCTION?

Gate failed to cut.

WHAT COULD HAVE CAUSED THIS TO HAPPEN?

Limit switch engaged due to cable movement/oscilation.

WHAT SHOULD YOU DO TO KEEPTHIS FROM HAPPENING?

Replace winch.

SUMMARY OF SUPPLY AND EQUIPMENT DROPS

2D TRIANNUAL CY 2001

	PLATFORM LOAD		SINGLE CONTAINER		CDS		TOTAL	
Number of Drops	1,5	536	1	75	1,841		3,552	
Number of Malfunctions		13		2	5		20	
Percentage of Malfunctions	0.	84	1.	.14	0.27		0.56	
Malfunction Phases:	IP	EF	IP	EF	IP	EF	IP	EF
Extraction	5	5	1	0	0	0	6	5
Deployment-Recovery	3	0	0	1	4	1	7	2
Release	0	0	0	0	0	0	0	0

IP-Incorrect Procedures

EF-Equipment Failure

SUMMARY OF PERSONNEL PARACHUTE JUMPS

2D TRIANNUAL CY 2001

		C-17	C-130	C-141	OTHER	TOTAL
	Number of Deployments	24,055	48,552	5,901	4,547	83,055
Nonmaneuverable	Number of Malfunctions	2	2	0	0	4
	Percentage of Malfunctions	0.008	0.04	0.00	0.00	0.004
	Number of Deployments	724	8,848	325	6,339	16,236
Maneuverable	Number of Malfunctions	0	1	0	1	2
	Percentage of Malfunctions	0.00	0.011	0.00	0.15	0.012
	Number of Deployments	108	1,406	33	3,417	4,964
Free-Fall	Number of Malfunctions	1	7	0	4	12
	Percentage of Malfunctions	0.93	0.50	0.00	0.12	0.24
	Number of Deployments	24,887	58,806	6,259	14,303	104,255
Total	Number of Malfunctions	3	10	0	5	18
	Percentage of Malfunctions	0.012	0.02	0.00	0.03	0.017

SUMMARY OF PERSONNELPARACHUTE MALFUNCTIONS

2D TRIANNUAL CY 2001

	NON- MANEUVERABLE	MANEUVERABLE	FREE-FALL	RESERVE
Number of Deployments	83,055	16,236	4,964	2
Number of Malfunctions	4	2	12	0
Towed Jumper	1	1	0	0
Broken Static Line	1	1	0	0
Entanglement	0	0	0	0
Failed to Inflate	0	0	1	0
Inversion	0	0	0	0
Pilot Chute	0	0	0	0
Semi-inversion	0	0	0	0
Suspension Lines	0	0	0	0
Other	2	0	11	0
Percentage of Malfunctions	0.005	0.012	0.24	0.00
Fatalities	0	0	0	1

^{*}Injuries

INJURIES OCCURRING ON PARACHUTE OPERATIONS AS REPORTED ON DA FORM 285

1 May - 31 August 2001

	C-17	C-130	C-141	UNKNOWN	TOTAL
PLF-Related Injuries	0	17	0	28	45
Main Malfunction	0	0	0	0	0
Misrouting of Static Line	0	0	1	3	4
Entanglements	0	0	0	0	0
Tree Landings	0	1	0	0	1
In Aircraft	0	0	0	0	0
Hazards on Drop Zone	0	2	0	3	5
Other	0	5	0	9	14
Insufficient Information	0	0	0	2	2

AIRCRAFT MALFUNCTIONS

These malfunction reports are not included in the statistical data nor reflected in the percentage of malfunctions. All aircraft systems malfunctions which may have led to an abort or no-drop are constantly reviewed and analyzed for repeat or recurring trends and solutions. Corrective actions are recommended through Air Force maintenance systems.

PERSONNEL DROPS	
Improperly operating doors or ramps	3
Static line retriever	0
SUPPLY AND EQUIPMENT DROPS	
Rail locks	5
Improperly operating ADS	1
Improperly operating doors or ramps	0
Release mechanism	2
Electrical system	0
CONTAINER DROPS	
Rollers	0
Type XXVI gate	0
Static line retriever	4
Release Mechanism	7
TOTAL	22